

# JSC DATA REQUIREMENTS DESCRIPTION (DRD)

(Based on JSC-STD-123.)

1. DRD Title  <b>Quality Assurance Plan Initiator Resistance Measurement Unit (IRMU)</b>	2. Date of current version  02/09/04	3. DRL Line Item No.  5	RFP/Contract No. (Procurement completes)
4. Use (Define need for, intended use of, and/or anticipated results of data) <b>To describe how the contractor will ensure compliance with cited quality requirements defining the total quality program from the initial award throughout the fabrication and delivery of the devices.</b>			5. DRD Category: (check one) <input checked="" type="checkbox"/> Technical <input type="checkbox"/> Administrative <input type="checkbox"/> SR & QA
6. References (Optional)	7. Interrelationships (e.g., with other DRDs) (Optional)		

8. Preparation Information (Include complete instructions for document preparation)

**Identifies elements of quality-related activities required during the contract.**

- a. The plan shall identify elements of the Quality Program organization objectives, implementing policies and procedures, and the subcontract controls system from the initial phase throughout design, development, fabrication, and delivery of contract end items including receiving, storage, testing, and all checkout functions.
- b. The plan shall describe the contractor's philosophy and approach to each element of the Quality Assurance program as required by the contract and interfaces with related program disciplines.
- c. The plan shall describe quality assurance systems to be utilized in stating requirements, procedures, status, problems, and corrective action.
- d. The plan also shall describe relationships between major quality assurance activities and program level events.

Ship to:  
 NASA Lyndon B. Johnson Space Center  
 Attn.: Stephan Liming EP5  
       Todd Hinkel EP5  
 Houston, TX 77058