



NASA Dryden Flight Research Center
PROCUREMENT QUALITY REQUIREMENTS



**ATTACHMENT Q-8
INSPECTIONS AND TEST DATA REQUIREMENTS**

1. The contractor shall perform all required inspections and tests to ensure that all articles and materials conform to contract requirements and applicable drawings and specifications. Such inspections and tests shall encompass the receiving, processing, fabrication, assembly, end-item and shipping phases.
2. The Contractor is responsible for all inspections and test data. This responsibility shall not affect any rights of NASA, DFRC, or a designated Government agency for any surveillance, source or other inspection. The Contractor shall be responsible for providing adequate personnel, methods and equipment to perform all inspections and tests to assure that articles and materials meet the requirements of the contract.
3. Inspection and test data requirements are the responsibility of the Contractor. The Contractor shall prepare and maintain records and data of all inspections and tests performed. Such records and data shall be appropriate for the type, scope and significance of the inspection or test performed and in sufficient detail and extent to provide for complete verification and evaluation of the operation.

When specified in contract documents, each article or material shipped against this contract shall be accompanied by copies of required inspection and test data to provide evidence of compliance with contract requirements.

All inspection and test data shall be verified by the Contractor's inspection/quality organization by use of signature or quality stamp and dating. In those cases where a formal inspection/quality organization is not in existence at the Contractor facility, the verification of inspection and test data shall be provided by a signature of an authorized official of the Contractor, accompanied by the date of such verification.

END OF Q-8

Approved

Gary May

Q-8 (12-97)