

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

Work Order	Work Type	Description	Location	Craft	Asset	Actual Labor Hours
59146	GC	NASA - PM - LANDSCAPING	NASA-DRYDEN	GENERAL		0:00
59102	JAN	B/703 RM 221 - SWEEP/MOP OFFICE AREA.	DAOF-B703	GENERAL		0:00
72519	SR	B/4825 Cafe - (Service Call) - Hood Cleaning	DFRC-B4825-GIFT-SHOP	ADMIN		0:00
59081	SR	703-VCC install 120V line in restroom	DAOF-B703	ELEC		0:00
59095	SR	B/4847 - (SERVICE CALL) - INSTALL ELECTRICAL DUPLEX	DFRC-B4847	ELEC		1:00
59074	SR	4847 ID & label receptacles during **OUTAGE #943**	DFRC-B4847	ELEC		4:30
63411	SR	B/4842 - (SERVICE CALL) - INSTALL DIMMABLE LIGHTING	DFRC-B4842	ELEC		0:00
60170	SR	B/4825 SECURITY - (SERVICE CALL) - ELECT SUPPORT	DFRC-B4825-POST1	ELEC		0:00
61262	SR	SUB 16 - (SERVICE CALL) WEEKLY METER READING	DFRC-NB089	ELEC		3:56
61265	SR	703 (Service Call) North side Data Center 2-208v L6-20a receptacles installed	DAOF-B703	ELEC		0:00
61279	SR	703 (Service Call) hook up electrical whip	DAOF-B703	ELEC		0:00
61296	SR	703 (Service Call) add receptacle to power box, install subpanel, correct wiring	DAOF-B703	ELEC		0:00
63393	SR	B/4820 - (SERVICE CALL) - EC PANEL LABELED	DFRC-B4820	ELEC		0:00
63527	SR	B/0192 LRO - OUTAGE # 953 (SRVC CALL) - BRKR / PHASING	DFRC-B192	ELEC	803002	0:00
63363	SR	B/703 RMS N232,N241,N242 - (SRVC CALL) - ADDL PWR	DAOF-B703	ELEC		0:00
63456	SR	B/LRO-0192 - OUTAGE #950 - ELECT TECH SUPPORT	DFRC-B192	ELEC	803002	10:30
63459	SR	NASA - (SERVICE CALL) - NASA PHASE 7 -SITE SURVEY	DFRC	ELEC		2:30
63460	SR	NASA - (SERVICE CALL) - NASA PHASE 7 -SITE SURVEY	10135	ELEC		1:30
63329	SR	703 (Service Call) install receptacles	DAOF-B703	ELEC		4:00
63356	SR	B/703 RM 221 CUBE "L" - (SC) - ADDITIONAL OUTLETS	DAOF-B703	ELEC		0:00
65558	SR	4810 SERVICE CALL-INSTALL SWITCH LOCKS	DFRC-B4810	ELEC		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

65507	SR	B/4820 MEZZ - OUTAGE #956 ELECTRICAL SUPPORT	DFRC-B4820	ELEC		18:30
65618	SR	B/4840 - Outage # 959 - Phantom Eye/Ray	DFRC-B4840	ELEC	3125035	3:00
65625	SR	4825 (SERVICE CALL) ROOF-TRACE AND I.D. BREAKER	DFRC-B4825-POST1	ELEC		1:15
65601	SR	B/4820 - (Service Call) - Additional Power	DFRC-B4820	ELEC		4:00
65647	SR	B/4820 - (Service Call) - Temporary Power	DFRC-B4820	ELEC		1:30
65505	SR	4872 (Service Call) add 3-way switch	DFRC-B4872	ELEC		3:00
65561	SR	703 SERVICE CALL - FABRICATION SHOP_INSTALL RECEPTACLE	DAOF-B703	ELEC		0:00
65741	SR	B/4800 RM 1115 - (Service Call) Additional Outlets	DFRC-B4800-FLOOR1	ELEC		0:00
65698	SR	4826-(SERVICE CALL) REMOVE, MOVE, INSTALL FORK LIFT CHARGER	DFRC-B4826	ELEC		0:00
65722	SR	B/4821 - Disconnect Trailer	DFRC-B4820	ELEC		1:30
65710	SR	B/4825 - (Service Call) - Additional Power	DFRC-B4825-POST1	ELEC		1:00
65711	SR	B/4809 - (Service Call) - Identify Breakers	DFRC-B4809	ELEC		0:30
65757	SR	4800 (SERVICE CALL) DE-LAMP 50% OF LIGHTS ON 1ST, 2ND, 3RD FLOORS	DFRC-B4800-FLOOR1	ELEC		5:00
65745	SR	SUB 15 (SERVICE CALL) INSTALL RECEPTACLE	DFRC-NB093	ELEC	1702007	0:00
65775	SR	SUB 16-INSTALL SWITCHGEAR HEATER	DFRC-NB089	ELEC	1636116	6:00
68063	SR	Substation 15 - Outage # 1013 (Service Call) - Install Power Supply	DFRC-NB093	ELEC	1702007	5:45
67928	SR	703 (SERVICE CALL) RUN POWER FROM WALL OUTLET TO WORK TABLE.	DAOF-B703	ELEC		0:00
68097	SR	4838-201 (SERVICE REQUEST) INSTALL TWIST-LOCK RECEPTACLE AND WATERPROOF J-BOX	DFRC-B4838	ELEC		0:00
68168	SR	703 4TH FLOOR SOUTH-REPAIR OR UPGRADE LIGHTING AS PRESENT FIXTURES OFFER LIGHTING THAT IS INSUFFICIENT	DAOF-B703	ELEC		0:00
68159	SR	B/703 - Outage # 974 - Electrical Support	DAOF-B703	ELEC		3:00
68117	SR	B/0192 LRO - Outage # 973 - Electrical Support	DFRC-B192	ELEC	803002	2:00
68158	SR	MDD/Area A - (Service Call) - Kill Test	DFRC-NB119	ELEC		1:30
67937	SR	E-25 Manhole (SERVICE CALL) verify conduit	DFRC-NB046	ELEC		2:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

67943	SR	4838-201 (SERVICE CALL) install new emergency light	DFRC-B4838	ELEC		1:30
67954	SR	B/4825 POST 1 - OUTAGE #966 - ELECTRICAL SUPPORT	DFRC-B4825-POST1	ELEC		1:30
68118	SR	B/4840 - Outage # 972 - Elec/Fire Support	DFRC-B4840	ELEC		3:00
68001	SR	B/4854 - (Service Call) - Electrical Support	DFRC-B4854	ELEC		2:30
68038	SR	4800-1115 REMOVE PINK GROUND WIRES	DFRC-B4800-FLOOR1	ELEC		0:00
70117	SR	4800-1014 (SERVICE REQUEST) HOOK UP TWO MODULAR WORKSTATIONS TO POWER; THERE IS ABOUT 3FT OF WHIP AND MORE MAY BE NEEDED AS THE JBOX WILL HAVE TO BE REACHED	DFRC-B4800-FLOOR1	ELEC		1:30
70270	SR	B/4840 Bay 6 - (Outage # 990) - Electrical Support	DFRC-B4820	ELEC		1:00
70065	SR	4808 - (SERVICE CALL) REMOVE A *POWERED* PARACHUTING HARNESS "TRAINER" FROM THE NORTH SIDE OF B4808 TO THE NEW TRAINING AREA IN B4807. THE TRAINING AREA IS BEING MOVED BECAUSE IT IS NOT	DFRC-B4808-LIFE-SUPPORT	ELEC		0:00
70274	SR	4823-205 (SERVICE REQUEST) HOOK UP A MODULAR FURNITURE UNIT	DFRC-B4823	ELEC		1:30
70168	SR	B/4852 - (Service Call) - Power Down Fuel Station	DFRC-B4852	ELEC		1:00
70315	SR	NASA Dryden (SERVICE REQUEST) IDENTIFY ELECTRICAL CIRCUITS FOR SECURITY CAMERAS IN FOUR LOCATIONS; SEE MARK FOR MAPS WITH EXACT LOCATIONS CAMERAS WILL NEED TO GO WHEN ASSESSING AVAILABLE CIRCUITS	NASA-DRYDEN	ELEC		0:00
70276	SR	B/4820 2nd Flr - (Outage # 984) - Electrical Support	DFRC-B4820	ELEC		2:00
70126	SR	DAOF - (Service Call) - Utility Meter Readings	DAOF	ELEC		0:30
70275	SR	NASA DRYDEN SUBSTATIONS (SERVICE REQUEST) ESCORT SQUARE D TO VARIOUS SUBSTATIONS SO WORK CAN BE PERFORMED	NASA-DRYDEN	ELEC		2:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

70040	SR	4807 (SERVICE CALL) REMOVE A TEMPORARY POWER POLE FROM THE NORTH SIDE OF THE BLDG IN THE "TRAINING AREA"; MUST SEE PHIL FOR ACCESS TO BLDG	DFRC-B4807	ELEC		2:00
70260	SR	B/4720 - (Service Call) - Tech Support	DFRC-B4720	ELEC		4:45
70283	SR	B/703 - (Service Call) Close Breaker	DAOF-B703	ELEC	90008	1:00
70284	SR	B/LRO-0192 - (Service Call)- Hardwire Electrical	DFRC-B192	ELEC	803002	2:00
70084	SR	B/4800-3103 (SERVICE REQUEST) REPLACE TWO PHASE RECEPTACLE WITH A ONE PHASE RECEPTACLE; NEED L-5-30S THAT IS 120V30A TO REPLACE A 208V30A	DFRC-B4800-FLOOR3	ELEC		1:00
70314	SR	703 (SERVICE REQUEST) IDENTIFY ELECTRICAL CIRCUITS FOR SECURITY CAMERAS IN 12 VARIOUS LOCATIONS; SEE MARK FOR MAPS WITH EXACT LOCATIONS CAMERAS WILL NEED TO GO WHEN ASSESSING AVAILABLE CIRCUITS	DAOF-B703	ELEC		1:00
70219	SR	4800-1412 (SERVICE REQUEST) DISCONNECT ELECTRIC AT PANELS: LP1-H18-CR7 AND LP1-H18A-CR6. CUSTOMER WANTS TO KEEP "PIGTAILS"	DFRC-B4800-FLOOR1	ELEC		1:00
70254	SR	B/4820 2nd Flr - Outage # 985 - Electrical Support	DFRC-B4820	ELEC	1901000	2:30
72310	SR	B/4823 - (Service Call) Outage # 1003- CNC Router/Lathes	DFRC-B4823	ELEC		11:00
72342	SR	B/703 - (Service Call) - Extention Cord	DAOF-B703	ELEC		1:00
72354	SR	DAOF - (Service Call) - Utility Meter Readings	DAOF	ELEC		1:00
72458	SR	703 (SERVICE REQUEST) ELECTRICALLY HOOK UP A WELDER IN THE FABRICATION SHOP	DAOF-B703	ELEC		1:30
72562	SR	4802 (SERVICE REQUEST) TECH SUPPORT FOR FORUM ON 3/31/11	DFRC-B4802	ELEC		9:15
72492	SR	B/4838 CITC - (Outage #1010) - Electrical Support	DFRC-B4838	ELEC		15:15
72567	SR	SUBSTATION 3 (SERVICE REQUEST) UNIT 6 - INSTALL SUPPORTS FOR EMT CONDUIT	DFRC-NB083	ELEC		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72384	SR	NASA Facility - (Service Call) - Support ARCADA Contractor	DFRC	ELEC		2:00
72391	SR	4840 DEMARK 3 (SERVICE REQUEST) TRACE ELECTRICAL CONDUIT TO FIND A SPARE ONE	DFRC-B4840	ELEC		0:30
72392	SR	4820 (SERVICE REQUEST) REMOVE WIRES FROM CEILING AND LOCATE POWER FOR A SPIDER BOX FOR CONTRACTORS	DFRC-B4820	ELEC		1:00
72397	SR	4826 (SERVICE REQUEST) CHANGE OUT 6 TOGGLE SWITCHES FOR MOTION SENSOR SWITCHES; 2EA IN THREE ROOMS: 102, 103, 104	DFRC-B4826	ELEC		8:30
72548	SR	DAOF - (Service Call) - Install temporary Power	DAOF-LAND	ELEC		3:00
72551	SR	B/4810 - (Service Call) - GFCI ID & Testing	DFRC-B4810	ELEC		0:00
74797	SR	4871 (SERVICE REQUEST) GUARD POST 13 - OPEN CONDUIT AND VERIFY WHETHER OR NOT MORE WIRES CAN BE PUT INTO IT; KEVIN ANDREWS MUST BE SEEN FIRST SO HE MAY MAKE CLEAR WHICH CONDUIT TO OPEN	DFRC-B4871	ELEC		1:00
74194	SR	B/4800 - (Service Call) - Delamping Office Areas	DFRC-B4800-FLOOR1	ELEC		0:00
74789	SR	4806 (SERVICE REQUEST) SAFETY ACTION ITEM #1979 - IN HYDRAULICS SHOP PANEL LP1-F4 HAS AN INCOMPLETE CIRCUIT DIRECTORY	DFRC-B4806	ELEC		1:00
74796	SR	4720 (SERVICE REQUEST) INSTALL DUPLEX RECEPTACLE FOR MFTS ANTENNA; SEE GUY THOMAS IN B4982 FOR SPECIFICS	DFRC-B4720	ELEC		3:30
75432	SR	4982 (Service Request) - Investigate the electrical configuration at B4982 for a future chiller replacement	DFRC-B4982	ELEC		0:45
75391	SR	4840 (SERVICE REQUEST) BAY 1, 2, 3 WEST WALL - CHECK TYPE OF RECEPTACLE "SS3-14" IS ALONG WITH BEING 480V. CUSTOMER NEEDS TO PLUG IN AIRCRAFT TO RECEPTACLE.	DFRC-B4840	ELEC		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

75461	SR	4820 (SERVICE REQUESTS) CONNECT THREE ELECTRICAL WHIPS FOR SOME MODULAR FURNITURE.	DFRC-B4820	ELEC		2:30
75306	SR	4720 (SERVICE REQUEST) RUN POWER THAT IS ALREADY THERE TO THE CONNEX FOR THE GLOBAL HAWK PROJECT.	DFRC-B4720	ELEC		3:00
75346	SR	B/4820 - (Service Call) -Outage #1028 - Install Power for Contractor	DFRC-B4820	ELEC		6:00
75466	SR	B4863 (Service Call) Outage #1032 - Install Breaker	DFRC-B4863	ELEC		0:00
75483	SR	4840 (SERVICE REQUEST) BAY 1 CONNECT AN FITTING TO THE END OF AN ELECTRICAL CORD	DFRC-B4840	ELEC		1:30
75514	SR	B/703 - Outage #1031 - Breaker Installation	DAOF-B703	ELEC		2:00
75438	SR	4820 (Service Request) 2nd Floor Control Room, verify the electrical feed sources and points of termination of the electrical conductors in an under floor black pull box – POC: Mark Nelson	DFRC-B4820	ELEC		2:00
79426	SR	703 (Service Request) Stencil date on grounds showing test dates of 9/09	DAOF-B703	ELEC		0:00
79612	SR	NB119 (Service Request) - Grounds for Phantom Eye: Clean, paint, label (stencil) effective test dates to comply with DCP-F-613; Please see Kevin for important specifics regarding job.	DFRC-NB119	ELEC		2:00
79634	SR	4720 (SERVICE REQUEST) RUN POWER THAT IS ALREADY THERE TO THE CONNEX FOR THE GLOBAL HAWK PROJECT.	DFRC-B4720	ELEC		4:55
79630	SR	B/4820 - (Service Call) - Remove Electrical Whips	DFRC-B4820	ELEC		3:00
79705	SR	CITC - (Service Call) - Training	DFRC-B4838	ELEC		0:00
79708	SR	CITC - (Service Call) - Training	DFRC-B4838	ELEC		0:00
79262	SR	DAOF - (Service Call) - Utility Meter Readings	DAOF	ELEC		0:30
79642	SR	B/192 LRO - (Service Call) -	DFRC-B192	ELEC		0:00
79685	SR	DAOF - (Service Call) - Utility Meter Readings	DAOF	ELEC		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

79254	SR	4824 (SERVICE REQUEST) TWO CONNEXES NEED LIGHTING AND SWITCHES INSTALLED. APPROX TWO FIXTURES PER CONNEX WOULD BE USEFUL.	DFRC-B4824	ELEC		18:30
79530	SR	4820-201 (Service Request) Assess for heavier circuit as old and now new GFI keep tripping	DFRC-B4820	ELEC		1:00
79585	SR	B/4800 Rm 1718 - (Service Call) - Electrical Support	DFRC-B4800-FLOOR1	ELEC		10:45
79696	SR	NASA-Dryden (Service request) Two trucks/trailers each need one 4-pronged receptacle for easy access	NASA-DRYDEN	ELEC		3:30
79698	SR	4871 (Service request) Guard Post 13 Shut down a breaker and LOTO the breaker until it needs to be turned on again when indicated	DFRC-B4871	ELEC		1:30
81704	SR	B/4982 - (Service Call) - Remove Electrical	DFRC-B4982	ELEC		2:00
82158	SR	DAOF - (Service Call) - Utility Meter Readings	DAOF	ELEC		0:45
81790	SR	B/4800 Rm 1716 - (Service Call) - Install GFCI Outlets	DFRC-B4800-FLOOR1	ELEC		0:00
81931	SR	B/4809 - (Service Call) Move Electrical Outlet	DFRC-B4809	ELEC		0:00
82032	SR	B/703 - (Service Call) Gas Supply Reading	DAOF-B703	ELEC		0:15
81636	SR	4802 - (Service Call) - Electrical Support	DFRC-B4802	ELEC		0:00
81980	SR	B/4824 (Service Call) - Connect (2) connectors to two support trailers; 208v, customer has one connector and is acquiring the second and requires labor only	DFRC-B4824	ELEC		4:30
82018	SR	B/4800 Rm 2511 - (Service Call) - Installation of (2) clocks	DFRC-B4800-FLOOR2	ELEC		2:15
81982	SR	B/4820 Rm 202 - (Outage #1069) - Temporary Power	DFRC-B4820	ELEC		3:30
82165	SR	B/4820 - (Outage #1075) - Installation of New Circuit Breakers	DFRC-B4820	ELEC		3:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

81811	SR	B/4820 Rm 112 - (Service Call) - Electrical Disconnect	DFRC-B4820	ELEC		2:30
81773	SR	B/4820 - Outage #1067 - Electrical Repair	DFRC-B4820	ELEC		1:30
81783	SR	B/4838 CITC - (Outage #1053) - Electrical Support	DFRC-B4838	ELEC		5:30
82164	SR	NB094 (service request) escort Area A techs into Area A substation	DFRC-NB094	ELEC		0:30
82171	SR	Denmarks 1-3 (B/4840) - Outage # 1079 - Electrical Pull Box	DFRC-B4840	ELEC		2:30
81974	SR	B/703 - (Outage # 1073) - Electrical Support	DAOF-B703	ELEC		1:00
84236	SR	B/4838 - (Service Call) - UPS switchover	DFRC-B4838A	ELEC		2:00
84286	SR	4820 (service request) WATER TUNNEL - install a GFCI outlet over the sink	DFRC-B4820	ELEC		0:30
84224	SR	4876 (service request) install a buzzer at the front desk that can be heard in the warehouse	DFRC-B4876	ELEC		0:00
84298	SR	AERO Inst - (Service Call) - De-energize panel	AERO	ELEC		1:00
84299	SR	AERO Inst. - (Service Call) - Installation of (3) Whips	AERO	ELEC		0:00
84267	SR	4800-1716 (Service Request) Relocate a receptacle	DFRC-B4800-FLOOR1	ELEC		3:00
84317	SR	B/4800 Rm 2407 - (Service Call) - Troubleshoot Lighting	DFRC-B4800-FLOOR2	ELEC		0:00
84368	SR	4800-2511 (service request) need installed a power line and a one receptacle gang box; for a tv	DFRC-B4800-FLOOR2	ELEC		4:30
84380	SR	4985 - (Service Request) - Electrical Hook Up	DFRC-B4982	ELEC		2:45
84266	SR	B/703 - (Service Call) - Light Switches	DAOF-B703	ELEC		1:30
85333	SR	B/4863 - (Service Call) - De-energize Pleion Panels	DFRC-B4863	ELEC		1:30
86833	SR	DAOF - (Service Call) - Install Electrical /Brackets for TV	DAOF-LAND	ELEC		0:00
86945	SR	T-1 / T-42 - (Service Call) - Estimate Disconnection of Utilities	DFRC-T-01	ELEC		1:30
86982	SR	B/4801 - (Service Call) - Assess Forming Machine	DFRC-B4801	ELEC		6:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

87033	SR	B/4844 - (Service Call) - Energize Electrical Circuits	DFRC-B4844	ELEC		4:30
86990	SR	4800 (SERVICE REQUEST) PREP WORK FOR OUTAGE #1099; SEE KEVIN ANDREWS FIRST AS HE HAS DONE MUCH OF THE LEG WORK.	DFRC-B4800-FLOOR2	ELEC		3:00
86878	SR	Sub 11 - (Service Call) - Find electrical source	DFRC-NB088	ELEC		1:00
86940	SR	B/4825 - (Service Call) - Evaluate Electrical	DFRC-B4825-POST1	ELEC		3:00
86974	SR	B/703 - AGE Shop (Service Call) - Relocate Outlet	DAOF-B703	ELEC		0:00
86817	SR	B/4872 - (Service Call) - Trace Power	DFRC-B4872	ELEC		1:00
86821	SR	B4820 - (Service Call) - LOTO Electrical Panels	DFRC-B4820	ELEC		2:15
86759	SR	DAOF - (Service Call) - Utility Meter Readings	DAOF	ELEC		0:30
86936	SR	B/4838 - (Outage #1094) - Electrical Technician Support	DFRC-B4838	ELEC	3132005	6:00
86996	SR	B/4840 - (Service Call) - Replace Plugs on Demark #3	DFRC-B4840	ELEC		1:00
86686	SR	4820 (service request) LOTO breakers 1 and 3 of panel LP1-D5.6A and remove some other locks that are no longer needed	DFRC-B4820	ELEC		1:00
86741	SR	B/4840 - (Outage 1089) - Electrical Tech Support	DFRC-B4840	ELEC		1:45
86972	SR	B/703 - (Service Call) - Fun Runner Project	DAOF-B703	ELEC		3:00
86961	SR	B/703 - (SERVICE REQUEST) - Verify that the DAOF current configuration will satisfy the Air Force's requirements detailed below.	DAOF-B703	ELEC		1:00
87037	SR	4800-1115B (SERVICE REQUEST) MOVE J-BOX AND ELECTRICAL CORD AS CORD WILL BE SHORTENED	DFRC-B4800-FLOOR1	ELEC		3:30
89650	SR	4850 (SERVICE REQUEST) EMERGENCY CENTER - REPLACE OUTLET COVERS OR COMPLETE OUTLETS ON 4 RECEPTACLES. THEY ARE CHILD PROOF 110V AND CANNOT TAKE STANDARD PLUGS. STANDARD 110V ARE NEEDED.	DFRC-B4850	ELEC		2:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89652	SR	SUBSTATION 11 - (Outage #1121) - Replace Switch	DFRC-NB088	ELEC		4:30
89472	SR	4802 (OUTAGE #1123) SUPPORT CONTRACTOR FOR HANGAR LIGHTING	DFRC-B4802	ELEC		2:30
89324	SR	4800-1708 (SERVICE REQUEST) REPRODUCTION ROOM - NEED BULBS CHANGED OUT. HAVING A HARD TIME WITH COLOR MATCH. NEED GE CHROMA 50's LIKE PHOTO LAB HAS. FIXTURES MAY NOT BE SUITABLE FOR CHROMA'S.	DFRC-B4800-FLOOR1	ELEC		0:00
89352	SR	703-SCC (SERVICE REQUEST) REPLACE 2 RECEPTACLES THAT ARE THE WRONG TYPE	DAOF-B703	ELEC		0:00
89554	SR	4820-200/201 (SERVICE REQUEST) LO/TO 20A BREAKER THAT IS FED FROM A 60A PANEL ON A HANGAR WALL	DFRC-B4820	ELEC		1:30
89556	SR	B/4982 - (Outage # 1119) - Land Wires To Chiller	DFRC-B4982	ELEC		2:00
89557	SR	B/4982 - (Outage # 1120) - Install New Electrical	DFRC-B4982	ELEC		1:00
89609	SR	B/4857 - (Service Call) -(Outage # 1132) WATR Radar Trailer	DFRC-B4857	ELEC		1:30
89624	SR	B/4851- (Outage#1134) - Clear Alarms on UPS	DFRC-B4851	ELEC		1:30
89262	SR	Sub 25 - (Outage 1105) - Switch Transformer	DFRC-SUB-25	ELEC		1:30
89522	SR	4820 (SERVICE REQUEST) 3RD FL - LO/TO A 480V BREAKER TO WHICH A CONDUIT RUNS FROM THE MOTOR CONTROL CENTER DOWN VERY NEAR THE CHILLER. THE GOAL IS TO DEMO THE CONDUIT AND SAFE IT OFF AT THE 3RD FLOOR.	DFRC-B4820	ELEC		3:00
89585	SR	B/703 - (Outage #1063) - Install Meter Module	DAOF-B703	ELEC		12:00
89354	SR	AERO INSTITUE (SERVICE REQUEST) REPLACE A COUPLE OF BLANKS WITH DUPLEX OUTLETS	AERO	ELEC		0:30
89304	SR	DAOF - (Service Call) - Utility Meter Readings	DAOF	ELEC		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89399	SR	B/4800 2nd FL - (Outage # 1099) - Installation of Emergency Lights	DFRC-B4800-FLOOR2	ELEC		3:30
89371	SR	B/703 VCC - (Service Call) - Install Electrical Outlet	DAOF-B703A	ELEC		0:00
89420	SR	B/4863 - (Service Call) - Re-energize Circuits	DFRC-B4863	ELEC		0:30
89502	SR	4830's ROTO GATE (SERVICE REQUEST) locate and identify the electrical circuit providing power to the B4830 Rotary gate in preparation for the parking lot #3 future electrical lighting outage	DFRC-B4830A	ELEC		1:30
89437	SR	B/4833-4866 - (Service Call) - Remove Conductors	DFRC-B4833	ELEC		3:45
89501	SR	703-N231 (SERVICE REQUEST) disconnect electrical power from the old furniture system and reconnect power to the new systems furniture	DAOF-B703	ELEC		0:00
89443	SR	B/4808 (DR# 470) - Service Call - Install Electrical	DFRC-B4808	ELEC		9:30
89555	SR	4820-201 (SERVICE REQUEST) A SPRINKLER/DELUGE "OFF" LIGHT WHICH HAS 220V BULBS NEEDS TO BE TRACED TO THE ELECTRICAL FFD AND LO/TO	DFRC-B4820	ELEC		2:00
89560	SR	4820 (SERVICE REQUEST) LO/TO SOURCE AFTER TRACING THE GEM CART RECEPTACLES AND THE WALL PACK LIGHTS	DFRC-B4820	ELEC		1:15
89360	SR	B/4840 Bay 3 - (Service Call) - Relocate Aircraft Power	DFRC-B4840	ELEC		0:00
89666	SR	B/703 Rm 111S - (Service Call) - Installation of Electrical Outlet	DAOF-B703	ELEC		0:00
89395	SR	B/703 VCC - (Service Call) - Installation of (6) Outlets	DAOF-B703A	ELEC		7:30
89497	SR	4985 DISCONNECT POWER FROM KTM TRAILER; SEE GUY FOR SPECIFICS	DFRC-B4985	ELEC		2:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89520	SR	4823 (SERVICE REQUEST) HIGH BAY HARDWIRE WELDER INTO OUTLET; IF POSSIBLE BY 9/12/11. POC's ARE DON WHITFIELD AT x 3905 OR JOE BARKER AT x6856	DFRC-B4823	ELEC		1:00
89539	SR	B/703 VCC - (Outage #1114) - Power to Gates	DAOF-B703A	ELEC		2:00
89577	SR	B/703 Rm 173 - (Service Call) - Troubleshoot Installation	DAOF-B703	ELEC		4:00
89623	SR	Parking Lot #3 - (Outage #1122) - Replace Light Poles	DFRC	ELEC		2:00
91670	SR	B/703 - (Service Call) - LO/TO Electrical To Cryogenics Sheds	DAOF-B703	ELEC		1:00
91676	SR	B/703 RM 231- (Service Call) - Install / Remove Electrical	DAOF-B703	ELEC		0:00
91686	SR	B/4820 - (Outage # 1146) - Hallway Light / Ceiling Modification	DFRC-B4820	ELEC		0:00
91557	SR	SUB 26 - (Service Call) - Access Panel	DFRC-NB125	ELEC		0:00
91559	SR	B/4800 Rm 1405 - (Service Call) - Troubleshoot Electrical Source	DFRC-B4800-FLOOR1	ELEC		1:30
91502	SR	4800-1122 (SERVICE REQUEST) CCR-214 - PROVIDE 120V POWER TO THE CENTER OF THE ROOM; SEE WIL FOR SPECIFICS	DFRC-B4800-FLOOR1	ELEC		0:00
91511	SR	DAOF - (Service Call) - Utility Meter Readings	DAOF	ELEC		0:11
91571	SR	B/4820 - (Service Call) - Shut Off Breaker	DFRC-B4820	ELEC		1:00
91536	SR	SUBSTATION 11 (SERVICE REQUEST) ESCORT AC COMPANY REP TO CHECK PHASING AT ALL BLDGS TIED INTO SUB 11	DFRC-NB088	ELEC		3:00
91592	SR	B/4820- (Service Call) - Disconnect lights	DFRC-B4820	ELEC		1:00
91598	SR	B/4802-B4806 - (Service Call) - Terminate New Conductors	DFRC-B4802	ELEC		0:00
91600	SR	4847 (SERVICE REQUEST) ON EAST WALL BY GROUND STATION INSTALL AN OUTLET FOR LARGE SCREEN TV'S SINCE THE GROUND STATION WILL BE IN FULL USE ALREADY	DFRC-B4847	ELEC		0:00
91610	SR	B/4810 - (Service Call) - Failure Review	DFRC-B4810	ELEC		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

91613	SR	B/703 - (Service Call) - Test Aircraft Grounding Stations	DAOF-B703	ELEC		0:00
91628	SR	B/4854 - (Service Call) - LO/TO Fuel Station	DFRC-B4854	ELEC		4:00
91641	SR	B/4800 Rm 3113 - (Service Call) - New Outlet Installed	DFRC-B4800-FLOOR3	ELEC		0:00
91643	SR	Substation 11 - (Outage # 1124) - Replace Transformer/Switchgear	DFRC-NB088	ELEC		3:00
93807	SR	B/4820 RM 102 - (Service Call) - LO/TO Breaker	DFRC-B4820	ELEC		1:00
93881	SR	B/0192 LRO - (Service Call) - Upgrade Wiring To UPS	DFRC-B192	ELEC	803002	0:00
93852	SR	B/4824 - (Service Call) - Installation of Additional Outlets	DFRC-B4824	ELEC		0:00
93854	SR	B/4824 - (Service Call) - Install 220 Cable	DFRC-B4824	ELEC		0:00
93885	SR	4825 SECURITY (SERVICE REQUEST) RELOCATE "CODE YANKEE" CONTROL BOX	DFRC-B4825-POST1	ELEC		0:00
93875	SR	4823 (SERVICE REQUEST) NEW MACHINE HOOK UP	DFRC-B4823	ELEC		0:00
93857	SR	4870 (SERVICE CALL) INSTALL AN OUTLET ON THE SOUTH SIDE OF THE ROOF FOR A CAMERA; SEE JOE FOR SPECIFICS x3114 OR x7054	DFRC-B4870	ELEC		0:00
93866	SR	B/4982 - (Outage # 1149) - Breaker Installation	DFRC-B4982	ELEC		0:00
63531	SR	B/4840 RM 126 - (SERVICE CALL) INSTALL 2 EXTINGUISHERS	DFRC-B4840	FIRE		1:30
65564	SR	NASA - Main Fire Water Tanks -(Service Call)	NASA-DRYDEN	FIRE		3:00
68010	SR	4800-1122 (SERVICE CALL) MODIFY FIRE ALARM	DFRC-B4800-FLOOR1	FIRE		1:00
68046	SR	B/4840-(SERVICE CALL) INSTALLATION OF TRANSFORMERS	DFRC-B4840	FIRE		19:00
68092	SR	B/4820 - Outage # 971 - Fire Support	DFRC-B4820	FIRE		2:00
70247	SR	B/703 RM221 - (Outage # 986) - Installation of New Sprinkler Pipes	DAOF-B703	FIRE		2:30
70104	SR	B/703 - (Outage 977) - Fire Tech Support	DAOF-B703	FIRE		2:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

70071	SR	703 (SERVICE REQUEST) SECOND FLOOR NORTH - THREE SPRINKLER HEADS ARE TOO LOW AND NEED TO BE SHORTENED.	DAOF-B703	FIRE		6:30
70106	SR	B/703 N: Outage # 976 - Fire Tech Support	DAOF-B703	FIRE		1:00
72574	SR	B/703 Outage # 1009 (Service Call) - Fire Tech Support	DAOF-B703	FIRE		1:30
72490	SR	B/4838 - (Outage # 1008) - Fire Tech Support	DFRC-B4838	FIRE		47:45:00
72568	SR	B/4810 - Outage # 1015 (Service Call) - Fire Tech Support	DFRC-B4810	FIRE		4:15
72462	SR	B/703 - (Outage # 1001) - Install New Fire Sprinklers	DAOF-B703	FIRE		3:00
72463	SR	B/703 - (Outage #1004) - Mirror Coating Facility	DAOF-B703	FIRE		1:30
74513	SR	DAOF - (Service Call) - Halon Extinguishers	DAOF-LAND	FIRE		0:00
74540	SR	NASA - DFRC - (Service Call) - Halon Fire Extinguishers	DFRC	FIRE		7:30
74766	SR	B/4838 CITC- (Service Call) - Flush Hydrant	DFRC-B4838	FIRE		4:45
74798	SR	B/4838 CITC - (Service Call) Flush Fire System	DFRC-B4838	FIRE		0:45
75463	SR	B703 - Outage #1026 - Installation of Fire Alarm Cable	DAOF-B703	FIRE		9:00
75398	SR	B/4801 & B/4802 - (Outage # 1024) - Fire Tech Support	DFRC-B4801	FIRE		7:05
75414	SR	B/703 2nd Flr S - (Outage #1030) - Relocate Fire Sprinkler	DAOF-B703	FIRE		1:00
79422	SR	B/703 SCI LABS 1 -2 - Outage #1038 - Fire Sprinklers	DAOF-B703	FIRE		3:30
79617	SR	B/4820 2nd fl - (Service Call) - Smoke Detectors	DFRC-B4820	FIRE		1:00
79523	SR	B/703 - (Service Call) - Testing of Doors	DAOF-B703	FIRE		3:00
79399	SR	B/4820 - (Service Call) - Disconnect/Cap Fire Sprinkler	DFRC-B4820	FIRE		7:00
79706	SR	CITC - (Service Call) - Training	DFRC-B4838	FIRE		1:00
79695	SR	B/4802 - (Service Call) - Deluge Cannons	DFRC-B4802	FIRE		7:30
81788	SR	NASA - (Service Call) - Review & Update Document	DFRC	FIRE		5:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

82145	SR	NASA - (Service Call) - Inspect all Evaporative Cooler Duct Detector Sampling Tubes and Elements.	DFRC	FIRE		17:30
81670	SR	B/4825 - (Service Call) - Install Additional Fire Extinguisher	DFRC-B4825-POST1	FIRE		0:40
81947	SR	B/4838B CITC - (Service Call) - Turn off Domestic Water	DFRC-B4838A	FIRE		0:50
82163	SR	B/4820 Hangar - (Outage #1077) - Riser Modifications	DFRC-B4820	FIRE		5:00
81786	SR	B/4820 1st Fl - Outage #1068 - Fire Tech Support	DFRC-B4820	FIRE		14:30
81642	SR	4851 (Service request) in "cage" room there is a fire extinguisher that needs to be relocated per Safety	DFRC-B4851	FIRE		0:10
81737	SR	B/4820 - Outage # 1060 - Fire Tech Support	DFRC-B4820	FIRE		5:45
82123	SR	B/4826 - (Service Call) - Fire Tech Support	DFRC-B4826	FIRE		4:00
81689	SR	B4820 - Outage # 1058 - Deluge Riser Modification	DFRC-B4820	FIRE		19:00
81690	SR	B/4820 Rm 201 - (Service Call) - Disable/Remove Smoke Detectors	DFRC-B4820	FIRE		1:00
81782	SR	B/4838 - (Outage # 1052) - Fire Tech Support	DFRC-B4838	FIRE		9:30
81798	SR	B/703 - Outage # 1062 - Fire Tech Support	DAOF-B703	FIRE		1:00
81672	SR	B/4838A CITC - Outage # 1051 - Fire Tech Support	DFRC-B4838	FIRE		8:30
84253	SR	B/4838 CITC - (Outage #1064) - Install/Test Fire Systems	DFRC-B4838	FIRE		20:00
84330	SR	B/703 SW - Hydrazine Cable	DAOF-B703	FIRE		2:30
86966	SR	B/4840 - (Outage #1093) - Global Hawk Fire Suppression	DFRC-B4840	FIRE		3:15
86901	SR	B/4853 - (Service Call) - Evaluate Fire Pumps 3 & 4	DFRC-B4853	FIRE	4801022	16:30
86839	SR	B/703 - (Service Call) - Assesment & Estimation	DAOF-B703	FIRE		0:00
86964	SR	B/4820 - (Outage #1095) - Modify FDC Piping	DFRC-B4820	FIRE		11:30
89680	SR	B/703 (SERVICE REQUEST) - FIRE DRILL	DAOF-B703	FIRE		2:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89621	SR	B/4838 - (Outage #1127) - Fire Sprinkler Relocation	DFRC-B4838	FIRE		6:00
89622	SR	B/4838 - (Outage # 1126) - Installation of Fire Devices/Program	DFRC-B4838	FIRE		4:00
89679	SR	B4820 2nd Fl - (Outage #1136) - Relocate Fire Sprinkler Line	DFRC-B4820	FIRE		2:00
89446	SR	B/703 - Outage #1117 - LAWA Pump Run	DAOF-B703	FIRE		3:00
89440	SR	B/4840 Rm 126 - (DR#459) - Fire Bell Installation	DFRC-B4840	FIRE		6:40
89647	SR	B/4820 - (Service Call) - Remove Water Motor Gong	DFRC-B4820	FIRE		0:30
89629	SR	B/4840 Rms 222-236 - (Outage # 1129) - Installation of Data Cables	DFRC-B4840	FIRE		2:00
91560	SR	B/4854 - (Service Call) - LO/TO Fuel Station	DFRC-B4854	FIRE		5:40
91570	SR	B/4820 - (Outage # 1142) - Convert Wet Systems	DFRC-B4820	FIRE		9:30
91624	SR	B/703 2nd Fl Labs - (Service Call) - Outage # 1145 - Fire System Connections	DAOF-B703	FIRE		22:30
93851	SR	B/4800 - (Outage # 1144) - Replacement of Smoke Detectors	DFRC-B4800-FLOOR2	FIRE		0:00
93848	SR	B/4820 - (Outage # 1148) - Installation of Sprinkler Drops	DFRC-B4820	FIRE		0:00
59103	SR	B/703 CONNEX BOX(ES) - RMV/RPLC CONNEX DOORS	DAOF-B703	GENERAL		0:00
59089	SR	4800-2804 hang mounting bracket	DFRC-B4800-FLOOR2	GENERAL		0:00
59141	SR	NASA FACILITY - FIRE DRILL SUPPORT	NASA-DRYDEN	GENERAL		1:00
59119	SR	B/4840 BAY 6 - (SERVICE CALL) - INSTALL SEC. PANEL	DFRC-B4840	GENERAL		4:00
59208	SR	B/4802 - (SERVICE CALL) - INSTALL SWITCHES	DFRC-B4802	GENERAL		0:00
59216	SR	B/4825 CAFE - (SERVICE CALL) - SUPPORT CHILI COOKOFF	DFRC-B4825-GIFT-SHOP	GENERAL		4:15
59134	SR	NASA - (SERVICE CALL) WEEKLY SAFETY INSPECTIONS	NASA-DRYDEN	GENERAL		0:00
59058	SR	4800 Second Floor	DFRC-B4800-FLOOR2	GENERAL		0:00
59063	SR	B/4820, 4823, 4876 - (SERVICE CALL) FIRE ALARM SUPPORT	DFRC-B4820	GENERAL		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

59042	SR	B/4823 RM 103 - (SERVICE CALL) ANCHOR SANDERS	DFRC-B4823	GENERAL		1:00
60176	SR	4847- (SERVICE CALL) - INSTALL GOVT HOIST	DFRC-B4847	GENERAL		0:00
61264	SR	B/4840 BAY 5 - (SERVICE CALL) RMV DC PWR SUPPLY	DFRC-B4840	GENERAL		0:00
61295	SR	NASA (B/4801, 4802, 4820) -SRVC CALL - LIGHT BULBS	NASA-DRYDEN	GENERAL		0:00
61294	SR	703 (Service Call) replace elevator light fixtures	DAOF-B703	GENERAL		0:00
63346	SR	4877 (Service Call) need "Fitness Center" sign	DFRC-B4877	GENERAL		4:00
63382	SR	B/4800 RM 2506B - (SRVC CALL) DEMO WALL	DFRC-B4800-FLOOR2	GENERAL		1:15
63381	SR	B/4800 RM 2506A - (SRVC CALL) DEMO WALL	DFRC-B4800-FLOOR2	GENERAL		2:00
63328	SR	B/4825 POST 1 SECURITY- (SERVICE CALL) BOLT BARREL	DFRC-B4825-POST1	GENERAL		0:00
63377	SR	NASA - (SERVICE CALL) WEEKLY SAFETY INSPECTIONS	NASA-DRYDEN	GENERAL		0:00
63354	SR	NASA - (SERVICE CALL) - FIRE TECH SUPPORT	NASA-DRYDEN	GENERAL		5:30
63349	SR	703-222 (Service Call) hang white board	DAOF-B703	GENERAL		0:15
63378	SR	B/4839 - (SERVICE CALL) - HANG PROJECTOR SCREEN	DFRC-B4839	GENERAL		3:00
63206	SR	B/4843 - (SERVICE CALL) - MOUNT GRINDER	DFRC-B4843	GENERAL		0:00
65597	SR	B/4800 Rm 2713 - (Service Call) - Hang Whiteboard	DFRC-B4800-FLOOR2	GENERAL		3:15
65588	SR	B4847 - (Service Call) Install Anchor Bolts	DFRC-B4847	GENERAL		1:30
65776	SR	B/4840 - (Service Call) - Install Locker	DFRC-B4840	GENERAL		1:15
65778	SR	B/716 - (Service Call) - Hang signs	DAOF-B716	GENERAL		0:00
65633	SR	B/4876 - (Service Call) - Vent Cover	DFRC-B4876	GENERAL		1:00
65684	SR	4800-2516 SERVICE CALL-HANG FILE BOXES	DFRC-B4800-FLOOR2	GENERAL		0:45
65553	SR	B/703 Rm 323K - (Service Call) Relocate items	DAOF-B703	GENERAL		0:00
65600	SR	B/4820 - (Service Call) - Signs, Bike Rack	DFRC-B4820	GENERAL		0:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

67976	SR	4800-2015/2120 (SERVICE CALL) IN ROOM 2015- PATCH AND PAINT SEVERAL SMALL HOLES LEFT AFTER TV BRACKETS REMOVED; IN ROOM 2120 REMOVE TV BRACKETS	DFRC-B4800-FLOOR2	GENERAL		0:00
68172	SR	B/4840 Rm 113C - (Service Call) - Hang Whiteboard	DFRC-B4840	GENERAL		1:15
70165	SR	B/4857 - (Service Call) - Adjust Desk	DFRC-B4857	GENERAL		2:15
70221	SR	4801-2100 (SERVICE REQUEST) - Video Camera Mounts	DFRC-B4801	GENERAL		10:45
70304	SR	4820 (SERVICE REQUEST) HANG AED BOX IN FIRST FLOOR ENTRYWAY HALL; POC IS RICH YOUNG	DFRC-B4820	GENERAL		0:30
70073	SR	703 (SERVICE REQUEST) SECOND FLOOR NORTH CONFERENCE ROOM - HANG SIX FILE BOXES	DAOF-B703	GENERAL		0:00
70224	SR	B/4800 RM 1012 - (Service Call) - Hang Clock	DFRC-B4800-FLOOR1	GENERAL		0:45
70255	SR	B/703 RM S233 - Install Whiteboard	DAOF-B703	GENERAL		0:35
70264	SR	B/703 - (Service Call) - Install TV bracket	DAOF-B703	GENERAL		1:15
70127	SR	B/4810 - (Service Call) Code F Move Tasks	DFRC-B4810	GENERAL		32:15:00
70087	SR	B/4800 RM 2712/2713 - (Service Call) - Remove Brackets	DFRC-B4800-FLOOR2	GENERAL		0:00
70220	SR	4850-100 (SERVICE REQUEST) REMOVE TV STAND, PATCH AND PAINT REMAINING HOLES	DFRC-B4850	GENERAL		0:00
73620	SR	4840 (SERVICE REQUEST) BAY 3 - INSTALL 2000ml SOAP DISPENSER; CONTACT GAYLE MARTIN OR RAUL SANCHEZ FOR SPECIFICS	DFRC-B4840	GENERAL		1:00
72322	SR	4800 (SERVICE REQUEST) RMS 2231 AND 2228: IN ROOM 2231 MOVE A WIHTE BOARD TO THE OUTER WALL WHICH IS A HARD WALL, THEN MOUNT A WHITE BOARD ON A CUBICLE PARTITION; IN ROOM 2228 TAKE DOWN A WHITE BOARD	DFRC-B4800-FLOOR2	GENERAL		0:00
72346	SR	B/4800 RM 1714 - (Service Call) Hang Whiteboard	DFRC-B4800-FLOOR1	GENERAL		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72330	SR	4840-118 (SERVICE REQUEST) REMOVE A PICTURE FROM THE WALL; ENTER ROOM FROM FIRST DOOR, IT IS A BIG PICTURE WITH A GREEN STICKY NOTE ON IT INDICATING IT IS THE ONE DUE TO BE REMOVED	DFRC-B4840	GENERAL		0:15
72515	SR	T-47 CUBE 29 (SERVICE REQUEST) HANG WHITE BOARD; SEE CHRIS IRWIN	DFRC-T-47	GENERAL		0:30
72505	SR	B/703 RM 343 - (Service Call) - Install Projectors/Screens	DAOF-B703	GENERAL		4:30
73616	SR	B/4800 - (Service Call) - Hang Paintings	DFRC-B4800-FLOOR1	GENERAL		30:00:00
72475	SR	4800-1724 (SERVICE REQUEST) QA OFFICE - HANG THREE PICTURES; SEE STEVE FOR SPECIFICS	DFRC-B4800-FLOOR1	GENERAL		1:30
72357	SR	703-234N (SERVICE REQUEST) HANG STAINLESS STEEL SHELF IN MEDICAL TO THE RIGHT OF THE GURNEY ON THE WALL PER DR. BENDRICK'S INSTRUCTIONS. DAWN WILL LEAVE A NOTE FOR APPROXIMATE PLACEMENT	DAOF-B703	GENERAL		0:40
72454	SR	4800 (SERVICE REQUEST) SECOND FLOOR: HANG WHITE BOARD IN ROOM 2716; HANG A PLAQUE IN THE HALL WAY BETWEEN ROOMS 2335 AND 2331	DFRC-B4800-FLOOR2	GENERAL		1:30
74778	SR	B/703 - (Service Call) - Secure IT Rack	DAOF-B703	GENERAL		0:00
74806	SR	B/4810 Parking Lot - (Service Call) - Handicap Parking	DFRC	GENERAL		12:00
74787	SR	B703 Rm S323 "K" - (Service Call) - Install Whiteboard	DAOF-B703	GENERAL		0:45
74777	SR	B/703 (Service Call) - Install Safety Tape	DAOF-B703	GENERAL		1:55
74774	SR	4800-1409 (SERVICE REQUEST) SEE LYDIA DORFMAN IN RM 1012 FOR ACCESS TO ANTHONY MORENO'S OFFICE IN 1409; HANG CLOCK	DFRC-B4800-FLOOR1	GENERAL		0:00
75528	SR	4840-118 (SERVICE REQUEST) HANG A FOAM BACKED POSTER IN THE HALL; SEE KURT FOR SPECIFICS	DFRC-B4840	GENERAL		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

75470	SR	700-S142A (SERVICE REQUEST) ASSEMBLE AND HANG A WHITE BOARD	DAOF-B703	GENERAL		1:00
79537	SR	DFRC - (Service Call) - Install (2) Portable Eyewashes	DFRC	GENERAL		3:30
79658	SR	B/4820 Rm 222 - (Service Call) - Whiteboard	DFRC-B4820	GENERAL		2:00
79621	SR	B/4802 - (Service Call) - Safety Day/Desert High School Ceremonies	DFRC-B4802	GENERAL		41:30:00
81664	SR	Exterior B/4840 - (Service Call) - FOD Sign	DFRC-B4840	GENERAL		0:30
82210	SR	NASA - (Service Call) - Program Irrigation Systems	DFRC	GENERAL		0:00
82217	SR	B/4800 Rms 2504 & 2508 - (Service Call) - Install Wall Plaques	DFRC-B4800-FLOOR2	GENERAL		0:30
84329	SR	B/4800 Rm 2148 - (Service Call) - Hang Pictures	DFRC-B4800-FLOOR2	GENERAL		2:00
84370	SR	B/4820 - (Service Call) - Cleaning of Flow Lab	DFRC-B4820	GENERAL		2:30
84371	SR	B/4820 - (Service Call) - Cleaning of Flow Lab	DFRC-B4820	GENERAL		2:00
89412	SR	B/4850 - (Service Call) - Installation of Bracket	DFRC-B4850	GENERAL		3:00
89606	SR	B/4845 Parking Lot - (Service Call) - Remove Sign	DFRC-B4845	GENERAL		0:15
89642	SR	B/4800 Rm 3202 - (Service Call) - Hang Whiteboards	DFRC-B4800-FLOOR3	GENERAL		2:45
89659	SR	B/4847 - (Service Call) - Installation of Brackets/Misc.	DFRC-B4847	GENERAL		3:15
89433	SR	B/4825 - (Service Call) - Cafeteria Patio	DFRC-B4825-GIFT-SHOP	GENERAL		4:50
89444	SR	NASA (B4801,4802,4826) - (Service Call) - Stripe Hangar Floor	DFRC	GENERAL		13:00
89672	SR	B/4800 - (Service Call) - Designate Smoking Area	DFRC-B4800	GENERAL		2:15
89673	SR	B/4801 - (Service Call) - Designate Smoking Area	DFRC-B4801	GENERAL		2:00
91553	SR	B/4825 - (Service Call) - Cafeteria Patio	DFRC-B4825-GIFT-SHOP	GENERAL		0:00
91521	SR	NASA - (Service Call) - Crack / Pot Hole Repairs	DFRC	GENERAL		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

91589	SR	B/4828 (Boneyard) - (Service Call) -Remove Metal from Bin	DFRC-B4828	GENERAL		0:30
91650	SR	B/703 Sophia Lab: (Service Call) - Install Brackets	DAOF-B703	GENERAL		0:00
65592	SR	NASA - (Service Call) - Reprogram T-stat	NASA-DRYDEN	HVAC		4:30
65751	SR	4809 TROUBLESHOOT EVAP COOLER #1	DFRC-B4809	HVAC	305006	4:30
65688	SR	NASA - (Service Call) - Reprogram T-stat	NASA-DRYDEN	HVAC		4:00
72386	SR	NASA Facility - (Service Call) - Install Programmable T-Stat	DFRC	HVAC		9:00
72448	SR	B/4876 - (Service Call) - Install Flashing On Duct	DFRC-B4876	HVAC	1002022	7:30
75433	SR	B/4800 FH 8A & 8B - (Service Call) - Shutdown Units	DFRC-B4800-FLOOR3	HVAC		1:00
75338	SR	703 (SERVICE REQUEST) ESTIMATE TO RECONNECT THE HVAC DUCTS ON THE NORTHWEST SECOND AND THIRD FLOORS	DAOF-B703	HVAC		3:45
79531	SR	B/4825 Cafe - (Service Call) - Service Ice Machines	DFRC-B4825-GIFT-SHOP	HVAC		4:45
79533	SR	B/4825 Cafe - (Service Call) - Service Ice Machines	DFRC-B4825-GIFT-SHOP	HVAC		4:30
81818	SR	B/4847 - (Service Call) - Programmable Thermostat	DFRC-B4847	HVAC		0:00
81815	SR	B/4841 - (Service Call) - Programmable Thermostat	DFRC-B4841	HVAC		3:00
81816	SR	B/4842- (Service Call) - Programmable Thermostat	DFRC-B4842	HVAC		1:30
81820	SR	B/4863 - (Service Call) - Programmable Thermostat	DFRC-B4863	HVAC		1:45
82053	SR	NASA - (Service Call) - Reprogram T-stat	NASA-DRYDEN	HVAC		4:00
81952	SR	4838 (service request) disconnect portable 5-ton unit to have it removed to the DAOF bldg 703	DFRC-B4838	HVAC		0:45
81671	SR	B/4840 Bays 1,2,3 - (Service Call) - Turn Off / On HVAC System	DFRC-B4840	HVAC		5:00
81808	SR	B/4838 - (Service Call) - Emergency Repair	DFRC-B4838	HVAC		8:00
81817	SR	B/4845 - (Service Call) - Programmable Thermostat	DFRC-B4845	HVAC		2:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

81819	SR	B/4857 - (Service Call) - Programmable Thermostat	DFRC-B4857	HVAC		2:00
81821	SR	B/4877 - (Service Call) - Programmable Thermostat	DFRC-B4877	HVAC		0:00
81822	SR	B/4826 - (Service Call) - Programmable Thermostat	DFRC-B4826	HVAC		0:00
84250	SR	"A" Area - (Service Call) - Reset AC Thermostats	DFRC	HVAC		4:00
84325	SR	B/4820 Flow Lab - (Service Call) - AC Install	DFRC-B4820	HVAC		2:00
86696	SR	4820 (service request) support to Mark Nelson and NASA subcontractor in determining if pneumatic lines are abandoned	DFRC-B4820	HVAC		1:45
86987	SR	703 (service request) calibrate the SHERLOCK 102 REFRIGERANT MONITOR and SENSOR located in the "chiller" room	DAOF-B703	HVAC		1:00
86689	SR	4838 (service request) CITC support for taking down main chiller starting at 7am 7/25/11	DFRC-B4838	HVAC		0:15
86708	SR	B/4800 FH6 Cooling Towers - (Service Call) - Bypass Valves	DFRC-B4800	HVAC		18:00
89663	SR	B/4823 - (Service Call) - Troubleshoot Industrial Freezer	DFRC-B4823	HVAC		0:00
89664	SR	B/4820 - (Service Call) - Investigate Drain	DFRC-B4820	HVAC		2:15
89327	SR	B/4982 - (Outage # 1109) - Installation of Valve	DFRC-B4982	HVAC		1:00
89524	SR	4800-3113 (SERVICE REQUEST) TRAPS AREA - CHECK TEMPERATURE AND HUMIDITY SO IT CONFORMS TO LATEST GUIDELINES FOR ELECTRONICS EQUIPMENT LONGEVITY	DFRC-B4800-FLOOR3	HVAC		0:00
89297	SR	B/703 - (Service Call) - Evaluate Ducting/Electrical to Portable AC Units	DAOF-B703	HVAC		3:00
89648	SR	B/4820 - (Service Call) - Evaluate Impact of Chiller Lines	DFRC-B4820	HVAC		1:30
89559	SR	B4800 FH1A - (Service Call) - Restart Chiller	DFRC-B4800	HVAC	1019001	1:00
91494	SR	B/4982 - (Service Call) - Chiller Training	DFRC-B4982	HVAC		5:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

91529	SR	B/4820 2nd Fl - (Outage # 1143) - Domestic Water Lines	DFRC-B4820	HVAC		5:00
91653	SR	B/4820 (SUB 3) - (Service Call) -Outage # 1137 - Connect Power to AFFF Pump Controllers	DFRC-B4820	HVAC		1:00
93804	SR	B/4838 - (Service Call) - Assist BMI In Switchover	DFRC-B4838	HVAC		2:00
63507	SR	NASA-DFRC collect trash only 11/19/2010	NASA-DRYDEN	JAN		18:00
87034	SR	B/4800 Rm 2412 - (Service Call) - Carpet Cleaning	DFRC-B4800-FLOOR2	JAN		3:30
59158	SR	B/703 - (SERVICE CALL) - ELEVATOR RECONFIGURATION	DAOF-B703	MECH		0:00
59142	SR	703-N232 wall mount monitor	DAOF-B703	MECH		0:45
63437	SR	4800 (SERVICE CALL) ROOM 1013 AND SURROUNDING ROOMS-REMOVE BRACKETS	DFRC-B4800-FLOOR1	MECH		0:45
63474	SR	4800-2804 (SERVICE CALL) MOUNT MONITOR	DFRC-B4800-FLOOR2	MECH		3:00
63478	SR	4808 (SERVICE CALL) MOUNT 52" TV	DFRC-B4808-LIFE-SUPPORT	MECH		4:00
63505	SR	703 (Service Call) install markers w/ anchors on ramp	DAOF-B703	MECH		1:15
63540	SR	4800-2340 (Service Call) hang poster	DFRC-B4800-FLOOR2	MECH		0:00
65760	SR	4820 (SERVICE CALL) WAREHOUSE-DEMARCATÉ FIRE EXTINGUISHER	DFRC-B4820	MECH		0:30
65559	SR	703 SERVICE CALL- FABRICATION SHOP_AIR LINES	DAOF-B703	MECH		0:00
65594	SR	B/703 Rm 332S - (Service Call) - Relocate whiteboard	DAOF-B703	MECH		0:00
65582	SR	B/703 Rm 243N - (Service Call) Install Insta-hot	DAOF-B703	MECH		0:00
65731	SR	4823 (SERVICE CALL) SEISMICALLY BRACE PORTABLE EYEWASH	DFRC-B4823	MECH		0:00
65713	SR	703 (SERVICE CALL) VCC & SCC-HANG AED BRACKETS	DAOF-B703	MECH		0:00
65723	SR	PARKING LOT #3-STANCHION HANDICAP PARKING	DFRC-NB058	MECH		1:30
66379	SR	703 (SERVICE CALL) INSTALL TWO SIGNS	DAOF-B703	MECH		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

68005	SR	703-S323B (SERVICE CALL) PATCH AND PAINT: SEE KARI ALVARADO	DAOF-B703	MECH		0:00
68084	SR	4800-2516 (SERVICE CALL) PAINT/TOUCH UP SOME SPACKLED SPOTS ON WALLS IN OFFICE	DFRC-B4800-FLOOR1	MECH		1:30
68110	SR	4825 CAFETERIA (SERVICE CALL) PULL BIG SCREEN AWAY FROM WALL FOR TV MAINTENENCE AND THEN REPLACE MONITOR; WILL NEED MANLIFT	DFRC-B4825-GIFT-SHOP	MECH		0:00
67929	SR	B/4800 - (Service Call) Roof Watch	DFRC-B4800	MECH		4:56
68074	SR	703-311S (SERVICE CALL) Hang Whiteboard	DAOF-B703	MECH		0:55
68093	SR	4808 (SERVICE CALL) NEED A BIT OF PAINT TOUCH UP IN THE TRAINING AREA	DFRC-B4807	MECH		0:00
68070	SR	Gate 1 - (Service Call) - Repair Pothole	DFRC-NB051	MECH		1:30
68188	SR	703 (Service Call) install markers w/ anchors on ramp	DAOF-B703	MECH		0:00
67926	SR	703 (SERVICE CALL) MOUNT LOCKERS ON WALLS	DAOF-B703	MECH		0:00
68135	SR	4800-2516 (SERVICE REQUEST) - PATCH & PAINT	DFRC-B4800-FLOOR1	MECH		0:30
70154	SR	4800-2117 AND 2305 (SERVICE CALL) SEE SUE (X3135) FOR ACCESS/SPECIFICS. ROOM 2117 HAS SEVERAL SHELVING UNITS THAT NEED AN OPENING CUT IN THEM FOR ACCESS TO WALL OUTLETS. ROOM 2305 HANG A WHITE BOARD	DFRC-B4800-FLOOR2	MECH		4:15
70121	SR	4800-2511 (SERVICE REQUEST) - REMOVE/INSTALL TV BRACKETS	DFRC-B4800-FLOOR2	MECH		2:00
70169	SR	B/703 - (Outage # 992) - Compressed Air	DAOF-B703	MECH		1:10
70194	SR	4800-2516 (SERVICE REQUEST) HANG A VERY LARGE PICTURE FOR SHAWN MCMARROW	DFRC-B4800-FLOOR2	MECH		2:00
70095	SR	703 (SERVICE CALL) NEED TECH TO OPERATE A MANLIFT FOR TWO HOURS ON 2/1/11 OR 2/2/11 DURING BUSINESS HOURS DURING A GPS ANTENNA TEST	DAOF-B703	MECH		0:00
70125	SR	4810-5 (SERVICE REQUEST) INSTALL DOOR STOPS FOR THE TWO NEW DOORS TO WORK CONTROL; ALSO...	DFRC-B4810	MECH		3:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

70290	SR	703-221 (SERVICE REQUEST) IN THIS ROOM THERE ARE TWO OFFICES THAT NEED ABOUT 5 PICTURES HUNG BETWEEN THEM. THE OFFICES BELONG TO TING SING AND BRENT COBLEIGH; SEE TARYN FOR SPECIFICS	DAOF-B703	MECH		0:00
72393	SR	B/703 Conf Rm - (Service Call) - Install Screens	DAOF-B703	MECH		0:00
72473	SR	703 (SERVICE REQUEST) FABRICATION SHOP - ANCHOR MACHINE; ALAN HAS NECESARRY HARDWARE FOR THE JOB	DAOF-B703	MECH		0:50
72381	SR	B/4840 Bays 1-3 - Install Rigid Piping	DFRC-B4840	MECH		0:00
72382	SR	B/4870 - Replace existing PVC	DFRC-B4870	MECH		0:00
72479	SR	4838-205 (SERVICE REQUEST) SEISMICALLY BRACE TWO TALL TAN STORAGE CABINETS THAT ARE OPPOSITE THE REST ROOMS	DFRC-B4838	MECH		0:00
74788	SR	4806 (SERVICE REQUEST) SAFETY ACTION ITEM #1980 - INSTALL A VENT PIPE ABOVE THE HYDROGEN CANISTER STORAGE AREA; QUALIFIERS: CAN BE NO EXHAUST FAN, HEIGHT REQUIREMENT TOPPED WITH TURBINE VENT	DFRC-B4806	MECH		8:15
74793	SR	703-S343 (SERVICE REQUEST) HANG A WHITE BOARD; SEE CHUCK JOHNSON OR ROBERT SAKAHARA FOR SPECIFICS	DAOF-B703	MECH		0:30
75381	SR	703 (SERVICE REQUEST) THIRD FLOOR SOUTHWEST NEAR IT CLOSET - MOUNT EVACUATION CHAIR; SEE TASHA FOR SPECIFICS AND LOCATION	DAOF-B703	MECH		0:20
75607	SR	DFRC NASA - (Service Call) - Service Portable Eyewashes	DFRC	MECH		13:00
75589	SR	B/4822 - (Service Call) - Valve & Gauge Replacement	DFRC-B4822	MECH		0:45
75604	SR	B/4982 - (Service Call) - Valve & Gauge Replacement	DFRC-B4982	MECH		1:15
75603	SR	B/4872 - (Service Call) - Valve & Gauge Replacement	DFRC-B4872	MECH		0:30
75597	SR	B/4840 - (Service Call) - Valve & Gauge Replacement	DFRC-B4840	MECH		1:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

75374	SR	703 (SERVICE REQUEST) TRASH PICK UP	DAOF-B703	MECH		3:00
75529	SR	B/703 - RM 231 - (Service Call) - Seismic Bracing	DAOF-B703	MECH		0:00
75562	SR	703 (SERVICE REQUEST) CHECK EIGHT PORTABLE EYEWASHES	DAOF-B703	MECH		5:10
75590	SR	B/4824 - (Service Call) - Valve & Gauge Replacement	DFRC-B4824	MECH		0:30
75586	SR	B/4800 - (Service Call) - Valve & Gauge Replacement	DFRC-B4800	MECH		1:45
75594	SR	B/4837 - (Service Call) - Valve & Gauge Replacement	DFRC-B4837	MECH		0:30
75596	SR	B/4838 - (Service Call) - Valve & Gauge Replacement	DFRC-B4838	MECH		0:30
75601	SR	B/4854 - (Service Call) - Valve & Gauge Replacement	DFRC-B4854	MECH		0:30
75335	SR	4820 (SERVICE REQUEST) EXTERIOR NORTH SIDE - CHECK HYDRAULIC LINES IN TWO PLACES AND REMEDY THE LINES RUBBING METAL TOGETHER.	DFRC-B4820	MECH		2:45
75592	SR	703 (SERVICE REQUEST) FOURTH FLOOR SOUTHWEST END AROUND CORNER FROM ELEVATOR - ATTACH CAGE TO WALL SO THE DOOR OF IT CAN BE LOCKED; SEE BOB FOR SPECIFICS	DAOF-B703	MECH		1:00
75375	SR	NASA DRYDEN (SERVICE REQUEST) TRASH PICK UP	NASA-DRYDEN	MECH		1:15
75587	SR	B/4720 - (Service Call) - Valve & Gauge Replacement	DFRC-B4720	MECH		2:00
75600	SR	B/4851 - (Service Call) - Valve & Gauge Replacement	DFRC-B4851	MECH		0:30
75557	SR	4800-2511 (SERVICE REQUEST) MOUNT TWO MONITORS ON WALL(S); LABOR ONLY, CUSTOMER HAS MONITORS AND HARDWARE	DFRC-B4800-FLOOR2	MECH		3:45
75588	SR	B/4800 - (Service Call) - Valve & Gauge Replacement	DFRC-B4800	MECH		0:45
75598	SR	B/4847 - (Service Call) - Valve & Gauge Replacement	DFRC-B4847	MECH		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

75599	SR	B/4850 - (Service Call) - Valve & Gauge Replacement	DFRC-B4850	MECH		0:30
75602	SR	B/4856 - (Service Call) - Valve & Gauge Replacement	DFRC-B4856	MECH		0:30
75409	SR	4830D (SERVICE REQUEST) CONFERENCE ROOM - HANG PROJECTOR SCREEN; CUSTOMER HAS PROJECTOR SCREEN	DFRC-B4830D	MECH		1:00
75440	SR	4800-1405 (SERVICE REQUEST) HANG BULLETIN BOARD; CUSTOMER HAS BOARD AND CORRESPONDING HARDWARE. SEE HOWARD NG x3803 FOR SPECIFICS	DFRC-B4800-FLOOR1	MECH		0:45
75445	SR	4826 (SERVICE REQUEST) PORTABLE STAGE - PROVIDE SOME KIND OF DETERRENT FOR BIRDS TRYING TO NEST ABOVE THE STAGE	DFRC-B4826	MECH		1:00
75424	SR	703-S142A (SERVICE REQUEST) HANG THREE MSDS CABINETS; WALL IS DRYWALL AND CABINETS ARE 2' 3"x2'	DAOF-B703	MECH		0:00
78240	SR	B/4820 - (Service Call) - Valve & Gauge Replacement	DFRC-B4820	MECH		3:30
79425	SR	703-311 (Service Request) unbolt and rebolt seismic bracing on a couple of cabinets so they can be moved. Needed on 3/11/11. See Anne for specifics.	DAOF-B703	MECH		0:00
79581	SR	4840-113C-Last cubicle (Service Request) hang a white board in Casie Clark's cubicle; See Sue for white board in 4800-2228	DFRC-B4840	MECH		4:00
79596	SR	703 (Service Request) Second floor North about 10 doors need numbers hung on them; See Sandy for numbers to hang	DAOF-B703	MECH		0:00
79704	SR	CITC - (Service Call) - Training	DFRC-B4838	MECH		1:30
79519	SR	4820 (Service Request) High bay - disk sander needs to be anchored down.; safety issue.	DFRC-B4820	MECH		1:45
79384	SR	4800-1504 (SERVICE REQUEST) HANG BULLETIN BOARD & APPROX. 10 PICTURES; SEE CHUCK OR KARI FOR SPECIFICS	DFRC-B4800-FLOOR1	MECH		3:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

79516	SR	NASA-Dryden (Service Request) Host EPA representative during annual inspections - pumps, relief valves, generators, etc.	NASA-DRYDEN	MECH		0:00
79707	SR	CITC - (Service Call) - Training	DFRC-B4838	MECH		0:00
79650	SR	B/703 (Outage 1076) - Replace Pressure Relief Valves	DAOF-B703	MECH		5:40
79703	SR	CITC - (Service Call) - Training	DFRC-B4838	MECH		2:00
79370	SR	4820 (SERVICE CALL) WAREHOUSE - UNBOLT THE CANTILEVER SHELVES FREE FROM THE FLOOR THEN REMOVE OR CUT THE REMAINING BOLTS FLUSH WITH THE FLOOR	DFRC-B4820	MECH		1:00
79413	SR	703-342 (Service Request) Hang a clock; customer has hardware for it.	DAOF-B703	MECH		0:00
79597	SR	703-S211 (Service Request) Hang 2 small white boards	DAOF-B703	MECH		0:00
79690	SR	4823 (Service Request) Second floor in NDI Lab need tie offs for when horizontal doors to first floor are opened; Safety issue	DFRC-B4823	MECH		0:00
79691	SR	4823 (Service Request) Anchor approx 15 machines to the ground for safety purposes	DFRC-B4823	MECH		0:00
81688	SR	B/703 - (Service Call) - Install Fire Plan Box	DAOF-B703	MECH		0:45
81662	SR	B/703 - (Service Call) - Piping Inspection	DAOF-B703	MECH		0:00
81698	SR	4876 (service request) connex behind warehouse has holes in the roof that need to be covered up; lead paint is an issue. See Jim regarding specifics	DFRC-B4876	MECH		0:00
81661	SR	Bulding 4800 Room 1029 Seismic brace two shelves and 2 cabinets	DFRC-B4800	MECH		0:00
81667	SR	4850 (service request) cabinet door fell off and needs to be put back on; see Sandra for specifics	DFRC-B4850	MECH		0:30
81668	SR	4800-2005 (service request) valance is coming down off the window	DFRC-B4800-FLOOR2	MECH		1:00
81763	SR	703-Hangar (service request) place carpet over hangar "danger zones" for Media Day. Must be completed prior to 06/08/2011	DAOF-B703	MECH		1:40

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

81905	SR	NASA Dryden (service request) escort techs around to each of the compressors	DFRC	MECH		1:00
81740	SR	4825 (service request) wash off back patio of building	DFRC-B4825	MECH		8:45
82008	SR	4847 (service request) "Restricted Area" sign torn down by wind; need to order new sign as the old one is faded and worn. See Ted Rothaupt for old sign and specifics	DFRC-B4847	MECH		0:45
82161	SR	T-20 (service request) mount a very large screen tv to be used for a flight report data feed. See Nick for specifics.	DFRC-T-20	MECH		3:00
81686	SR	703 (service request) Portable eyewash stations to be charged and put into PM system; see Zaheer Ali ph# 650-417-8405	DAOF-B703	MECH		0:30
81687	SR	4800 (service request) to meet ADA requirements: ladies room 1016 add a soap dispenser on the side wall at 48" high; mens room 1418 add a soap dispenser on side wall 48" high and insulate all exposed	DFRC-B4800-FLOOR1	MECH		1:30
84276	SR	4823 (service request) need a machine anchored; see Andy for specifics	DFRC-B4823	MECH		1:00
84293	SR	B/703 - (Service Call) - Replace Wind Socks	DAOF-B703	MECH		3:00
84244	SR	4801-112 (service request) hang a 48"x96" white board on a drywall surface	DFRC-B4801	MECH		3:00
84183	SR	4800-1013-cubicle 7 (service request) lower a desk to meet ergonomic standards for customer	DFRC-B4800-FLOOR1	MECH		2:00
84292	SR	703-S212 (service request) install new paper towel dispenser into new kitchenette area	DAOF-B703	MECH		0:35
84277	SR	4851 (service request) hang AED mounting box on wall.	DFRC-B4851	MECH		0:30
84372	SR	Sub 26 - (Service Call) - Test and PM	DFRC-NB125	MECH		0:00
84280	SR	4857 (service request) hang AED mounting box on wall.	DFRC-B4857	MECH		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

84172	SR	4800-3103 ((service request) hang a vacuum wall mount on a concrete wall; see Rich for specifics	DFRC-B4800-FLOOR3	MECH		0:45
84396	SR	703 (service request) High Bay Mirror Coating Facility - attach crane log book to wall beside electrical disconnect	DAOF-B703	MECH		1:00
84287	SR	4800-1617 (service request) hang a bracket for a flat screen tv, the customer has the needed hardware	DFRC-B4800-FLOOR1	MECH		1:45
84369	SR	Sub 26 - (Service Call) - Troubleshoot Generator	DFRC-NB125	MECH		4:00
85454	SR	B/703 (Service Request) - Bird Proof Hangar Door	DAOF-B703	MECH		6:00
87038	SR	B/703 - (Service Call) - Outage #1106 - Reinstall Calibrated Gas Meter	DAOF-B703	MECH		2:00
86711	SR	DAOF - (Service Call) - Handicap Parking Stalls	DAOF	MECH		16:40
86925	SR	B/4809 - (Service Call) - Install New Auto Hoist	DFRC-B4809	MECH		26:45:00
86882	SR	NASA - (Service Call) - Skylight Inspections	DFRC	MECH		0:30
86777	SR	4847 (service request) install new hoist	DFRC-B4847	MECH		5:00
86977	SR	B/4844 Restroom - (Service Call) - Insulate HW Piping	DFRC-B4844	MECH		1:00
86884	SR	B/703 - (Service Call) - Install TV Brackets / GPS Antenna	DAOF-B703	MECH		2:00
86778	SR	4847 (service request) remove existing hoist	DFRC-B4847	MECH		3:15
86922	SR	4800-1409 (service request) raise Jeremy Cable's desk to meet ergonomic standards for customer	DFRC-B4800-FLOOR1	MECH		0:30
89658	SR	B/703 VCC- (Service Call) - Hang Frames	DAOF-B703A	MECH		0:25
89678	SR	703-322S (SERVICE REQUEST) BRACE STORAGE BOXES WITH BAR AND L-BRACKETS; SEE KAREN FOR SPECIFICS	DAOF-B703	MECH		0:00
89568	SR	703 (SERVICE REQUEST) NEED SAND BAGS MADE AND PUT INTO PLACE IN CASE OF ANOTHER STORM AS THE LAST ONE CAUSED SOME FLOODING AND WATER DAMAGE.	DAOF-B703	MECH		4:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89400	SR	B/4820 2nd FL - (Outage #1110) - Hot Water Heat	DFRC-B4820	MECH		1:30
89599	SR	B/703 - (Service Call) - Air Compressor Relief Valve Testing	DAOF-B703	MECH		0:25
89600	SR	PARKING LOT #3 (SERVICE REQUEST) AND OVERFLOW PARKING NEED WEED ABATEMENT AND DELINEATORS PLACED FOR ORGANIZED TRAFFIC FLOW. SEE KEVIN ANDREWS x 7614 FOR DELINEATOR PLACEMENT	DFRC-NB058	MECH		7:45
89613	SR	B/4800-2607 - (SERVICE CALL) - DOOR NEEDS CLOSER	DFRC-B4800-FLOOR2	MECH		0:00
89616	SR	B/703 Rm N213 - (Service Call) Install Projector Screen	DAOF-B703	MECH		0:50
89674	SR	4800-1025 (SERVICE REQUEST) HANG A CLOCK IN JOHN KELLY'S OFFICE. SEE JOHN FOR SPECIFICS x 2308	DFRC-B4800-FLOOR1	MECH		0:15
89333	SR	4800-1115B (SERVICE REQUEST) MOVE SHELF AND BRACKETS APPROX. 10FT	DFRC-B4800-FLOOR1	MECH		2:00
89311	SR	NASA - (Service Call) - Backflow Job Walk	NASA-DRYDEN	MECH		8:15
89649	SR	703 (SERVICE REQUEST) SOUTH EAST SIDE - TO KEEP EQUIPMENT AND VEHICLES OUT OF FIRE DEPT ACCESS AREA IT NEEDS TO BE PAINTED WITH YELLOW STRIPING.	DAOF-B703	MECH		0:00
89498	SR	4847 NEED "T" IN AIR LINE TO HAVE SHOP AIR ON BOTH SIDES OF BUILDING	DFRC-B4847	MECH		0:00
89503	SR	PARKING LOT #3 (SERVICE REQUEST) AND OVERFLOW PARKING NEED WEED ABATEMENT AND DELINEATORS PLACED FOR ORGANIZED TRAFFIC FLOW. SEE KEVIN ANDREWS x 7614 FOR DELINEATOR PLACEMENT	DFRC-NB058	MECH		5:30
89373	SR	B/703 VCC - (Service Call) - Patch and Paint Wall	DAOF-B703A	MECH		4:00
89441	SR	B/4840 Bay 6 - (DR# 471) Service Call - Aircraft Jacks	DFRC-B4840	MECH		3:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89601	SR	PARKING LOT #3 (SERVICE REQUEST) AND OVERFLOW PARKING NEED WEED ABATEMENT AND DELINEATORS PLACED FOR ORGANIZED TRAFFIC FLOW. SEE KEVIN ANDREWS x 7614 FOR DELINEATOR PLACEMENT	DFRC-NB058	MECH		8:30
89637	SR	703 (SERVICE REQUEST) SOUTH EAST ROLLING GATE NEEDS A NEW SIGN HUNG ON IT. THE SIGN IS IN TASHA'S CUBICLE.	DAOF-B703	MECH		0:25
89372	SR	B/703 VCC - (Service Call) - Carpentry Tasks	DAOF-B703A	MECH		3:20
89403	SR	NASA-DRYDEN (SERVICE REQUEST) ON 9/13/11 SET UP APPROX 7 SIGNS ON A-FRAMES FOR DIRECTIONS TO A 9/14/11 EVENT AT BLDG 4833; SEE RONNIE FOR SPECIFICS	NASA-DRYDEN	MECH		4:45
91674	SR	DAOF - (Service Call) - Sewage Lift Station Levels	DAOF	MECH		0:00
91495	SR	T-13, T-16, T-17: (Service Call) - Secure Water	DFRC	MECH		1:00
91496	SR	T-13, T-16, T-17: (Service Call) - Secure Electricity	DFRC	MECH		2:00
91690	SR	B/4802 - (Service Call) - Open Vault	DFRC-B4802	MECH		0:15
91694	SR	703-321 (SERVICE REQUEST) SEISMICALLY ANCHOR THREE STORAGE SHELVES	DAOF-B703	MECH		0:00
91564	SR	703-N242 (SERVICE REQUEST) CUBICLES "A" THROUGH " L" - 12 CABINETS NEED TO BE SIESMICALLY BRACED; ROOM N233 (FATIGUE COUNTERMEASURE FACILITY) SEISMICALLY BRACE LARGE CABINET	DAOF-B703	MECH		0:00
91526	SR	4840-222A (SERVICE REQUEST) PATCH AND PAINT A VERY SMALL SECTION OF THE DOOR TO THE ROOM; THE OFFICE NUMBER WAS PULLED OFF OF THE DOOR AND TOOK THE FINISH WITH IT	DFRC-B4840	MECH		0:54
91594	SR	4820-223 (SERVICE REQUEST) LOAD FRAME ROOM HAS TWO BENCH GRINDERS THAT NEED TO BE ANCHORED TO THE FLOOR	DFRC-B4820	MECH		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

91618	SR	4982 (SERVICE REQUEST) SUPPORT FLIGHT MISSION DURING AN AIR FORCE POWER OUTAGE RUNNING GENERATORS FROM 12:00PM TO POSSIBLY AS LATE AS 7:00PM 10/6/11	DFRC-B4982	MECH		4:00
91660	SR	4865 (SERVICE REQUEST) ANCHOR 15 RACKS TO THE GROUND FOR SEISMIC BRACING	DFRC-B4865	MECH		0:00
91663	SR	4865 (SERVICE REQUEST) PAINT DEMARCATIONS ON FLOOR DESIGNATING VARIOUS PARTS AND SAFETY AREAS NEEDED FOR SHUTTLE ASSETS BREAKDOWN	DFRC-B4865	MECH		0:00
91666	SR	DAOF (SERVICE REQUEST) CRYOGEN BLDGS - NEED LADDER TO APPLY ADHESIVE BACKED HAZMAT NUMBERS TO INSTALLED NFPA SIGNS. 12 NUMBERS TOTAL, 3 EA. ON 4 SIGNS. SEE RALPH FOR MATERIALS	DAOF	MECH		0:00
91667	SR	703A (SERVICE REQUEST) HANG ONE WHITE BOARD ON SCC	DAOF-B703A	MECH		0:00
91668	SR	4840 (SERVICE REQUEST) REMOVE PARTITION BETWEEN RMS 135 & 136. THERE ARE NO ELECTRICAL COMPONENTS TO THIS PARTITION. SEE KNUT FOR SPECIFICS.	DFRC-B4840	MECH		0:00
93880	SR	B/4802 - (Service Call) - Event Set Up/Tear Down	DFRC-B4802	MECH		0:00
93862	SR	B/703S - (Service Call) - Restrooms/Break Area Back In Service	DAOF-B703	MECH		0:00
93867	SR	4840-221 (SERVICE REQUEST) SEISMICALLY BRACE TWO RACKS AND TWO CABINETS ON THE FAR WALL OF THE ROOM.	DFRC-B4840	MECH		0:00
93834	SR	4800-1409B (SERVICE REQUEST) CODE "C" CONFERENCE ROOM - MOUNT WIRELESS PROJECTOR ON CEILING	DFRC-B4800-FLOOR1	MECH		0:00
93842	SR	4854 (SERVICE REQUEST) ASSISTANCE IS NEEDED TO GAIN PHOTO RECORD OF SOON TO BE DEMOLISHED ROOF	DFRC-B4854	MECH		0:30
93810	SR	B/4985 - (Service Call) - Anchor Machinery	DFRC-B4985	MECH		1:00
59025	TC	B/4802 HANGAR - RESET BREAKER		ELEC		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

65700	TC	4800-2121 RESTORE LIGHT USAGE	DFRC-B4800-FLOOR2	ELEC		3:30
65784	TC	B/703 - S/E Elevator - Emergency Phone	DAOF-B703	ELEC		4:00
65596	TC	B/4832 - Reset Breaker	DFRC-B4832-COMPUTER-SUPPORT	ELEC		0:30
65637	TC	B/4982 - Outage # 960 - Elect. Support	DFRC-B4982	ELEC		3:30
65659	TC	4820-124 CHECK 480V RECEPTACLE	DFRC-B4820	ELEC		0:30
65636	TC	B/4810 Rm 12 - Outage # 957 Elect Support	DFRC-B4810	ELEC		2:00
65646	TC	B/4840 Rm 113C - Breaker Tripping	DFRC-B4840	ELEC		0:30
65650	TC	B/0192 LRO - No Power	DFRC-B192	ELEC	803002	5:00
65662	TC	B/4800 Rm 1811 - Replace lights	DFRC-B4800-FLOOR1	ELEC		1:00
65663	TC	B/4840 - Demark #2	DFRC-B4840	ELEC		0:00
65644	TC	B/4840 Bays 1,2,3 - Replace lights	DFRC-B4840	ELEC		13:00
65599	TC	B/4800 Rm 1726 - Lighting	DFRC-B4800-FLOOR1	ELEC		0:30
65730	TC	B/4877 - Fan repair	DFRC-B4877	ELEC		3:00
65734	TC	4820-SHUT DOWN SUB PANEL FOR CONTRACTORS	DFRC-B4820	ELEC		1:30
65737	TC	4800-3305 CHANGE LIGHT OUT	DFRC-B4800-FLOOR3	ELEC		1:00
65756	TC	B/4800 - Breaker Tripped	DFRC-B4800-FLOOR1	ELEC		0:30
65681	TC	4800 ROOF-TROUBLESHOOT ELECTRONIC SWITCH ON TELEMETRY DISH	DFRC-B4800	ELEC		2:00
65643	TC	B/4800 Rm 2412 - Replace light bulbs	DFRC-B4800-FLOOR2	ELEC		1:00
65655	TC	Substation 16 - Troubleshoot "buzzing" noise	DFRC-NB089	ELEC		42:30:00
65762	TC	4851 CHECK POWER PANEL CIRCUITS	DFRC-B4851	ELEC		1:00
65585	TC	B/0192 LRO - (Outage # 962) Elect Support	DFRC-B192	ELEC	803002	6:00
65715	TC	703 TOOL CRIB-COMPUTERS NOT WORKING	DAOF-B703	ELEC		0:30
65718	TC	4854-CHECK BREAKER AT FUELING STATION	DFRC-B4854	ELEC		2:30
65725	TC	B/4800 - Replace overhead light	DFRC-B4800-FLOOR1	ELEC		0:30
65587	TC	B/4800 Exterior - Rpr/Rplc Outlet	DFRC-B4800-FLOOR1	ELEC		2:00
65634	TC	B/4800 Rm 1100 - Replace broken bulb	DFRC-B4800-FLOOR1	ELEC		0:30
65739	TC	B/4841 - Cal Lab - Replace Light	DFRC-B4841	ELEC		2:00
65614	TC	4800-3113 EXIT SIGN BULB OUT	DFRC-B4800-FLOOR3	ELEC		1:00
65616	TC	4800-1729 REPLACE LIGHTS OUT	DFRC-B4800-FLOOR1	ELEC		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

65782	TC	4825-REPAIR LIGHT IN DARLENE HOMIAK'S OFFICE	DFRC-B4825-POST1	ELEC		1:00
66066	TC	4800-1022 REPAIR ELECTRICAL ERASEWAY	DFRC-B4800-FLOOR1	ELEC		0:00
65975	TC	4838-201-19R EMERGENCY LIGHT NOT WORKING	DFRC-B4838	ELEC		1:00
68024	TC	B/4840 Rm 226 - Lighting	DFRC-B4840	ELEC		2:00
68034	TC	4800-1716 CHECK GFCI RECEPTACLE-CUSTOMER SAYS IT FAILED A TRIP TEST BY TAKING TOO LONG TO TRIP	DFRC-B4800-FLOOR1	ELEC		1:00
67986	TC	4982-GENERATORS JUST STARTED UP-9:46AM	DFRC-B4982	ELEC		1:00
68048	TC	B/703 - Repair light	DAOF-B703	ELEC		1:00
68076	TC	Gate 47 - Gate repair	DFRC-GATE-47	ELEC		16:00
68080	TC	4823 CHEM CRIB-LIGHT OUT	DFRC-B4823	ELEC		1:00
67948	TC	NASA FACILITY - "A" AREA: PLEASE TROUBLESHOOT AND RESET BREAKERS 23 AND 24 THAT ARE TRIPPED AGAIN THESE BREAKERS CONTROL SECURITY CAMERAS 18 AND 19. SEE TIM FOR DETAILS. THANKS	NASA-DRYDEN	ELEC		0:30
68144	TC	4876 CHANGE SEVERAL (4) SHORT LIGHTS THAT ARE OUT DOWNSTAIRS IN THE BIN ROWS	DFRC-B4876	ELEC		1:00
67925	TC	GATE 47-STUCK OPEN; INOPERABLE	DFRC-GATE-47	ELEC		5:00
68087	TC	4841 REPLACE SOME LIGHTS THAT ARE OUT.	DFRC-B4841	ELEC		1:30
67946	TC	4800 Please check the handicapped door that is nearest bldg 4801. It is stuck open. Thank you.	DFRC-B4800-FLOOR1	ELEC		0:30
68111	TC	4803 CHECK BREAKER; SEVERAL RECEPTACLES HAVE LOST POWER	DFRC-B4803	ELEC		0:30
68112	TC	4810 CHECK LIGHTS THROUGHOUT NORTH HALF OF BLDG FROM MAIN DOOR OVER SO THE "CODE F AREA" HAS SUFFICIENT LIGHTING; SOME LIGHTS ARE OUT, SOME FLICKER.	DFRC-B4810	ELEC		1:00
67916	TC	4843-LOCK SHOP/SECURITY-POWER LOSS TO ONE RECEPTACLE	DFRC-B4843	ELEC		1:00
68021	TC	B/4820 RM 105 - Loss of Power	DFRC-B4820	ELEC		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

67910	TC	4800 3RD FL FOYER-CHANGE PICTURE LIGHT	DFRC-B4800-FLOOR3	ELEC		1:30
67914	TC	4800-1418 MENSROOM-SOME LIGHTS OUT	DFRC-B4800-FLOOR1	ELEC		0:30
67953	TC	4838 Please check several exit lights that have one or more bulbs out: rms.111 and 112, entrance hall on the east side and exit hall on the west side; and on the second floor: rms. 205 and 214 as well	DFRC-B4838	ELEC		1:00
68073	TC	GATE 48 TROUBLESHOOT INOPERABLE GATE	NASA-DRYDEN	ELEC		4:00
68098	TC	B/4800 Rm 1409B - Replace Light	DFRC-B4800-FLOOR1	ELEC		0:30
68105	TC	4820 REPAIR/REPLACE SUMP PUMPS IN ELECTRICAL AND COMMUNICATIONS VAULTS	DFRC-B4820	ELEC		7:00
68139	TC	4810 MENSROOM LIGHTS OUT AND WILL NOT COME BACK ON	DFRC-B4810	ELEC		0:30
67984	TC	B/703 - S/E Elevator not working	DAOF-B703	ELEC		1:00
68157	TC	B/4806 - Lights	DFRC-B4806	ELEC		1:15
68163	TC	4840-156 REPLACE DESK TOP LAMP FLUORESCENT BULB	DFRC-B4840	ELEC		0:30
68185	TC	703 BOILER ENCLOSURE-CHANGE OUT BAD GFI RECEPTACLE	DAOF-B703	ELEC		1:00
68187	TC	4823 CHEM CRIB LOCKER "E" - LIGHT OUT INSIDE LOCKER	DFRC-B4823	ELEC		0:30
67934	TC	4800 FH6 REPAIR RECEPTACLE	DFRC-B4800	ELEC		1:00
67951	TC	4825 Guard Post One-Please check three security cameras down and power out. Thank you.	DFRC-B4825	ELEC		1:00
67957	TC	4800-1512 Please check a possible tripped breaker. Thank you.	DFRC-B4800-FLOOR1	ELEC		0:00
67975	TC	4800-1512 TWO RECEPTACLES WITH NO POWER ON SAME WALL	DFRC-B4800-FLOOR1	ELEC		0:30
67978	TC	B/4820 - Air Compressor #1 - Rebuild mag starter	DFRC-B4820	ELEC	403002	6:30
68008	TC	4800-1115 CHANGE LIGHT OUT ON WORK BENCH	DFRC-B4800-FLOOR1	ELEC		0:15
68011	TC	4800-1708 CHANGE SEVERAL (11) CEILING LIGHTS THAT ARE OUT.	DFRC-B4800-FLOOR1	ELEC		1:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

68013	TC	4800-2717 CHECK ON BEEPING. MAY BE FROM UPS .	DFRC-B4800-FLOOR2	ELEC		0:15
68014	TC	703 MAIN VEHICLE GATE_NE SIDE OF BLDG-THE GATE IS INOPERABLE; THE BADGE READERS DO NOT WORK REMOTELY OR IN PERSON-GATE HAS TO BE HAND-DRILL MANIPULATED	DAOF-B703	ELEC		2:00
68039	TC	4825 GIFT SHOP-HANDICAPPED DOORS NOT CLOSING	DFRC-B4825-GIFT-SHOP	ELEC		0:00
68040	TC	703 NE HANGAR DOOR NOT CLOSING PROPERLY	DAOF-B703	ELEC		1:00
68059	TC	B/4800 Rm 1422 - Light	DFRC-B4800-FLOOR1	ELEC		0:30
68069	TC	B/4826 - Replace Overhead Lights	DFRC-B4826	ELEC		0:00
67973	TC	4825-SECURITY: LIGHTS OUT AROUND MURALS/PICTURES	DFRC-B4825-POST1	ELEC		0:45
67918	TC	NASA - Handicap Gates down	NASA-DRYDEN	ELEC		4:30
67927	TC	4807 RESTROOM LIGHTS OUT OR FLICKERING	DFRC-B4807	ELEC		3:15
68026	TC	NASA - Repair Sign	NASA-DRYDEN	ELEC		0:00
68160	TC	4800-1409B CUBICLE 4-REPLACE BURNED OUT 4'FLUORESCENTS OVER DESK	DFRC-B4800-FLOOR1	ELEC		0:30
68161	TC	4850-111 CHECK POWER OUT ALONG BOTH SIDES OF ONE WALL	DFRC-B4850	ELEC		0:15
68006	TC	4833-103 CHECK A PANEL SEVERAL TV'S ARE PLUGGED INTO THAT KEEPS "POPPING" EVEN AFTER THE BREAKER WAS FLIPPED BACK ON.	DFRC-B4833	ELEC		3:00
68128	TC	4838-120 ONE LIGHT OUT AND ONE FLICKERING INTERMITTENTLY	DFRC-B4838	ELEC		0:30
68134	TC	4800-1012 REPLACE LIGHT OUT OVER VAL ZELLMER'S DESK.	DFRC-B4800-FLOOR1	ELEC		0:30
70118	TC	4800-3302 LIGHT FIXTURE HAS BULBS FLICKERING AND NEED TO BE CHANGED OUT; THE FIXTURE IS NEAR JACK SHELDON'S DESK	DFRC-B4800-FLOOR3	ELEC		0:30
70163	TC	B/4820 RM 202 - Loss Of Power	DFRC-B4820	ELEC		1:00
70114	TC	B/4800 Rm 2520 - Overhead Light	DFRC-B4800-FLOOR1	ELEC		0:30
70150	TC	B/4809 - Overhead Lighting	DFRC-B4809	ELEC		4:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

70032	TC	4800-2100 EXEC. CONF. RM. - CHECK INTO REMOVING 2 CONTROL SWITCHES TO THE PROJECTOR SCREEN AND COVERING THE LOCATIONS WITH PLATES; SEE TIM PETERS FOR SPECIFICS	DFRC-B4800-FLOOR2	ELEC		2:00
70033	TC	4820 LADIES ROOM-LIGHT OUT	DFRC-B4820	ELEC		0:30
70316	TC	4809 ELECTRICALLY DISCONNECT POWER TO VEHICLE LIFT; SEE ED MATHIESON FOR SPECIFICS	DFRC-B4809	ELEC		2:00
70105	TC	4800-2407 HUMAN RESOURCES - CHECK FLICKERING LIGHTS; OCCUPANT BELIEVES THEY MAY BE THE EMERBENCY LIGHTS	DFRC-B4800-FLOOR2	ELEC		1:15
70266	TC	4800-1028 POWER WENT OUT AT WORK STATION	DFRC-B4800-FLOOR1	ELEC		0:30
70229	TC	4800-1409A POSSIBLE BREAKER TRIPPED; COMPUTER NOT POWERING ON	DFRC-B4800-FLOOR1	ELEC		1:00
70278	TC	Substation 12 (B/4830) - Troubleshoot meter	DFRC-NB095	ELEC		1:00
70132	TC	Gate 47 - Continued Repair	DFRC-GATE-47	ELEC		17:00
70142	TC	703 TROUBLESHOOT/REPAIR 110V RECEPTACLE ASSOCIATED WITH A GPS ANTENNA; WILL NEED TO USE MANLIFT	DAOF-B703	ELEC		3:00
70156	TC	703 THIRD FLOOR NORTHEAST CORNER HALLWAY HAS LIGHTS OUT - SAFETY HAZARD	DAOF-B703	ELEC		2:00
70096	TC	B/4800 Rm 1122 - Emergency Light	DFRC-B4800-FLOOR1	ELEC		1:15
70193	TC	4800-2523 LIGHTS FLICKERING OVER CONNIE HINES DESK	DFRC-B4800-FLOOR2	ELEC		0:00
70262	TC	4820 WAREHOUSE AND HI BAY- SEVERAL OVERHEAD LIGHTS OUT; MAY NEED MANLIFT.	DFRC-B4820	ELEC		8:00
70292	TC	B/703 NW MENS - REPLACE BULBS	DAOF-B703	ELEC		2:00
70141	TC	4800-1013 LIGHT OUT OVER EILEEN DITKA'S DESK	DFRC-B4800-FLOOR1	ELEC		1:30
70191	TC	4810 CODE F SIDE-WORKSTATION SHELVES NEED A FLUORESCENT WORK LIGHT; SEE VICKI GRAY	DFRC-B4810	ELEC		0:15
70026	TC	4800-2103 CHECK SENSOR SWITCH AS THE LIGHTS ARE CONSTANTLY ON.	DFRC-B4800-FLOOR2	ELEC		4:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

70038	TC	4801- EXTERIOR LIGHTS OUT ON PARKING LOT SIDE OF BLDG; THEY ARE ABOVE THE "DROIDS LAB". PLEASE GET TO THEM ASAP AS IT GETS VERY DARK AND IS A SAFETY HAZARD	DFRC-B4802	ELEC		2:00
70039	TC	4802- EXTERIOR LIGHTS OUT AT SOUTHEAST CORNER OF BLDG - ON THE FLIGHTLINE SIDE	DFRC-B4802	ELEC		2:00
70043	TC	4854 NO POWER TO JPTS (JET) FUEL TANK; SEE RON LARSON (PH# 661-341-8625) FOR MORE INFORMATION	DFRC-B4854	ELEC		6:30
70239	TC	B/703 RM 111 - No Power	DAOF-B703	ELEC		0:15
70298	TC	B/4825 Cafe - No Power	DFRC-B4825-GIFT-SHOP	ELEC		2:00
70302	TC	B/T-1 - Gate Operation	DFRC-T-42	ELEC		3:30
70077	TC	4840 SECOND FLOOR MENS ROOM - LIGHT OUT OVER URINALS	DFRC-B4840	ELEC		1:30
70081	TC	4800-1504 INSIDE THIS ROOM IS PENNY BARNHILL'S OFFICE WHICH HAS A LIGHT OUT	DFRC-B4800-FLOOR1	ELEC		0:30
70089	TC	B/4800 Rm 3302 - Electrical Outlet Repair	DFRC-B4800-FLOOR3	ELEC		0:30
70111	TC	B/T-20 - Overhead Lights	DFRC-T-20	ELEC		0:30
70113	TC	4800-2316 IN THE HALL NEAR THE OFFICE THERE ARE TWO OR MORE FIXTURES THAT HAVE LIGHTS OUT	DFRC-B4800-FLOOR2	ELEC		0:15
70131	TC	4820-202 HEATHER MALISKA'S CUBICLE - BLOWN FUSE	DFRC-B4820	ELEC		0:30
70187	TC	B/4820 - Lock Out Bridge Crane	DFRC-B4820	ELEC		0:30
70226	TC	B/4859 - Troubleshoot Sensor	DFRC-B4859	ELEC		2:00
70243	TC	B/T-47 - Overhead Light	DFRC-T-47	ELEC		1:00
70244	TC	B/4800 Rm 3103 - Antenna Not Working	DFRC-B4800-FLOOR3	ELEC		10:00
70245	TC	B/4800 RM 1412 - Replace missing bulbs	DFRC-B4800-FLOOR1	ELEC		0:30
70248	TC	4800-2321 LIGHT OUT IN OFFICE	DFRC-B4800-FLOOR2	ELEC		0:30
70271	TC	B/703 RM S334 - Troubleshoot Outlet	DAOF-B703	ELEC		1:00
70300	TC	B/4800 Rm 3113 - Lights	DFRC-B4800-FLOOR3	ELEC		1:00
70155	TC	B/703 - West Center Roll Up Door	DAOF-B703	ELEC	90047	1:00
70180	TC	4857 LIGHT OUT OVER JOE FERNANDEZ'S DESK	DFRC-B4857	ELEC		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

70225	TC	4800-1735 POSSIBLE TRIPPED BREAKER; COMPUTER NOT WORKING AND DETERMINED BY ODIN TO BE A "BLOWN FUSE"	DFRC-B4800-FLOOR1	ELEC		0:30
70272	TC	4800-1115 SOME LIGHTS ARE OUT	DFRC-B4800-FLOOR1	ELEC		0:30
70233	TC	4809 BREAKER TRIPPED BY SMALL HEATING UNIT	DFRC-B4809	ELEC		1:00
70235	TC	703-311 ENTRY WAY TO OFFICE HAS AN EMERGENCY LIGHT TURNING ON AND OFF	DAOF-B703	ELEC		0:00
70281	TC	4800-1810 LIGHT OUT IN LADIES ROOM	DFRC-B4800-FLOOR1	ELEC		1:00
70294	TC	4802 HANGAR - SOME LIGHTS OUT; SEE RICK	DFRC-B4802	ELEC		4:30
70099	TC	4820-123 "WATER TUNNEL" AT LEAST 9 LIGHTS OUT THAT NEED REPLACING	DFRC-B4820	ELEC		14:00
70182	TC	4824 CHECK EMERGENCY LIGHT-ONLY STAYS ON APPROX. 10 SECS AND IS VERY DIM. SEE JUSTIN FOR LOCATION	DFRC-B4824	ELEC		2:00
70192	TC	4876 OFFICE AREA-CHECK AN ELECTRICAL SMOKE SMELL IN THE AREA	DFRC-B4876	ELEC		0:30
70253	TC	B/4800 Rm 1504 - Room is dim	DFRC-B4800-FLOOR1	ELEC		0:30
72338	TC	4830A CONFERENCE ROOM - FLICKERING FLUORESCENT LIGHT	DFRC-B4830A	ELEC		1:00
72385	TC	4825 GIFT SHOP - BOTH BUTTONS FOR EACH OF THE HANDICAPPED DOORS ARE INOPERABLE	DFRC-B4825-GIFT-SHOP	ELEC		2:00
72428	TC	4840-202 CHECK ELECTRICAL BURNING SMELL	DFRC-B4840	ELEC		0:15
72308	TC	4800-1720 CHANGE TWO BURNED OUT LIGHTS OVER CLINTON NELSON'S DESK	DFRC-B4800-FLOOR1	ELEC		2:30
72309	TC	4823 MACHINE SHOP - CHECK POWER TO SAW THAT IS SUDDENLY INOPERABLE; WORK STOPPAGE	DFRC-B4823	ELEC		2:00
72323	TC	SUBSTATION 12 REPAIR POTENTIAL TRANSFORMERS	DFRC-NB095	ELEC		8:00
72445	TC	Buckhorn (B/4720) - Remove Power Cord	DFRC-B4984	ELEC		1:00
72466	TC	4825 CAFETERIA - IN THE AMERICAN EATERY OVER THE DEEP FRYER ARE TWO BURNED OUT LAMPS THAT NEED REPLACING	DFRC-B4825-GIFT-SHOP	ELEC		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72345	TC	B/4800 RM 1714 - Under Shelf Lighting	DFRC-B4800-FLOOR1	ELEC		0:30
72495	TC	4800 HORSESHOE EXTERIOR - CHECK THE GEM CART PLUGS; TWO OF THEM ARE NOT POWERING UP THE GEM CARTS.	DFRC-B4800-FLOOR1	ELEC		0:30
72499	TC	4832 LIGHTS OUT; 24 IN WAREHOUSE, 2 IN OFFICE, 1 IN MAILROOM. THEY ARE ALL HIGH UP AND WILL NEED A MANLIFT EXCEPT THE OFFICE AND MAILROOM	DFRC-B4832-MAIL-ROOM	ELEC		6:00
72535	TC	B/703 Rm 111N - Lighting	DAOF-B703	ELEC		1:00
72387	TC	B/4800 Rm 1115 - Troubleshoot light sensor	DFRC-B4800-FLOOR1	ELEC		0:15
72411	TC	B/4800 Rm 2016 - Install additional outlet/power	DFRC-B4800-FLOOR2	ELEC		7:00
73618	TC	4839-20 CHECK RECEPTACLE, HAS NO POWER.	DFRC-B4839	ELEC		1:00
73626	TC	4810 REPLACE DESKTOP LIGHT; 4' 32W BULB	DFRC-B4810	ELEC		0:30
72550	TC	B/T-47 - Lighting	DFRC-T-47	ELEC		1:00
72316	TC	NASA Dryden - TEMPORARILY SEAL 8 ELECTRICAL CONDUITS; SEE MIKE MONAHAN	NASA-DRYDEN	ELEC		2:00
72317	TC	4823 REMOVE FOUR BREAKERS FROM BUS DUCT AND RETURN TO CUSTOMER AS WELL AS REMOVE A SMALL AMOUNT OF WIRE FROM THE CEILING: SEE ANDY BLUA	DFRC-B4823	ELEC		2:00
72334	TC	T-72 SOME LIGHTS OUT; POSSIBLE BAD BALLASTS	DFRC-T-72	ELEC		3:00
72447	TC	B/4800 RM 1412 - Overhead Light	DFRC-B4800-FLOOR1	ELEC		1:00
72471	TC	4800-2708 CHANGE LIGHTS OUT/BAD BALLAST POSSIBLY	DFRC-B4800-FLOOR2	ELEC		1:00
72457	TC	4810 POWER LOSS IN WALL BETWEEN ROOMS; SEE ALI FOR SPECIFICS.	DFRC-B4810	ELEC		0:30
72460	TC	4833-104 CONTROL ROOM - CLEAN UP RODENT WASTE IN COMPUTER RACKS AND SURROUNDING AREAS. SEAL CONDUITS WITH GROMMETS OR THE LIKE TO KEEP RODENTS FROM TRAVELING THROUGH THEM. SAFETY MUST SUPERVISE	DFRC-B4833	ELEC		17:00
72514	TC	B/703 2nd Flr - Lighting	DAOF-B703	ELEC		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72370	TC	4800-2328 FLICKERING LIGHT OVER DESK AREA	DFRC-B4800-FLOOR2	ELEC		1:00
72418	TC	4876 SECURITY CALLED TO SAY THERE WAS A PROBLEM WITH THE A/C POWER	DFRC-B4876	ELEC		0:30
72421	TC	4872 REPLACE LIGHT FIXTURE; WIND BLEW DOOR AWAY FROM TECH AND SMASHED INTO FIXTURE	DFRC-B4872	ELEC		4:00
72371	TC	4820 JANITORIAL CLOSET - CHECK LIGHTING, IT IS MUCH TOO DIM TO BE EFFECTIVE FOR THE JANITORS	DFRC-B4820	ELEC		2:30
72372	TC	NASA Dryden - GAS METERS NOT WORKING; TROUBLESHOOT AND REPAIR NEEDED	NASA-DRYDEN	ELEC		2:30
72500	TC	B/4850 Rm 111 - Overhead Light	DFRC-B4850	ELEC		0:30
72533	TC	B/4838 - Lighting Problem	DFRC-B4838	ELEC		1:30
72554	TC	703-111C CHECK TWO FIXTURES OF LIGHTS THAT ARE OUT; MAY ALSO HAVE BAD BALLASTS	DAOF-B703	ELEC		2:00
72498	TC	4847 CHECK FLOOD LIGHT ON WEST HANGAR DOOR. IT GOES ON AND OFF INTERMITTENTLY	DFRC-B4847	ELEC		3:00
72525	TC	703 HANGAR DOORS; RE-RADIATION SWITCH IS BROKEN	DAOF-B703	ELEC		0:00
72404	TC	4840-209-CUBICLE 1 - DIM LIGHTS OVER DESK COMPLETELY; THE GLARE IS CAUSING THE CUSTOMER HEADACHES	DFRC-B4840	ELEC		0:30
72503	TC	4800-2347 LOST POWER IN PART OF OFFICE AND OFFICE NEXT DOOR	DFRC-B4800-FLOOR2	ELEC		0:30
72504	TC	4800-1405 RI LAB - SOME LIGHTS OUT; SOME FLICKERING	DFRC-B4800-FLOOR1	ELEC		1:00
72575	TC	4800-2225 CHANGE FLICKERING LIGHT	DFRC-B4800-FLOOR2	ELEC		1:00
72578	TC	703-342 CHECK THE RECEPTACLES "IN" THE TABLE. THEY HAVE NO POWER.	DAOF-B703	ELEC		1:00
73622	TC	4837 CHECK LIGHT/BALLAST IN CALIBRATION ROOM	DFRC-B4837	ELEC		2:00
73628	TC	4800-1732 SOME LIGHTS OUT	DFRC-B4800-FLOOR1	ELEC		2:00
72408	TC	4809 AGE STORAGE LOT - A GFI OUTLET TO THE WASHRACK HAS NO POWER AND IS NEEDED PRESENTLY	DFRC-B4809	ELEC		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72409	TC	4809 AGE STORAGE LOT - A GFI OUTLET TO THE WASHRACK HAS NO POWER AND IS NEEDED PRESENTLY	DFRC-B4809	ELEC		2:00
72389	TC	4801 CHECK HANGAR LIGHTING AS IT APPEARS TO BE INOPERABLE	DFRC-B4801	ELEC		1:30
72383	TC	4800-2331 FLICKERING LIGHT IN THE OFFICE TO THE RIGHT AND OVER THE DESK	DFRC-B4800-FLOOR2	ELEC		0:30
72396	TC	703 SECOND FLOOR UTILITY CLOSET HAS A LIGHT OUT	DAOF-B703	ELEC		1:30
72400	TC	4801 HANGAR HAS APPROX. 6 LIGHTS OUT	DFRC-B4801	ELEC		3:30
72401	TC	4820-122 LOAD FRAME CONTROL ROOM HAS SOME LIGHTS OUT	DFRC-B4820	ELEC		1:00
72486	TC	B/4800 RM 1001 - Repair ADA Pushbutton	DFRC-B4800-FLOOR1	ELEC		0:45
72451	TC	Gate 48 - Breaker Tripping	DFRC	ELEC		6:00
72480	TC	4800 HALL WAY NEAR ROOMS 1800-1806 LIGHTS FLICKERING NEED TO BE FIXED	DFRC-B4800-FLOOR1	ELEC		1:00
72491	TC	4800-3103 REPLACE OLD OUTLET WITH NEW GFCI ON A WORKBENCH	DFRC-B4800-FLOOR3	ELEC		1:00
72518	TC	4720 DOOR BUZZER STUCK AND GOING OFF CONTINUOUSLY	DFRC-B4720	ELEC		1:00
72521	TC	4840-224 CHECK AN EMERGENCY LIGHT THAT IS INOPERABLE	DFRC-B4840	ELEC		0:30
72522	TC	B192 ELECTRICALLY DISCONNECT SOME EQUIPMENT SO A TRAILER COULD BE MOVED	DFRC-B192	ELEC	803002	0:30
74784	TC	B/4840 Rm 117 - Overhead lights	DFRC-B4840	ELEC		0:45
74772	TC	4800-1502 ENTRY THROUGH 1504 TO ROSALEA TOBERMANS ROOM; NEED LIGHT CHANGED	DFRC-B4800-FLOOR1	ELEC		0:30
74791	TC	4809 SOME LIGHTS OUT IN THE TOOL CAGE	DFRC-B4809	ELEC		1:00
74792	TC	4806 SOME LIGHTS OUT THROUGHOUT THE BLDG	DFRC-B4806	ELEC		3:00
74795	TC	4838 THREE EXIT SIGNS NEED BULBS IN ROOMS 201, 205, AND OUTSIDE ROOM 115; ROOM 206 NEEDS TWO FLUORESCENT LIGHTS REPLACED	DFRC-B4838	ELEC		3:00
74760	TC	B/4844 - Disconnect electrical power	DFRC-B4844	ELEC		2:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

74762	TC	B/4800 - Exit signs / Overhead lighting	DFRC-B4800-FLOOR3	ELEC		4:00
74764	TC	B/4823 - Lighting	DFRC-B4823	ELEC		0:30
74775	TC	4840-107 MENS ROOM - LIGHT OUT OVER THE SINK	DFRC-B4840	ELEC		0:30
74781	TC	4800-2511 FLICKERING LIGHT OVER JAMES PAVLICEK'S CUBICLE	DFRC-B4800-FLOOR2	ELEC		0:30
75392	TC	4823 WELD SHOP - LIGHT OUT IN SOLE FIXTURE OF CORNER AREA CREATING A SAFETY ISSUE NOW THAT THE CORNER IS VERY DARK	DFRC-B4823	ELEC		2:00
75393	TC	703-N212 POSSIBLE TRIPPED BREAKER - ELECTRIC DOWN IN OCCUPANT CUBICLE	DAOF-B703	ELEC		1:30
75515	TC	B/4800 Rm 1105 - Replace light	DFRC-B4800-FLOOR1	ELEC		0:30
75298	TC	4800-2701 FOUR SHORT BULBS BURNED OUT	DFRC-B4800-FLOOR2	ELEC		1:00
75386	TC	B/4800 Rm 3113 - UPS Alarm	DFRC-B4800-FLOOR3	ELEC		1:00
75473	TC	4800-1704 SEVERAL LIGHTS OUT	DFRC-B4800-FLOOR1	ELEC		1:30
75474	TC	4840-113C CUBICLE POWER STRIP HAS NO POWER TOO IT; FIRST CUBICLE TO THE RIGHT	DFRC-B4840	ELEC		1:00
75309	TC	4800-2128 FLICKERING LIGHT	DFRC-B4800-FLOOR2	ELEC		0:30
75310	TC	SUBSTATION 5 - CHECK BLDGS 4864 AND 4859; THEY HAVE BOTH LOST POWER	DFRC-NB085	ELEC		1:00
75501	TC	4810-1 EXIT SIGN HAS BLINKING LIGHT	DFRC-B4810	ELEC		0:30
75524	TC	4850 EXTERIOR REST ROOM NEED LIGHT CHANGED	DFRC-B4850	ELEC		1:00
75504	TC	4839 SMELLING ELECTRICAL BURNING SMELL IN THE BLDG	DFRC-B4839	ELEC		0:30
75506	TC	4840-222 SEVERAL LIGHTS OUT	DFRC-B4840	ELEC		1:00
75547	TC	4840-107 CHECK/TROUBLESHOOT EXHAUST FAN - STILL NOT WORKING	DFRC-B4840	ELEC		1:00
75369	TC	B/703 - S/W Elevator Phone	DAOF-B703	ELEC		1:00
75371	TC	4818 POST #6 LOOKS LIKE FLOOD LIGHT EXPLODED	DFRC-B4818	ELEC		0:30
75402	TC	4800 FIRST AND SECOND FLOOR - CHECK ELECTRICAL SMELL	DFRC-B4800-FLOOR1	ELEC		3:00
75403	TC	4800-2402 CODE M CONFERENCE ROOM - LIGHT OUT	DFRC-B4800-FLOOR2	ELEC		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

75447	TC	B/4800 Rm 1733 - Replace Light	DFRC-B4800-FLOOR1	ELEC		1:00
75491	TC	LRO 192 SOUTH BASE- CLEAN CORRODED GROUNDS RODS AND REBAR INSIDE TWO GROUND WELLS; SEE TIM FOR INTERIOR ACCESS TO BUILDING.	DFRC-B192	ELEC		3:40
75492	TC	LRO192 SOUTH BASE - CHECK ALL ELECTRICAL PANELS TO MAKE SURE GROUNDS INSIDE PANELS ARE NOT TIED TO NEUTRAL; SEE TIM FOR INTERIOR ACCESS TO BUILDING.	DFRC-B192	ELEC		1:30
75336	TC	4720 MEET BART RUSNAK AT THE "NIKE" SITE AND SHOW HIM WHERE THE FACILITIES UPS POWER RUNS	DFRC-B4720	ELEC		0:30
75354	TC	T-1 AND T-42 REPAIR POWER FEEDS TO TRAILERS, REPLACE FUSES, INSTALL PULL BOXES	NASA-DRYDEN	ELEC		4:30
75384	TC	4839 REAR EXIT - ABOVE EMERGENCY LIGHT AND/OR BALLAST IS GOING OUT	DFRC-B4839	ELEC		1:00
75388	TC	4846 SEVERAL LIGHTS OUT IN MARIA CORONADO'S OFFICE	DFRC-B4846	ELEC		0:30
75452	TC	B4870 - Exterior Light	DFRC-B4870	ELEC		1:00
75358	TC	B/4810 R/R - Replace light	DFRC-B4810	ELEC		0:30
75363	TC	B/4800 Rm 1728 - Remove bulbs	DFRC-B4800-FLOOR1	ELEC		0:30
75428	TC	703-111 BROKEN WALL OUTLET	DAOF-B703	ELEC		1:00
75368	TC	B/T-42 - Repair Disconnect	DFRC-T-42	ELEC		0:00
75417	TC	B/4800 Rm 3113 - Flickering Light	DFRC-B4800-FLOOR3	ELEC		0:30
75320	TC	Sub 12 - (Outage #1019) - Troubleshoot Meter	DFRC-NB095	ELEC		12:00
75468	TC	T-47 BLOWN FUSE IN KITCHEN AREA	DFRC-T-47	ELEC		1:00
75321	TC	703-VCC COVER PLATES NEEDED TO COVER HOLES IN WALL	DAOF-B703	ELEC		1:00
75532	TC	B/4800 Rm 2338 - Replace light	DFRC-B4800-FLOOR2	ELEC		1:00
75564	TC	B/4803 - Troubleshoot power	DFRC-B4803	ELEC		0:30
75486	TC	703-N211 & N212 MANY LIGHTS OUT	DAOF-B703	ELEC		2:00
75487	TC	B/703 4th Fl - Lighting	DAOF-B703	ELEC		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

75390	TC	4826 WALL POWER TO AIRCRAFT DOWN - WORK STOPPAGE	DFRC-B4826	ELEC		2:00
75389	TC	B4820 Rm 200 - No power	DFRC-B4820	ELEC		0:15
75441	TC	4800-2407 CHECK A FLICKERING LIGHT	DFRC-B4800-FLOOR2	ELEC		0:30
75340	TC	4800-1022 BADLY FLICKERING LIGHTS GIVING OCCUPANT HEADACHE; FIRST OFFICE WITH DOOR ON IT BEFORE STAIRS - SEE JIM ROSS	DFRC-B4800-FLOOR1	ELEC		0:30
75347	TC	4800-1122 LIGHT SWITCH HOT TO THE TOUCH	DFRC-B4800-FLOOR1	ELEC		1:00
75407	TC	4820-206 CONTRACTOR GIVEN "OK" TO DISASSEMBLE MODULAR CUBICLE ONLY TO DISCOVER IT IS WIRED AND HOT.	DFRC-B4820	ELEC		0:15
75410	TC	4800-1022 CHANGE SOME LAMPS THAT ARE OUT IN THE LIGHT BOXES	DFRC-B4800-FLOOR1	ELEC		2:00
75548	TC	4800-3202 NEED NEW SWITCH COVER ON PDU; ALSO NEED TO KNOW WHAT SWITCH GOES TO: MAY BE THE FLOOR?	DFRC-B4800-FLOOR3	ELEC		1:30
79381	TC	4830C Reset circuit breaker(s)	DFRC-B4830C	ELEC		1:00
79416	TC	B/4820 - Repair Exit/emergency Lights	DFRC-B4820	ELEC		6:30
79420	TC	4820 High bay - several lights out; approx. eight lights	DFRC-B4820	ELEC		2:30
79421	TC	4800-2145 Mens room light out	DFRC-B4800-FLOOR2	ELEC		1:00
79580	TC	4838 Southwest exterior door exit light is burned out	DFRC-B4838	ELEC		0:30
79587	TC	B/4832 - Lost Power	DFRC-B4832-COMPUTER-SUPPORT	ELEC		9:00
79702	TC	B/4809 - Remove/Replace Parts Washer	DFRC-B4809	ELEC		7:30
79608	TC	4800 Second floor picture lights need to be changed as they are burned out	DFRC-B4800-FLOOR2	ELEC		1:00
79609	TC	4823 Machine shop has several lights out	DFRC-B4823	ELEC		3:30
79629	TC	4840 Entry murals need the lighting changed out	DFRC-B4840	ELEC		0:00
79624	TC	4857 mens room lights out	DFRC-B4857	ELEC		0:30
79641	TC	B/4800 Rm 1616 - Replace Light Bulbs	DFRC-B4800-FLOOR1	ELEC		0:30
79505	TC	4825 Repair portable generator electrical plug	DFRC-B4825-POST1	ELEC		3:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

79546	TC	4800-1115 Flickering light	DFRC-B4800-FLOOR1	ELEC		1:00
79256	TC	4800-1115 REPLACE A BURNED OUT WORKBENCH LIGHT; PROBABLY 3FT. FLUORESCENT TUBE	DFRC-B4800-FLOOR1	ELEC		1:30
79373	TC	B/4822 PSSF - Replace Lights	DFRC-B4822-PSSF	ELEC		0:45
79374	TC	B/4823 Mens Room - Lights Out	DFRC-B4823	ELEC		0:30
79375	TC	B/4800 RM 1708 - Lights out	DFRC-B4800-FLOOR1	ELEC		1:00
79390	TC	B/4809 Rm 5 - Replace light	DFRC-B4809	ELEC		1:30
79627	TC	4800 Entry murals need the lighting changed out	DFRC-B4800-FLOOR1	ELEC		0:00
79645	TC	4840 Second floor has lights around copy area out	DFRC-B4840	ELEC		1:00
79654	TC	B/703 Rm 111A - Outlet	DAOF-B703	ELEC		0:30
79678	TC	4800-1016 Ladies room needs lights replaced	DFRC-B4800-FLOOR1	ELEC		1:00
79699	TC	B/4802 - Emergency Lighting	DFRC-B4802	ELEC		6:30
79700	TC	B/4841 - Lights	DFRC-B4841	ELEC		1:30
79635	TC	B/4840 Rm 226 - Light	DFRC-B4840	ELEC		1:30
79631	TC	4830C Repair/replace loose receptacle and broken cover plate	DFRC-B4830C	ELEC		0:45
79512	TC	B/4850 - Exterior Lighting	DFRC-B4850	ELEC		0:30
79524	TC	B/4720 - Troubleshoot UPS system	DFRC-B4720	ELEC	2301008	6:00
79377	TC	B/4824 - Emergency Light Alarm	DFRC-B4824	ELEC		1:30
79435	TC	B/4800 Rm 2407 - Bad Ballast	DFRC-B4800-FLOOR2	ELEC		1:30
79593	TC	4832 Replace circuit breaker	DFRC-B4832-COMPUTER-SUPPORT	ELEC		7:30
79693	TC	B/4800 Rm 1409-8 - Troubleshoot Electrical	DFRC-B4800-FLOOR1	ELEC		0:30
79656	TC	4800-2225 VITS RM - Check ballast/light over Donna White's desk	DFRC-B4800-FLOOR2	ELEC		0:30
79513	TC	B/703 Rm 111S - Lighting	DAOF-B703	ELEC		1:30
79510	TC	B/4840 - Repair Outlet	DFRC-B4840	ELEC		1:30
79412	TC	4820-122 GFI keeps tripping.	DFRC-B4820	ELEC		2:00
79599	TC	4800-1413 Ladies room has a badly flickering light	DFRC-B4800-FLOOR1	ELEC		0:30
79628	TC	4825 Change out lighting to murals	DFRC-B4825-POST1	ELEC		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

81784	TC	4847 change lights out and clean light lenses of insect matter	DFRC-B4847	ELEC		2:30
81785	TC	B/4820 - Troubleshoot Water Leak	DFRC-B4820	ELEC		1:30
81894	TC	B/4802 - No AC Power	DFRC-B4802	ELEC		0:30
81626	TC	4825 Security mural needs some lights changed	DFRC-B4825-POST1	ELEC		1:00
81652	TC	B. 4800 Replace burned out bulb, emergency exit sign located in hallway by Rm. 3113.	DFRC-B4800-FLOOR3	ELEC		1:30
81663	TC	B/4800 Rm 1708 - Lights	DFRC-B4800-FLOOR1	ELEC		2:00
81823	TC	B/4840 - Exterior Lighting	DFRC-B4840	ELEC		0:30
81799	TC	4809 "lead's office" has some lights out	DFRC-B4809	ELEC		0:30
81958	TC	703-334 various electrical plugs on ECR table are not working properly	DAOF-B703	ELEC		1:00
81989	TC	4800-2149 ladies room needs some lights changed near the entrance	DFRC-B4800-FLOOR2	ELEC		1:00
81949	TC	703-332F broken wall plug cover on west wall	DAOF-B703	ELEC		0:00
81950	TC	703-332F broken wall plug cover on west wall	DAOF-B703	ELEC		0:15
82155	TC	B/4847 - Reset Breaker (Outage # 1080)	DFRC-B4847	ELEC		3:30
82116	TC	4820-112 nearby is an electrical closet that needs to have the light changes as soon as possible	DFRC-B4820	ELEC		1:00
82206	TC	4803 light out	DFRC-B4803	ELEC		0:30
81935	TC	4802 mens room has a light out over the center urinal	DFRC-B4802	ELEC		0:45
82122	TC	B/4840 Bays 1-3 - Troubleshoot Aircraft Power	DFRC-B4840	ELEC		0:30
82147	TC	703-S142A first appears to be power glitch in room but turns out to be lighting/ballast issue	DAOF-B703	ELEC		1:00
81680	TC	B/703 Rm 111A - Loss of Power	DAOF-B703	ELEC		0:00
81755	TC	B/4833 Rm 101 - Emergency Lighting	DFRC-B4833	ELEC		1:30
81757	TC	B/703 Rm N213 - Light Switch	DAOF-B703	ELEC		1:00
81643	TC	4851 - Emergency Exit Lights	DFRC-B4851	ELEC		1:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

81971	TC	B/4720 - (Outage #1098) Troubleshoot Noise on UPS	DFRC-B4720	ELEC		5:30
81691	TC	B/4820 - Troubleshoot Dry Transformer	DFRC-B4820	ELEC		2:00
81893	TC	4826 Power to aircraft is out - 400Hz	DFRC-B4826	ELEC		0:30
81764	TC	4800-1720 lighting motion sensor in ceiling is bad	DFRC-B4800-FLOOR1	ELEC		1:00
81767	TC	703-232N a motion sensor timer recently reset for longer times is now not coming on at all	DAOF-B703	ELEC		1:00
81789	TC	B/4800 Rm 1716 - Lighting	DFRC-B4800-FLOOR1	ELEC		1:30
81738	TC	B/4806 Lab - Troubleshoot Receptacle	DFRC-B4806	ELEC		1:00
81939	TC	703 many exterior lights are out around the DAOF campus	DAOF	ELEC		0:00
81940	TC	703 three roof lights are out	DAOF-B703	ELEC		0:00
81967	TC	4800-1418 some lights out	DFRC-B4800-FLOOR1	ELEC		1:00
82028	TC	4823-300 Machine Rm has two lights out	DFRC-B4823	ELEC		1:00
82029	TC	4800-3103 inside office has three lights out	DFRC-B4800-FLOOR3	ELEC		0:20
82038	TC	4800-1409 near the mail drop a light is flickering badly	DFRC-B4800-FLOOR1	ELEC		0:40
81981	TC	4800-2225 check sensor switch; see Theresia for specifics	DFRC-B4800-FLOOR2	ELEC		1:30
82010	TC	4800-2340 lights coming on and off randomly making it very difficult to work; See #81954	DFRC-B4800-FLOOR2	ELEC		1:30
82121	TC	B/4800 Rm 1708 - Troubleshoot Outlet	DFRC-B4800-FLOOR1	ELEC		2:00
82071	TC	4833 shuttle hangar has a gas meter with three incoming wires that are uninsulated and need insulation ASAP	DFRC-B4833	ELEC		0:30
82153	TC	B/4839 - Mouse in Trap	DFRC-B4839	ELEC		1:00
81956	TC	B/4801 Rm 2217 - Troubleshoot Emergency Lights	DFRC-B4801	ELEC		0:30
81960	TC	4876 18 lights out up high; 1 light out in isles. See Dee for specifics	DFRC-B4876	ELEC		9:00
81714	TC	4800-1122 some lights are out in the environmental lab and need replacing	DFRC-B4800-FLOOR1	ELEC		2:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

81744	TC	4859 break room receptacle needs a cover - where the vending machines used to be	DFRC-B4859	ELEC		0:30
81747	TC	703-S322M Comm Room - closet next to employee's cafeteria - all lights are out and customer is sitting in the dark	DAOF-B703	ELEC		2:00
82040	TC	B/703 Rm N242 - Light Out	DAOF-B703	ELEC		1:00
81796	TC	4851 mens room has two lights out	DFRC-B4851	ELEC		1:30
81797	TC	703-N232 several lights are out	DAOF-B703	ELEC		1:30
82154	TC	B/4830 - Troubleshoot and Reset breaker	DFRC-B4830E	ELEC		0:30
82156	TC	B/4826 - No Aircraft Power	DFRC-B4826	ELEC		0:30
82212	TC	B/4840 A5 - Aircraft Power Supply	DFRC-B4840	ELEC		3:00
81644	TC	B/4800 - (Outage #1097) - Automatic door not working	DFRC-B4800-FLOOR1	ELEC		13:30
81647	TC	4870 Restroom lights out	DFRC-B4870	ELEC		0:30
81648	TC	Repair/replace the leaking dielectric union on the heating water piping in the SOFIA Lab- if either effort is clearly going to be >\$500, please stop work and inform Site Manager immediately	DAOF-B703	ELEC		1:00
81649	TC	Repair/replace Victaulic coupling on the 4th floor south-Other instructions -- if either effort is clearly going to be >\$500, please stop work and inform Site Manager immediately.	DAOF-B703	ELEC		2:20
81654	TC	B/703 4th Flr North - Drain Industrial Lines	DAOF-B703	ELEC		0:00
81954	TC	B/4800 Rm 2340 - Troubleshoot Lights	DFRC-B4800-FLOOR2	ELEC		0:30
84290	TC	B/4840 Bays 1-3 - Lights	DFRC-B4840	ELEC		1:00
84303	TC	B/4801 - Light Switch	DFRC-B4801	ELEC		22:00
84211	TC	4800 second floor - several "picture" lights out	DFRC-B4800-FLOOR2	ELEC		1:12
84215	TC	4820 several lights are out in the high bay and in the warehouse under the mezzanine	DFRC-B4820	ELEC		4:00
84265	TC	B/4823 Highbay - Troubleshoot Conduit	DFRC-B4823	ELEC		3:00
84184	TC	4800-2606 lights out in hallway near room	DFRC-B4800-FLOOR2	ELEC		0:30
84235	TC	B/4833 - Lighting	DFRC-B4833	ELEC		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

84291	TC	703-122A North - approx. sixteen lights are out	DAOF-B703	ELEC		2:00
84180	TC	4838 exit sign bulbs are out in two places; at the top of the central stairs in rm 205 and in rm 214	DFRC-B4838	ELEC		1:00
84233	TC	B/4800 Rm 1115 - Hallway Lighting	DFRC-B4800-FLOOR1	ELEC		0:30
84403	TC	DAOF - Main Vehicle Gate	DAOF	ELEC		1:00
84413	TC	B/4800 Rm 2317 - Lighting	DFRC-B4800-FLOOR2	ELEC		2:00
84310	TC	4822 PSSF light in hall outside ladies room is out	DFRC-B4822-PFSSF	ELEC		0:18
84313	TC	4820 in the hall outside room 103 there are several lights out	DFRC-B4820	ELEC		0:45
84271	TC	4800-1122 troubleshoot/replace a 3-prong 4-plug receptacle that has burn marks on it	DFRC-B4800-FLOOR1	ELEC		1:00
84327	TC	B4820 - Troubleshoot Shorted Lighting	DFRC-B4820	ELEC		2:00
84331	TC	4820 (service request) work with contractor to show the correct way for plugging into a shunt trip breaker; see Mark Nelson for details	DFRC-B4820	ELEC		8:00
84373	TC	B/703 Rm 141N - Repair Electrical Cord	DAOF-B703	ELEC		1:00
84391	TC	4800-2804 light going out over Patty's desk making it difficult to work	DFRC-B4800-FLOOR2	ELEC		0:30
84393	TC	4810 north inside of bldg and exit sign is burning out; see Laurie	DFRC-B4810	ELEC		0:30
84394	TC	4809 two ceiling bulbs are out in the shop making it harder to work - the ceiling is about 15ft up; see Jose	DFRC-B4809	ELEC		1:30
84402	TC	703 third floor south east mens room replace ballast and change lamps	DAOF-B703	ELEC		1:00
84377	TC	703 Found an unused opening in unmarked power panel in the DAOF Hangar Sensor Laboratory, which is a violation of NEC Article 110.12(A).	DAOF-B703	ELEC		0:30
84378	TC	703 Protective covers for outdoor electrical outlets were missing or broken on DAOF Building 703, which violates NEC Article 408.8(A).	DAOF-B703	ELEC		1:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

84249	TC	4838-135, 137 lights out in both offices	DFRC-B4838	ELEC		2:00
84307	TC	B/4838 Rm 210 - Lights	DFRC-B4838	ELEC		1:00
84157	TC	4833 emergency light repair- rm 100 over the door, rm 103 both have emergency lights out; the light in the hall seems to be missing; in the hangar over the south wall and middle door it seems to have	DFRC-B4833	ELEC		3:00
84174	TC	4800-1115 light fixture not just flickering but flashing as well	DFRC-B4800-FLOOR1	ELEC		0:30
84400	TC	4820 LO/TO at panel LP1-E4.1 due to contractor cutting wires	DFRC-B4820	ELEC		1:00
84406	TC	NASA Dryden - lights out in several locations as noticed by Security:	NASA-DRYDEN	ELEC		8:00
84170	TC	B/4800 Rm 1301/1302 - Light Out	DFRC-B4800-FLOOR1	ELEC		0:30
84363	TC	Gate 8 is inoperable; not responding to remote	DFRC-GATE-08	ELEC		0:00
84365	TC	4801 Panel LCC-1 - (Outage 1088) - Repair Panel	DFRC-B4801	ELEC	3123109	0:00
84374	TC	703 first floor southeast hall a wall outlet is inoperable	DAOF-B703	ELEC		1:00
84385	TC	B/4853 - Alarm Sounding	DFRC-B4853	ELEC		0:00
83113	TC	4830A row of lights out - to the rear left of bldg if looking from the entryway	DFRC-B4830A	ELEC		3:00
85081	TC	4820-111 office has some lights out	DFRC-B4820	ELEC		0:30
86671	TC	4802 electrical panel under light timer is humming	DFRC-B4802	ELEC		0:00
86681	TC	4809 desk area in the garage has lost power; see James Johnson	DFRC-B4809	ELEC		0:30
86898	TC	4823 SHEET METAL SHOP - REPAIR RECEPTACLE	DFRC-B4823	ELEC		2:00
86992	TC	4800-1105 SOME LIGHTS OUT NEAR OCCUPANT'S DESK	DFRC-B4800-FLOOR1	ELEC		0:45
86986	TC	4800-2221 exit light is out	DFRC-B4800-FLOOR2	ELEC		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

86707	TC	4825 Cafeteria - American Eatery - a walk-in freezer in the rear of the eatery has a light out inside; it appears to be a long tube, white, and possibly in two pieces. See Young for specifics	DFRC-B4825	ELEC		1:00
86717	TC	Post 2 (Guard Shack) - Lighting	DFRC-B4834	ELEC		1:00
86770	TC	4870 smell smoke; perhaps a ballast	DFRC-B4870	ELEC		3:00
86910	TC	703 fourth floor north two 8ft fluorescent bulbs are out	DAOF-B703	ELEC		1:00
86927	TC	4800-1418 mens room has lights out by the showers	DFRC-B4800-FLOOR1	ELEC		0:15
86970	TC	B/4820 Rm 130- Replace Light	DFRC-B4820	ELEC		1:00
86973	TC	B/4800 Rm 3111 - Exposed Junction Box	DFRC-B4800-FLOOR3	ELEC		1:00
86751	TC	4840-209 emergency lights out	DFRC-B4840	ELEC		2:00
86931	TC	4847 repair door bell	DFRC-B4847	ELEC		1:30
86944	TC	B/4800 Rm 1716 - Power Out	DFRC-B4800-FLOOR1	ELEC		1:00
86948	TC	703 HANGAR TWO LIGHTS OVER G-3 ARE OUT	DAOF-B703	ELEC		0:00
86713	TC	B/4830E - (Outage #1116) - Power out through bldg	DFRC-B4830E	ELEC		10:15
86760	TC	4840-234 a secure lab's emergency lights are out; see Paul for access to lab	DFRC-B4840	ELEC		1:30
86669	TC	703 third floor south side mens room has several lights out	DAOF-B703	ELEC		1:00
86670	TC	4823 Sheet Metal Shop has about 15 lights out and the hallway has 1 that need to be changed	DFRC-B4823	ELEC		21:30
86693	TC	4800-1412 conference room projector needs new light - meeting will be in session from 1-4pm 7/21 anytime after would be better	DFRC-B4800-FLOOR1	ELEC		0:45
86896	TC	4800-1613 INSPECT AND REPAIR THE HALL LIGHTS NEAR ROOM 1613	DFRC-B4800-FLOOR1	ELEC		0:30
86975	TC	B/4800 3rd Flr - Replace Light bulb	DFRC-B4800-FLOOR3	ELEC		2:00
86905	TC	NASA "A" Area (Kay & Assoc) - Disconnect /LO-TO Power	DFRC	ELEC		1:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

86953	TC	4801 BAY 2 SOUTHWEST AIRCRAFT POWER FROM WALL IS DOWN; WORK STOPPAGE	DFRC-B4801	ELEC		0:00
86968	TC	B/4800 Rm 1728 - Replace Lights	DFRC-B4800-FLOOR1	ELEC		0:30
87018	TC	4850-111 LIGHT OUT OVER DESK	DFRC-B4850	ELEC		0:30
86849	TC	703 Fabrication shop - two machines plugged into the same outlet are not working	DAOF-B703	ELEC		0:30
86860	TC	Flightline - hydraulics control panel has no power	DFRC-FLIGHTLINE	ELEC		0:30
86939	TC	4863 BURNING SMELL IN DANNY AVILA'S OFFICE AND NO WHERE ELSE	DFRC-B4863	ELEC		13:30
86967	TC	B/4832 - Replace Lights	DFRC-B4832-MAIL-ROOM	ELEC		1:30
86716	TC	B4800 Rm 1811 - Lighting	DFRC-B4800-FLOOR1	ELEC		0:30
86742	TC	GUARD POST 2 - RECEPTACLE SPARKED AND BURNED UP THE OUTLET	DFRC-B4834	ELEC		3:00
86747	TC	4830A - PUT COVER BACK ON WIRES BECAUSE CUSTOMER CANNOT CLIMB UNDER DESK AND DO IT	DFRC-B4830A	ELEC		0:15
86748	TC	4820 - CLEAN UP AND REPLACE HIGH BAY LIGHT THAT EXPLODED	DFRC-B4820	ELEC		1:00
86762	TC	4800-1733 conference room has a light out	DFRC-B4800-FLOOR1	ELEC		0:30
86688	TC	4802 repair/replace indicator lights on 400Hz panel; one green, one red. See Paul for specifics	DFRC-B4802	ELEC		0:00
86775	TC	4823 several lights out	DFRC-B4823	ELEC		4:30
86815	TC	4800-1728 remove a few lights; see Kelly for specifics	DFRC-B4800-FLOOR1	ELEC		0:30
86818	TC	4840-118 light out on desk hutch	DFRC-B4840	ELEC		0:15
87029	TC	4800-1422 LIGHTS GOING OUT OVER DESK	DFRC-B4800-FLOOR1	ELEC		0:30
86824	TC	4826 power to aircraft is down	DFRC-B4826	ELEC		0:30
86935	TC	B/4803 - Disconnect Welder	DFRC-B4803	ELEC		0:15
86900	TC	B/4830B - No Power	DFRC-B4830B	ELEC		0:30
86960	TC	4830B NO POWER TO COMM ROOM	DFRC-B4830B	ELEC		0:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

87022	TC	4809-23 some lights are out in the History Office; for access see Pete on 8/19/11 or 8/22/11	DFRC-B4809	ELEC		4:00
86962	TC	4810 JEAN MANNING'S OFFICE - NEED 1 OR 2 LIGHTS DIMMED/REMOVED DUE TO GLARE ON COMPUTER AND PHONE SCREENS	DFRC-B4810	ELEC		0:30
87036	TC	4800-1115B LAB - FLICKERING LIGHTS - 14FT HIGH CEILINGS WILL NEED 12FT LADDER OR DOUBLE DOORS ALLOW FOR SCISSOR LIFT ENTRY	DFRC-B4800-FLOOR1	ELEC		1:00
89676	TC	703 SOUTH EAST ELEVATOR NEEDS LIGHTING CHECKED AND LENS CEILING TILES CLEANED	DAOF-B703	ELEC		0:55
89175	TC	4857 ROLL UP DOOR WAS WORKED ON EARLIER AND NOW THE BLDG ALARM CANNOT BE SET BECAUSE THERE IS AN UNKNOWN ROLL UP DOOR ISSUE	DFRC-B4857	ELEC		1:30
89364	TC	B/4840 Bay 5 - Power to Aircraft Out	DFRC-B4840	ELEC		0:30
89466	TC	4800 FIRST FLOOR EAST SIDE CORRIDOR LIGHTING IS TOO DARK FOR JUST CONSERVATION LIGHTING. THERE MUST BE SOME LIGHTS OUT THAT NEED CHANGING.	DFRC-B4800-FLOOR1	ELEC		0:30
89467	TC	4800 FIRST FLOOR NORTH CORRIDOR (FROM THE EAST END OVER TO THE MAIN ENTRANCE) LIGHTING IS TOO DARK FOR JUST CONSERVATION LIGHTING. THERE MUST BE SOME LIGHTS OUT THAT NEED CHANGING.	DFRC-B4800-FLOOR1	ELEC		2:00
89477	TC	4800-2508 NEED TO MOVE LIGHTSWITCH ACROSS THE ROOM; THE ROOM WAS RECONFIGURED AND NOW THE OCCUPANTS HAVE TO WALK ACROSS A DARK ROOM TO GET TO THE LIGHT SWITCH CREATING A REAL SAFETY HAZARD	DFRC-B4800-FLOOR2	ELEC		2:00
89481	TC	4800 PANEL LP2-K19 - FIX PANEL LABELING IN ELECTRICAL PANEL	DFRC-B4800	ELEC		0:00
89489	TC	4800-2016 AND STAIRWELL #2 EACH HAVE A LIGHT OUT; SEE TAMMY FOR SPECIFICS	DFRC-B4800-FLOOR2	ELEC		1:00
89504	TC	B 4847 Office area- emergency light flashing	DFRC-B4847	ELEC		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89505	TC	B 4720 UPS Room- Audible Alarm	DFRC-B4720	ELEC		0:00
89510	TC	4800-2501 MENS ROOM SMELLS LIKE ELECTRONICS ARE BURNING	DFRC-B4800-FLOOR2	ELEC		5:00
89298	TC	4800-2317 TOO MUCH GLARE FOR OCCUPANT; NEED TO REMOVE A FEW BULBS	DFRC-B4800-FLOOR2	ELEC		0:30
89306	TC	4800-2323 CHECK TWO LIGHTS THAT ARE FLICKERING AND BUZZING	DFRC-B4800-FLOOR2	ELEC		0:30
89329	TC	4820-204 OFFICE HAS A LIGHT OUT	DFRC-B4820	ELEC		1:00
89530	TC	B4802- Lights fail to turn on	DFRC-B4802	ELEC		0:15
89542	TC	4800-3113 IN THE HALLWAY FROM 3103 LEADING UP THE STAIRS TO 3113 THERE IS A LIGHT OUT ABOVE THE STEPS	DFRC-B4800-FLOOR3	ELEC		0:30
89547	TC	4800-1518 CHECK MOTION SENSOR LIGHT SWITCH AS IT SEEMS TO BE GOING OFF ABOUT EVERY FIVE MINUTES	DFRC-B4800-FLOOR1	ELEC		1:00
89339	TC	B/4840 Bay 5 - No AC power	DFRC-B4840	ELEC		0:30
89357	TC	4800-2613 EXIT SIGN BULB OUT	DFRC-B4800-FLOOR2	ELEC		0:45
89550	TC	4840-156 TOO DARK; TOO MANY LIGHTS OUT	DFRC-B4840	ELEC		1:45
89551	TC	4825 CAFETERIA - CHECK POWER TO SODA MACHINE AS IT APPEARS TO HAVE NONE. SEE GEMMA BURRESS x3689	DFRC-B4825	ELEC		1:00
89552	TC	4802 RESTORE AIRCRAFT POWER	DFRC-B4802	ELEC		1:00
89567	TC	4810 SIX VACUUMS NEED DAMAGED CORDS REPLACED	DFRC-B4810	ELEC		2:00
89361	TC	4844 MODULAR WALL HAS NO POWER	DFRC-B4844	ELEC		0:15
89569	TC	4823 SHEET METAL SHOP - EXIT SIGN WITH LIGHT OUT	DFRC-B4823	ELEC		1:00
89572	TC	4823 REPAIR THREE ELECTRICAL ITEMS; SEE BELOW	DFRC-B4823	ELEC		1:00
89579	TC	4981 REPAIR WIRING TO BLOCK HEATER AND BATTERY CHARGER	DFRC-B4981	ELEC		3:30
89581	TC	NASA DRYDEN BLDGS 4720, 4981, 4982 LOSS OF POWER FROM AIR FORCE; SMOOTH TRANSITION TO GENERATORS	NASA-DRYDEN	ELEC		1:15
89583	TC	B/4841 - Lighting	DFRC-B4841	ELEC		1:00
89586	TC	4820-124 SEVERAL LIGHTS OUT	DFRC-B4820	ELEC		2:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89588	TC	4820 WATER TUNNEL - TEST ALL RECEPTACLES TO SEE IF THEY ARE ON THE BATHROOM GFCI CIRCUIT.	DFRC-B4820	ELEC		3:30
89416	TC	4800-2146 LIGHT OUT OVER MATT GRAHAM'S DESK	DFRC-B4800-FLOOR2	ELEC		0:30
89589	TC	4800-2129 KITCHEN HAS SOME LIGHTS OUT	DFRC-B4800-FLOOR2	ELEC		0:30
89596	TC	B/4839 - Lighting	DFRC-B4839	ELEC		1:00
89603	TC	B/4871 - Replace Receptacle Cover	DFRC-B4871	ELEC		1:15
89604	TC	4800 SECOND FLOOR - PDU PHASE ROTATION	DFRC-B4800-FLOOR3	ELEC		0:00
89619	TC	B/4809 - Lighting	DFRC-B4809	ELEC		0:15
89630	TC	4840 OFFICE AREAS FOR BAYS 1, 2, 3 - CIRCUIT BREAKER SEEMS TO HAVE TRIPPED BECAUSE POWER IS OUT IN SEVERAL OUTLETS	DFRC-B4840	ELEC		1:00
89643	TC	B/4800 Rm 1505 - Lighting	DFRC-B4800-FLOOR1	ELEC		0:30
89525	TC	4840 BAY 3 POWER OUT AGAIN	DFRC-B4840	ELEC		0:30
89636	TC	4800-2804 LIGHT GOING OUT IN OFFICE	DFRC-B4800-FLOOR2	ELEC		0:30
89341	TC	4800-2205 LADIES ROOM HAS SOME LIGHTS OUT	DFRC-B4800-FLOOR2	ELEC		0:30
89392	TC	4720 NORTH SIDE CONNEX - A BREAKER KEEPS TRIPPING; ASSISTANCE NEEDED FOR MISSION SUPPORT	DFRC-B4720	ELEC		2:00
89470	TC	703 FABRICATION SHOP HAS SOME LIGHTS OUT	DAOF-B703	ELEC		0:00
89263	TC	4809 PROVIDE AND HANG A REFLECTIVE EXIT SIGN. THE ARROW ON THE SIGN NEEDS TO POINT LEFT; SEE RONNIE FOR SPECIFICS	DFRC-B4809	ELEC		1:15
89283	TC	4825 SECURITY NEEDS SOME SPECIALTY BULBS FOR THE WALLS	DFRC-B4825-POST1	ELEC		0:30
89284	TC	4830B REAR DOOR EXIT SIGN HAS A BULB OUT	DFRC-B4830D	ELEC		0:45
89363	TC	B/4802 - Power to Aircraft Out	DFRC-B4802	ELEC		0:15
89394	TC	4800-1728 CHANGE FLICKERING LIGHT	DFRC-B4800-FLOOR1	ELEC		0:30
89313	TC	4720 SIDE DOOR BUZZER SUDDENLY INOPERABLE	DFRC-B4720	ELEC		1:00
89314	TC	4800-2511 HALLWAY OUTSIDE ROOM HAS LIGHTS OUT	DFRC-B4800-FLOOR2	ELEC		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89316	TC	4876 ADMIN AREA - LIGHT OUT AND ANOTHR FLICKERING AND HISSING	DFRC-B4876	ELEC		1:00
89425	TC	B/4809 - (Emergency Outage # 1118) - Disconnect Conductors	DFRC-B4809	ELEC		2:00
89290	TC	4857 BLDG ALARM NOT WORKING - CLEAN SENSOR WITH SCRUB PAD AND CLEANER AS SENSOR IS QUITE DIRTY PER KRIS KIM	DFRC-B4857	ELEC		1:00
89383	TC	4840 PHANTOM EYE TM TRAILER - CHECK THE POWER TO THE AIR CONDITIONING.	DFRC-B4840	ELEC		1:00
89404	TC	703 SOUTHEAST AND SOUTHWEST STAIRWELLS 2ND FLOOR THERE IS A LIGHT OUT	DAOF-B703	ELEC		1:00
89265	TC	4806 SOME LIGHTS OUT	DFRC-B4806	ELEC		3:00
89340	TC	B/4801 - Lights Out	DFRC-B4801	ELEC		0:45
89370	TC	B/703 N/E - Hangar Door Warning Buzzer	DAOF-B703	ELEC		0:00
89398	TC	4820-102 TWO 48" WORKBENCH BULBS ARE OUT	DFRC-B4820	ELEC		0:30
89424	TC	B/ 4840 Bay 3- wall outlets not working	DFRC-B4840	ELEC		0:30
89617	TC	4850 EXTERIOR LIGHTS HAVE COME ON DURING THE DAYLIGHT HOURS. MAY BE DUE TO LOSS OF POWER OVER WEEKEND DISRUPTING TIMER.	DFRC-B4850	ELEC		0:15
89411	TC	B/4840 - Exterior Elevator (Alimak)	DFRC-B4840	ELEC		5:00
89495	TC	4840 BAY 3 CHECK CIRCUIT BREAKER AS COMPUTERS HAVE LOST POWER	DFRC-B4840	ELEC		1:30
89633	TC	4856 LIGHT OUT IN SHOP AREA	DFRC-B4856	ELEC		1:00
89435	TC	B/703 Rm 311-F - Troubleshoot Wire Issue	DAOF-B703	ELEC		0:30
89379	TC	B/703 - Troubleshoot / Repair GPS Transmitter	DAOF-B703	ELEC		1:30
89582	TC	4800-1405 LIGHT GOING OUT OVER OCCUPANT'S DESK	DFRC-B4800-FLOOR1	ELEC		0:30
89644	TC	B/4825 Cafe - Reset Breaker	DFRC-B4825-GIFT-SHOP	ELEC		2:00
89407	TC	B/4800 Rm 3209 - Lighting	DFRC-B4800-FLOOR3	ELEC		0:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89417	TC	4840 BAY 6 TROUBLESHOOT ELECTRIC IN FRONT OF A PAIR OF MODULAR FURNITURE CUBICLES WHERE A STRUCTURE MAY NEED POWER REMOVED. SEE GARY JOHNSON OR GARY EDWARDS FOR SPECIFICS	DFRC-B4840	ELEC		4:00
89496	TC	4838 BULBS OUT ON TWO EXIT SIGNS; FIRST FLOOR INTERIOR RIGHT SIDE OF MAIN ENTRANCE AND SECOND FLOOR INTERIOR EAST SIDE OF BLDG	DFRC-B4838	ELEC		0:30
89538	TC	4826 WALL POWER TO AIRCRAFT IS DOWN	DFRC-B4826	ELEC		0:30
89594	TC	4840 SPIRAL STAIRCASE HAS LIGHTING ON IT AND IT IS OUT	DFRC-B4840	ELEC		1:00
89620	TC	B/4870 - Loss of Power	DFRC-B4870	ELEC		2:00
91678	TC	B/4824 - Fire Investigation & System Start Up	DFRC-B4824	ELEC		0:00
91492	TC	703-113C NORTH - CUBICLE OUTLETS HAVE NO POWER	DAOF-B703	ELEC		2:00
91493	TC	4800-2221 CHECK ON A BALLAST NEXT TO A MICROPHONE THAT MAY BE CAUSING AN AUDIO DISTURBANCE IN THE VIDEO BROADCAST SYSTEM; FIRST SEE DONNA IN RM 2225	DFRC-B4800-FLOOR2	ELEC		1:30
91497	TC	NB119 SOUTH OF MDD AREA A PAD - A 208V 3-PHASE OUTLET IS ONLY PRODUCING 200V; NEEDED FOR MISSION SUPPORT FOR PHANTOM EYE	DFRC-NB119	ELEC		1:00
91499	TC	4800-1714 FLICKERING LIGHT	DFRC-B4800-FLOOR1	ELEC		1:00
91500	TC	4830A - BREAKER TRIPPED	DFRC-B4830A	ELEC		0:30
91556	TC	B/703 Rm 111S - Reset Breaker	DAOF-B703	ELEC		0:30
91685	TC	B/703 Roof - Exterior Lighting	DAOF-B703	ELEC		0:00
91692	TC	4826-105 MENS ROOM LIGHT IS BURNED UP	DFRC-B4826	ELEC		2:00
91508	TC	4800 SOUTH SIDE GEM CART RECEPTACLE IS OUT OF POWER. IT IS LABELED T-20-A CIRCUIT 14	DFRC-B4800	ELEC		0:30
91569	TC	B/4810 Rm 2B - Replace Light Bulb	DFRC-B4810	ELEC		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

91573	TC	4826 - 3PHASE 480V PANEL PP1-B8 #4 - PUG ON INSIDE OF PANEL FELL OUT; SEE WALT FOR SPECIFICS	DFRC-B4826	ELEC		0:30
91518	TC	B/4809 - Lighting	DFRC-B4809	ELEC		4:30
91525	TC	4801-113A MODEL LAB HAS A TRIPPED BREAKER	DFRC-B4801	ELEC		0:30
91577	TC	4800-1122 ENVIRONMENTAL LAB TESTING IS INTERRUPTED BY LOSS OF 400Hz POWER	DFRC-B4800-FLOOR1	ELEC		0:30
91579	TC	4840 SECOND FLOOR LADIES ROOM HAS A LIGHT OUT NEAR THE SINK	DFRC-B4840	ELEC		0:30
91532	TC	703 SECOND FLOOR MEDICAL OFFICE HAS A LIGHT OUT AND THE MOTIION SENSOR SWITCH IS NOT WORKING PROPERLY	DAOF-B703	ELEC		0:00
91541	TC	4800-1115 WORK BENCH LIGHT IS OUT	DFRC-B4800-FLOOR1	ELEC		1:30
91542	TC	4838 TWO LIGHTS OUT - ROOM 212 AN EMERGENCY LIGHT HAS A BULB OUT; ROOM 106 AN EXIT LIGHT HAS A BULB OUT.	DFRC-B4838	ELEC		0:45
91596	TC	4800-2323 THE LIGHTING IS TOO BRIGHT	DFRC-B4800-FLOOR2	ELEC		0:30
91602	TC	4840-234 SOME LIGHTS ARE BURNED OUT; THE DIM LIGHT IS DISRUPTIVE TO A PROJECT IN PROGRESS	DFRC-B4840	ELEC		0:30
91617	TC	4801 NO POWER TO RECEPTACLES	DFRC-B4801	ELEC		0:30
91622	TC	4820 TRIPPED CIRCUIT BREAKER	DFRC-B4820	ELEC		0:30
91626	TC	4838-212 AN OUTLET JUST INSIDE THE DOOR SHOCKED THE CUSTOMER; USUALLY SHE HAS TO JIGGLE THE OUTLET TO GET POWER	DFRC-B4838	ELEC		0:30
91629	TC	4800-2404 - (OUTAGE # 1147) PDU HAVING POWER PROBLEMS	DFRC-B4800-FLOOR2	ELEC		0:00
91633	TC	B/4800 Rm 2523 - Lighting	DFRC-B4800-FLOOR2	ELEC		0:30
91634	TC	B/4800 Rm 2225 - Lighting	DFRC-B4800-FLOOR2	ELEC		1:30
91639	TC	B/4800 Rm 2404 - Breaker Reset	DFRC-B4800-FLOOR2	ELEC		0:00
91640	TC	B/4800 Rm 1505 - Lighting	DFRC-B4800-FLOOR1	ELEC		0:30
91645	TC	B/4838 - (Outage #1125) - Clear UPS Alarms	DFRC-B4838	ELEC		16:00
91648	TC	B/703 Sophia Lab - Lighting	DAOF-B703	ELEC		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

91651	TC	4802 EAST SIDE RECEPTACLES FOR GEM CARTS ARE NOT SUPPLYING POWER.	DFRC-B4802	ELEC		0:30
91669	TC	703 THE HALLWAY LIGHTS OUTSIDE ROOMS N232 AND N234 ARE OUT, SEE RALPH.	DAOF-B703	ELEC		0:00
91960	TC	B/4800 Rm 1732 - Lighting	DFRC-B4800-FLOOR1	ELEC		0:30
93808	TC	B/4800 Rm 1732 - Light Sensor	DFRC-B4800-FLOOR1	ELEC		0:30
93898	TC	4832 ODIN SIDE HAS ABOUT 14 LIGHTS OUT THAT NEED CHANGING	DFRC-B4832-COMPUTER-SUPPORT	ELEC		0:00
93829	TC	B/4800 Rm 1115 - Light Sensor	DFRC-B4800-FLOOR1	ELEC		1:00
93895	TC	B/4820 - Troubleshoot/Repair VFD	DFRC-B4820	ELEC	605001	0:00
93888	TC	B/4831 - Lighting	DFRC-B4831	ELEC		0:00
93890	TC	4806 TWO BANKS OF LIGHTS HAVE RECENTLY GONE OUT AND NEED REPLACING	DFRC-B4806	ELEC		0:00
93893	TC	4840 SECOND FLOOR MENS ROOM HAS A LIGHT OUT OVER THE SINK	DFRC-B4840	ELEC		0:00
93811	TC	B/4801 Rm 107 - Light Lense	DFRC-B4801	ELEC		0:30
93817	TC	4840-156 CONFERENCE ROOM OUTLET REPEATEDLY TRIPPING PLUG STRIP; JOHN WILL HAVE PUT A "POST-IT" OVER THE OUTLET INDICATING WHICH ONE IT IS, OR SEE JOHN FOR SPECIFICS	DFRC-B4840	ELEC		0:00
93800	TC	B/4876 - Reset Breaker	DFRC-B4876	ELEC		0:30
93801	TC	B/4832 - Reset Breaker	DFRC-B4832	ELEC		0:30
93826	TC	703-S122 NEAR DOOR "A" THERE IS A SWITCH PLATE COVER BROKEN	DAOF-B703	ELEC		0:00
93844	TC	B/4824 - Remove Electrical Components	DFRC-B4824	ELEC		0:00
93860	TC	4806 WEAK BREAKER KEEPS TRIPPING; CALL DANNY AT 661-816-9939	DFRC-B4806	ELEC		0:00
93861	TC	B/4824 - Troubleshoot Gate Operator Controls	DFRC-B4824	ELEC		0:00
93825	TC	B/4847 - Lighting	DFRC-B4847	ELEC		1:00
93830	TC	B/4876 - Reset Breaker	DFRC-B4876	ELEC		0:30
93831	TC	B/4801 Rm 107 - Lighting	DFRC-B4801	ELEC		2:00
93833	TC	B/703 4th Floor - Lighting	DAOF-B703	ELEC		0:00
93814	TC	703 AGE SHOP HAS SOME LIGHTS OUT	DAOF-B703	ELEC		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

93816	TC	4822 LAB IS TOO DIM	DFRC-B4822-MEDICAL	ELEC		2:00
93823	TC	4800 PASSENGER ELEVATOR HAS A LIGHT OUT	DFRC-B4800	ELEC		0:30
93849	TC	192 LRO HAS SOME INTERIOR LIGHTS OUT AND AT LEAST 4 EXTERIOR LIGHTS 2 OF WHICH ARE THE RED EMERGENCY ROOF LIGHTS; SEE HECTOR FOR SPECIFICS AND HECTOR WOULD LIKE TO BE PRESENT WHILE THE WORK IS DONE.	DFRC-B192	ELEC	803002	0:00
93877	TC	4823 CHEM CRIB EMERGENCY LIGHTS ARE ON THOUGH THERE WAS NO LOSS OF POWER	DFRC-B4823	ELEC		0:00
93821	TC	4800-1115 INSTALL COVER PLATE	DFRC-B4800-FLOOR1	ELEC		0:15
93855	TC	B/4800 Rm 3113 - Lighting	DFRC-B4800-FLOOR3	ELEC		0:00
93873	TC	Gate 6 ("A" Area) - Rotogate behind the trailers. The gate is not working properly.	NASA-DRYDEN	ELEC		0:00
65575	TC	B/4826 - Fire Alarm Panel in Alarm	DFRC-B4826	FIRE		0:30
65658	TC	B/4833 - Fire Tech Support - Deluge Valve	DFRC-B4833	FIRE		7:30
65595	TC	B/4825 Post 1 - Panel in Alarm	DFRC-B4825-POST1	FIRE		11:00
65576	TC	B/4872 - Fire Alarm Panel in Alarm	DFRC-B4872	FIRE		2:15
65709	TC	B/4826 - Replacement of Solenoid Valves	DFRC-B4826	FIRE		27:00:00
65639	TC	NB118 - Outage # 961 - Fire Tech Support	DFRC-NB118	FIRE		7:00
67931	TC	B/4826 - Replacement of GFE Viking Valve	DFRC-B4826	FIRE		12:00
68100	TC	4820 WAREHOUSE-WET PIPE_MAIN DRAIN VALVE. REPLACE VALVE, HAS A BAD SEAT AND IS DIFFICULT TO OPERATE. FOUND DURING OUTAGE#971	DFRC-B4820	FIRE		6:00
67964	TC	4800-3206 MCC2-Replace annunciator panel green indicator light for Inergen; the light has been burned out. See Antonio for specifics.	DFRC-B4800-FLOOR3	FIRE		1:05
68025	TC	4840-107 MENSROOM-REPAIR SPRINKLER HEAD COVER; HAS FALLEN ONCE AND BEEN REPAIRED. HAS FALLEN AGAIN	DFRC-B4840	FIRE		0:10
68068	TC	4820 FIRE ALARM CONTROL PANEL (FACP) IS IN ALARM; FRONT ENTRY WAY	DFRC-B4820	FIRE		0:10

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

68186	TC	4823 CHEM CRIB-FIRE ALARM CONTROL PANEL SOUNDING	DFRC-B4823	FIRE		1:10
70037	TC	703 -1ST FLOOR SOUTH SIDE- REPLACE BATTERIES FOR DAMPER POWER SUPPLY	DAOF-B703	FIRE		0:00
70092	TC	703 HANGAR NORTHEAST CORNER - HYDRAZINE NOT CONNECTED; NEED TO FIND OUR WHY AND CONNECT IT.	DAOF-B703	FIRE		0:00
70312	TC	B/4824 - Fire Panel in Alarm	DFRC-B4824	FIRE		0:45
72313	TC	4825 BREAK ROOM - CHECK ON PLACING OR REPLACING A FIRE EXTINGUISHER; SEE MATTHEW RIECK FOR SPECIFICS	DFRC-B4825-POST1	FIRE		0:30
72347	TC	Initiate a priority trouble call to identify the source(s) of water intrusion that are causing recurring failures of the smoke detector at B4801 and make corrective repairs to mitigate the problem	DFRC-B4801	FIRE	1002024	14:00
73617	TC	4840-221 CHECK A FIRE PIPE THAT IS LEAKING VERY BADLY. THERE IS NO FIRE EMERGENCY. THE CEILING IS WET.	DFRC-B4840	FIRE		1:00
72417	TC	4820 CHECK FACP IN ALARM	DFRC-B4820	FIRE		0:10
72553	TC	B/703 HANGAR - MOVE TWO HYDRAZINE SENSORS	DAOF-B703	FIRE		2:00
72510	TC	B/4802 - Zone 10 Riser	DFRC-B4802	FIRE		1:20
72547	TC	4802 INSPECT PRIME LINES THROUGHOUT BLDG 4802; ON JOHN TRIGG'S REQUEST	DFRC-B4802	FIRE		0:15
72523	TC	SUBSTATION 6 - FIRE SUPPORT FOR DE-ENERGIZING A SINGLE BREAKER	DFRC-NB094	FIRE		0:15
72527	TC	4802 DELUGE PRIME LINE LEAK - RISER #4 EQUIP# 2228008	DFRC-B4802	FIRE	2228008	5:00
74767	TC	4800-2527 REPLACE THREE BURNED OUT RED LED LIGHTS ON THE FIRE ALARM CONTROL PANEL; SEE ANTONIO FOR THREE RED LED REPLACEMENT LAMPS.	DFRC-B4800-FLOOR2	FIRE		1:30
75512	TC	NB103 REMOVE AND DISASSEMBLE FAILED CLA VALVE; TROUBLESHOOT CAUSE OF FAILURE AND ADVISE CUSTOMER	DFRC-NB103	FIRE		6:00
75356	TC	B/4823 - Gas Detection Alarm	DFRC-B4823	FIRE	4801036	0:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

75484	TC	4823 CHEM CRIB - FIRE ALARM CONTROL PANEL BUZZING	DFRC-B4823	FIRE		0:10
75544	TC	4825 "FIRE" PRINTER OFF LINE AGAIN/STILL FOR THE LAST TWO DAYS; HAVE TRIED ALL THE "TRICKS" TO KEEP IT RUNNING BUT TO NO EFFECT.	DFRC-B4825-POST1	FIRE		1:00
75573	TC	4840 SECOND FLOOR ANUNCIATOR PANEL ALARM GOING OFF FOR ZONE 5 - POSSIBLY FOR INERGEN	DFRC-B4840	FIRE		1:10
75561	TC	4802 FIRE CONTROL BOX/PANEL ALARM GOING OFF "NOZZLE TAMPER" IN ZONE 4	DFRC-B4802	FIRE		0:30
75570	TC	B/4856 - Battery Alarm	DFRC-B4856	FIRE		0:30
75444	TC	4823 CHEMICAL CRIB - FIRE ALARM CONTROL PANEL BUZZING	DFRC-B4823	FIRE		0:25
75485	TC	703 OUTSIDE 131B - HOSE REEL ASSEMBLY OR BARRIERS ARE LOOSE	DAOF-B703	FIRE		0:30
79428	TC	4802 Alarm panel sounding	DFRC-B4802	FIRE		0:10
79590	TC	4826 Sounds like water is running through fire suppression pipes	DFRC-B4826	FIRE		0:15
79456	TC	NB119 A "fire" valve is leaking at the 20ft level	DFRC-NB119	FIRE		1:00
79372	TC	4825 SECURITY - BORROW A COUPLE OF FIRE EXTINGUISHERS FOR A PROJECT; ONE FOR A VEHICLE AND ONE FOR A SMALL BLDG	DFRC-B4825-POST1	FIRE		0:40
79538	TC	4825 Air Force printer inoperable	DFRC-B4825-POST1	FIRE		1:00
79539	TC	4847 Fire extinguisher needs a sign posted over it indicating it's location	DFRC-B4847	FIRE		0:10
79480	TC	703 Disconnect flow switches from old auto-call fire system	DAOF-B703	FIRE		2:00
79677	TC	703 South east side of bldg - CSX panel in alarm	DAOF-B703	FIRE		0:10
79686	TC	T-69 Smoke detector has bad battery	DFRC-T-69	FIRE		0:10
81898	TC	B/4800 - (Outage # 1081) Replace Sensors	DFRC-B4800-FLOOR2	FIRE		0:00
81900	TC	B/4800 - (Outage # 1081) - Replace Sensors	DFRC-B4800-FLOOR3	FIRE		0:00
81896	TC	B/4809 - Alarm Sounding	DFRC-B4809	FIRE		0:30
82005	TC	B/4840 2nd Flr - Smell of Smoke	DFRC-B4840	FIRE		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

81795	TC	4801 fire alarm control panel is buzzing	DFRC-B4801	FIRE		1:00
81957	TC	703 Cannon #8 is leaking	DAOF-B703	FIRE		0:05
84289	TC	B/4839 - System Alarm	DFRC-B4839	FIRE		0:40
84216	TC	4832 Warehouse - check fire suppression hardware after it was hit by a bird	DFRC-B4832-MAIL-ROOM	FIRE		0:10
84169	TC	4823 chem crib - gas detector in alarm	DFRC-B4823	FIRE		2:00
84315	TC	4823 Sheet Metal shop - replace 3 faded fire extinguisher signs	DFRC-B4823	FIRE		0:15
84384	TC	NB103 (Water Tank) - Water Fill Valve	DFRC-NB103	FIRE		1:30
86774	TC	B/4800 3rd Fl - Fire Alarm Control Panel	DFRC-B4800	FIRE	2204002	9:00
87026	TC	B/4800 Rm 2404 - Inergen Alarm	DFRC-B4800-FLOOR2	FIRE		0:00
86855	TC	4801 check what appears to be a sensor alarm going off; caller has never seen it before	DFRC-B4801	FIRE		0:05
86838	TC	B/703 - (Outage 1096) - Replace Flow Switches	DAOF-B703	FIRE		15:00
86893	TC	4800-3202 ACROSS THE HALL IS AN INERGEN PANEL THAT NEEDS THE LIGHT IN THE SWITCH REPLACED AS IT IS OUT; SEE ANTONIO FOR SPECIFICS	DFRC-B4800-FLOOR3	FIRE		0:00
86933	TC	703 SUPPORT LAWA FIRE SYSTEM TESTING PER RALPH ANTON	DAOF-B703	FIRE		0:30
88064	TC	B/4853 - Troubleshoot/Repair Fire Pump #3	DFRC-B4853	FIRE	4801023	11:00
86888	TC	B/4853 - Fire Pump Testing	DFRC-B4853	FIRE		3:00
86887	TC	B/4840 - Fire Pump Testing	DFRC-B4840	FIRE		5:00
86814	TC	4838 FACP in alarm	DFRC-B4838	FIRE		0:09
87016	TC	703-332C ESCUTCHEON FELL OFF FIRE SPRINKLER AND NEEDS TO BE REPAIRED	DAOF-B703	FIRE		0:00
89492	TC	703 CENTER HALL FACP IN ALARM STATING," TROUBLE =8 "	DAOF-B703	FIRE		0:00
89310	TC	B/4801 - Fire Alarm Box Sounding	DFRC-B4801	FIRE		1:00
89508	TC	NASA DRYDEN-SUPPORT FIRE ALARM DRILLS AT VARIOUS BUILDINGS ON CAMPUS	NASA-DRYDEN	FIRE		5:55

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89325	TC	703 CHECK FIRE VAULTS FOR WATER. IF WATER IS IN THE VAULTS PUMP IT OUT. THIS IS ALSO TO DETERMINE IF THERE IS A LEAK.	DAOF-B703	FIRE		1:00
89389	TC	B/4840 - Test Smoke Detectors	DFRC-B4840	FIRE		0:30
89511	TC	4800-1118 DISCOVERED DURING FIRE DRILL THERE IS A STROBE IN THE ROOM FOR THE HEARING IMPAIRED BUT NO SOUNDING ALARM LOUD ENOUGH OVER THE EQUIPMENT TO GET THE ATTENTION OF THE HEARING OCCUPANTS	DFRC-B4800-FLOOR1	FIRE		0:30
91683	TC	B/4824 - Fire Investigation & System Start Up	DFRC-B4824	FIRE		1:00
91565	TC	703-S343 HANG PORTABLE FIRE EXTINGUISHER IN OFFICE AND PUT UP A SIGN TO LABEL	DAOF-B703	FIRE		0:10
91566	TC	B/4824 - FACP Sounding	DFRC-B4824	FIRE		0:30
91516	TC	B/4853 - Alarm Sounding	DFRC-B4853	FIRE		0:15
91605	TC	4800-3113 INERGEN TROUBLE ALARM ON THEN OFF SHORTLY THEREAFTER	DFRC-B4800-FLOOR3	FIRE		0:09
91621	TC	4852 FACP ALARM IS SOUNDING	DFRC-B4852	FIRE		0:10
93846	TC	703 REMOVE HYDRAZINE CORD - NO LONGER IN USE	DAOF-B703	FIRE		1:00
59027	TC	B/4820 - RESET FIRE ALARM PANEL	DFRC-B4820	GENERAL		0:00
65677	TC	B/703 - Wheel Chair Bracing	DAOF-B703	GENERAL		0:00
65583	TC	B/4820 RM 108 - Repair dispenser	DFRC-B4820	GENERAL		0:00
65635	TC	B/4876 - Repair Rain Leak	DFRC-B4876	GENERAL		0:15
65641	TC	B/4800 Rm 1100 - Replace door stop	DFRC-B4800-FLOOR1	GENERAL		0:30
65645	TC	B/4800 East Entry Door - Ice	DFRC-B4800-FLOOR1	GENERAL		3:50
65675	TC	B/4832 (Odin) - Investigate smell	DFRC-B4832-COMPUTER-SUPPORT	GENERAL		1:15
65621	TC	B/4802 2nd flr - Replace light defuser	DFRC-B4820	GENERAL		0:15
65726	TC	B/4800 Rm 1013 - Dead mouse	DFRC-B4800-FLOOR1	GENERAL		0:45
67962	TC	B/4800 Rm 2321 - Ceiling Leak	DFRC-B4800-FLOOR2	GENERAL		8:00
67999	TC	B/4800 - Ceiling leaks	DFRC-B4800-FLOOR2	GENERAL		5:30
68062	TC	B/T-16 - Repair awning	DFRC-T-16	GENERAL		1:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

68071	TC	B/703 - Repair door hinge	DAOF-B703	GENERAL		0:00
70094	TC	4982 NEED BUTT CAN FOR EXTERIOR OF BLDG	DFRC-B4982	GENERAL		0:30
70265	TC	4809 DISPOSE OF DEAD RODENT; IN A LARGE ROOM IN THE BACK LEFT CORNER	DFRC-B4809	GENERAL		0:15
70025	TC	4825 REPAIR DRYWALL IN SECURITY POST 1 BREAKROOM	DFRC-B4825-POST1	GENERAL		2:15
70046	TC	4840 BAY 5-NEED MORE MOUSE TRAPS; SEE ART LAVOIE	DFRC-B4840	GENERAL		0:15
70134	TC	B/4806 - Ice	DFRC-B4806	GENERAL		0:35
70079	TC	703 SOUTHEAST EXTERIOR SMOKING AREA HAS ACCUMULATED MANY WEEDS THAT NEED REMOVAL	DAOF-B703	GENERAL		2:00
70246	TC	B/4800 - Door slamming	DFRC-B4800-FLOOR1	GENERAL		0:15
70269	TC	4830C REPLACE CEILING TILE AT WALL; LEAK NO LONGER EXISTS DUE TO RE-ROOFING JOB. SEE MARIA OR OCCUPANTS FOR SPECIFIC LOCATION	DFRC-B4830C	GENERAL		0:00
70035	TC	4800-1418 TWO PAPER TOWEL DISPENSERS ARE NOT WORKING	DFRC-B4800-FLOOR1	GENERAL		0:15
70279	TC	B/T-72 - Door Repair	DFRC-T-72	GENERAL		8:45
70295	TC	4802 REPLACE MISSING CEILING TILE NEXT TO SMALL ROLL UP DOOR AND SHACK; SEE RICK	DFRC-B4802	GENERAL		0:00
70256	TC	4832 DISCARD DEAD RODENT ON ODIN SIDE	DFRC-B4832-COMPUTER-SUPPORT	GENERAL		0:15
70259	TC	B/4802 - Floor drains	DFRC-B4802	GENERAL		0:30
72394	TC	4800-2005 REMOVE KEYBOARD TRAY; SEE AFREEKIA REGARDING THE MATTER.	DFRC-B4800-FLOOR2	GENERAL		0:15
72349	TC	703 FIRST FLOOR SOUTH - SIGN FOR HEARING PROTECTION FELL DOWN; NEEDS TO BE HUNG BACK UP ASAP	DAOF-B703	GENERAL		0:10
72494	TC	703 FABRICATION SHOP - NEED MICE TRAPS	DAOF-B703	GENERAL		0:15
72139	TC	4839 REPLACE MANUAL SOAP AND PAPER TOWEL DISPENSER (1EA) IN LADIES AND MENS RESTROOMS WITH AUTOMATIC DIISPENSERS	DFRC-B4839	GENERAL		3:00
72307	TC	703-N131D REPLACE PAPER TOWEL DISPENSER IN OFFICE'S RESTROOM	DAOF-B703	GENERAL		0:10

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72326	TC	703 THIRD FLOOR - INVESTIGATE NATURE AND ORIGIN OF NOXIOUS FUMES	DAOF-B703	GENERAL		1:00
72315	TC	B/4800 Rm 2349 - Repair Blinds	DFRC-B4800-FLOOR2	GENERAL		0:00
72336	TC	703-N131C LIFE SUPPORT - NEED MORE MOUSE TRAPS	DAOF-B703	GENERAL		0:10
72337	TC	703-N131C INSTALL 10 DOOR SWEEPS IN VARIOUS LOCATIONS; SWEEPS PROVIDED	DAOF-B703	GENERAL		0:40
72440	TC	B/4832 - Mouse Infestation	DFRC-B4832-COMPUTER-SUPPORT	GENERAL		1:45
72555	TC	4800-1012 CHECK A KEYBOARD TRAY THAT IS NOT OPERATING CORRECTLY	DFRC-B4800-FLOOR1	GENERAL		0:30
72507	TC	4825 SECURITY SIDE- KEYBOARD TRAY NOT MOVING AS DESIGNED	DFRC-B4825-POST1	GENERAL		0:30
72576	TC	4720 UPS ROOM - CHECK FOR DEAD RODENTS AS THERE IS A VERY BAD SMELL OF THE SAME	DFRC-B4720	GENERAL		1:45
72339	TC	4800-2205 LADIES ROOM - DISPENSER DOOR HAS COME OFF HINGES: NEED TALLER PERSON TO SET DOOR BACK ON HINGES	DFRC-B4800-FLOOR2	GENERAL		0:15
72513	TC	B/4830A - Ceiling Tiles	DFRC-B4830A	GENERAL		0:30
74197	TC	B/4839 Rm 9 - Pest Control	DFRC-B4839	GENERAL		0:15
75563	TC	B/4832 - Remove Mouse trap	DFRC-B4832	GENERAL		0:05
75315	TC	B/4857 - Pest Control	DFRC-B4857	GENERAL		0:05
75453	TC	B/4870 - Pest Control	DFRC-B4870	GENERAL		0:30
79639	TC	B/4822 - Door Latch Sticking	DFRC-B4822-MEDICAL	GENERAL		0:45
79434	TC	B/4800 Rm 2211 - Remove Tarp	DFRC-B4800-FLOOR2	GENERAL		2:00
79419	TC	B/4840 Rm 103 - Remove dead rodent	DFRC-B4840	GENERAL		0:15
79437	TC	B/4839 - Repair Pothole	DFRC-B4839	GENERAL		1:15
79563	TC	B/4840 Rm 105-8 - Dead Mouse	DFRC-B4840	GENERAL		0:10
79640	TC	B/4802 Hangar - Foul odor	DFRC-B4802	GENERAL		4:00
79689	TC	B/4808 - Pest Control	DFRC-B4808-LIFE-SUPPORT	GENERAL		0:15
81932	TC	B/4800 Rm 1409A - Remove Mouse	DFRC-B4800-FLOOR1	GENERAL		0:10
81733	TC	B/4800 Rm 1420 - Pest Control	DFRC-B4800-FLOOR1	GENERAL		0:15
82039	TC	B/4800 Rm 1406 - Mouse in trap	DFRC-B4800-FLOOR1	GENERAL		0:30
84304	TC	B/4800 - Traps Needed	DFRC-B4800-FLOOR1	GENERAL		0:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

84358	TC	B/4825 Cafe - HVAC Vent Cleaning	DFRC-B4825-GIFT-SHOP	GENERAL		11:30
84305	TC	B/4820 - Mouse traps	DFRC-B4820	GENERAL		0:15
84375	TC	B/4800 Rm 2412 - Repair Tripping Hazard	DFRC-B4800-FLOOR2	GENERAL		0:45
86981	TC	B/4857 - Pest Control	DFRC-B4857	GENERAL		0:15
86779	TC	B/T-17 & B/4802 - Remove & Reinstall AC Units	DFRC-B4802	GENERAL		7:00
86946	TC	B/4839 - Foul Odor	DFRC-B4839	GENERAL		0:30
87057	TC	B/4839 - Pest Control	DFRC-B4839	GENERAL		0:45
86702	TC	B/4857 - Pest Control	DFRC-B4857	GENERAL		0:30
86902	TC	B/4839 - Pest Control	DFRC-B4839	GENERAL		0:45
86980	TC	B/4850 - Door Handle Repair	DFRC-B4850	GENERAL		0:15
86782	TC	B/4800 Rm 3304 - Repair Items	DFRC-B4800-FLOOR3	GENERAL		1:15
86976	TC	B/4844 - Replace Ceiling Tiles	DFRC-B4844	GENERAL		1:15
86947	TC	B/4840 Rm 202B - Pest Control	DFRC-B4840	GENERAL		1:00
86979	TC	B/4825 - Pest Control	DFRC-B4825-POST1	GENERAL		0:15
87025	TC	B/4838 - Broken Sprinkler	DFRC-B4838	GENERAL		3:30
86780	TC	B/4857 - Pest Control	DFRC-B4857	GENERAL		0:30
89279	TC	B/4839 - Pest Control	DFRC-B4839	GENERAL		0:30
89368	TC	B/4720 - Pest Control	DFRC-B4720	GENERAL		1:15
89312	TC	B/4840 Bay 3 - Pest Control	DFRC-B4840	GENERAL		0:30
89432	TC	B/4840 - FOD Clean up	DFRC-B4840	GENERAL		6:30
89376	TC	B/4840 Rm 226 (et al)- Replace Ceiling Tiles	DFRC-B4840	GENERAL		0:00
91567	TC	NASA - Paint Out Stop Sign	DFRC	GENERAL		1:30
93891	TC	B/4824 - HAZMAT Clean Up of Fire	DFRC-B4824	GENERAL		0:00
65788	TC	4840 BAY 6-BLOWING COLD AIR	DFRC-B4840	HVAC		0:15
65586	TC	B/4800 Rm 2701 - Cold	DFRC-B4800-FLOOR2	HVAC		0:00
65672	TC	4840 BAY 4-AIRCRAFT COOLING AIR DOWN	DFRC-B4840	HVAC		0:30
65598	TC	B/4833 - No Heat	DFRC-B4833	HVAC		1:00
65627	TC	4850-101 ROOM TOO COLD	DFRC-B4850	HVAC		2:15
65628	TC	4830C-BLDG IS TOO COLD AT 62F	DFRC-B4830C	HVAC		0:15
65629	TC	4822 BLDG IS TOO COLD; HEAT HASN'T COME ON TODAY	DFRC-B4822-MEDICAL	HVAC		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

65631	TC	B/4800 Rm 1028 - Too Hot	DFRC-B4800-FLOOR1	HVAC		1:50
65578	TC	B/4800 Rms 2126, 2128 - Too Cold	DFRC-B4800-FLOOR2	HVAC		0:30
65648	TC	B/4800 Rm 2170 - Too Cold	DFRC-B4800-FLOOR2	HVAC		0:30
65686	TC	4823-210 SECOND FLOOR TOO WARM	DFRC-B4823	HVAC		1:30
65671	TC	4820 SUPPORT FOR BOILER	DFRC-B4820	HVAC		1:00
65729	TC	4840-113B ROOM HAS NO HEAT	DFRC-B4840	HVAC		1:45
65651	TC	4800-2223 CHECK MECHANICAL CABINET-AHU	DFRC-B4800-FLOOR2	HVAC		1:30
65750	TC	4850 FRONT OFFICE AREA TOO WARM	DFRC-B4850	HVAC		1:15
65683	TC	4820-106 REPAIR CEILING HEATER	DFRC-B4820	HVAC		21:45
65579	TC	B/4800 Rm 1724 - No Heat	DFRC-B4800-FLOOR1	HVAC		0:00
65580	TC	B/4867 - Heater not working	DFRC-B4867	HVAC		0:15
65774	TC	B/4982 - HVAC unit noise	DFRC-B4982	HVAC		4:00
65607	TC	T-01 TOO COLD-HEAT NOT RESPONDING	DFRC-T-01	HVAC		2:00
65609	TC	4823-MACHINE SHOP TOO COLD AT 58F	DFRC-B4823	HVAC		0:15
65610	TC	4831- TOO COLD IN BATTERY LAB	DFRC-B4831	HVAC		4:00
65649	TC	B/T-72 - AC/Heater not working	DFRC-T-72	HVAC		12:00
65860	TC	4800-1114 BLOWING COLD AIR; T-STAT READS 69F	DFRC-B4800-FLOOR1	HVAC		1:15
65577	TC	B/4832 - Sewage Smell	DFRC-B4832-COMPUTER-SUPPORT	HVAC		1:00
65603	TC	703-BOILER #1 WILL NOT START	DAOF-B703	HVAC		7:00
65687	TC	4825 AUDITORIUM IS TOO WARM	DFRC-B4825	HVAC		2:00
65714	TC	4825 GIFT SHOP TOO COLD	DFRC-B4825-GIFT-SHOP	HVAC		0:30
65719	TC	4800-1806 TOO COLD	DFRC-B4800-FLOOR1	HVAC		0:30
65622	TC	B/4850 Rm 111 - Vent Diffuser	DFRC-B4850	HVAC		0:30
65653	TC	4822 MEDICAL TOO WARM	DFRC-B4822-MEDICAL	HVAC		2:00
65768	TC	4800-2219 SMALL MEZZANINE TOO COLD AT 65F	DFRC-B4800-FLOOR2	HVAC		0:15
65721	TC	4839-CHECK ON AIR CONDITIONER	DFRC-B4839	HVAC		0:30
65657	TC	703 REPAIR COMMUNICATIONS BETWEEN FLN#3 AND INSIGHT	DAOF-B703	HVAC		2:00
65704	TC	703-122S LASER LAB-HEAT IS OFF; BLOWING COLD AIR	DAOF-B703	HVAC		5:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

65615	TC	4843-CHECK TWO THERMOSTATS	DFRC-B4843	HVAC		1:15
65763	TC	B/703 Rm 334S - Too Hot	DAOF-B703	HVAC		0:30
67959	TC	4822-Please check the clinic. It is too cold at 60.1 degrees. Thank you.	DFRC-B4822-MEDICAL	HVAC		2:15
68056	TC	B/4820 Rm 130 - Heat Pump	DFRC-B4820	HVAC		2:00
68065	TC	B4800-RM 2613 TOO WARM	DFRC-B4800-FLOOR2	HVAC		29:30:00
68078	TC	4870 CHECK TWO HVAC UNITS; IT'S VERY COLD. ONE UNIT READS 72 BUT OCCUPANTS ARE CONVINCED IT'S MUCH COLDER. THE OTHER UNIT READS 65 AND HAS NOT CHANGED ALL DAY AND WARMED THE AREA UP.	DFRC-B4870	HVAC		0:00
67980	TC	B/4839 - Too cold	DFRC-B4839	HVAC		1:00
68082	TC	703-. S142A too cold; t-stat says 70F, usually can feel heater now and again throughout the day but haven't felt it yet today.	DAOF-B703	HVAC		2:30
67905	TC	4800-1810 CHECK TEMPERATURE WOMEN'S AIR CREW ROOM	DFRC-B4800-FLOOR1	HVAC		0:15
67908	TC	B/4800 - Too Hot	DFRC-B4800	HVAC		0:45
67930	TC	4801-104A ROOM TOO WARM	DFRC-B4801	HVAC		8:00
67938	TC	4800-1409 too cold	DFRC-B4800-FLOOR1	HVAC		0:15
68145	TC	4820-201 CONTROL ROOM IS TOO WARM AT 81F; SEE KNUT ROEPEL EXT. 3840	DFRC-B4820	HVAC		0:00
68090	TC	B/4822 PSSF - Too Hot	DFRC-B4822-PSSF	HVAC		0:15
68096	TC	B/703 Rm 221 - Install diffusers	DAOF-B703	HVAC		1:00
68106	TC	B/4800 FH6 - Repair Bypass Valves	DFRC-B4800	HVAC		24:30:00
68130	TC	B/4822 - Too Cold	DFRC-B4822-MEDICAL	HVAC		0:30
68155	TC	4800-1422 TOO COLD AT 65.5F	DFRC-B4800-FLOOR1	HVAC		0:00
68169	TC	4800-1426 TOO COLD AT 57F	DFRC-B4800-FLOOR1	HVAC		0:01
67939	TC	4823 chem crib OFFICE too cold	DFRC-B4823	HVAC		0:30
68022	TC	B/4800 - Too Cold	DFRC-B4800-FLOOR1	HVAC		0:30
68095	TC	B/4840 Rm 113C - Too Hot	DFRC-B4840	HVAC		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

68114	TC	4830A NETWORK COMM RM VERY HOT; NEED TO COOL DOWN ROOM ASAP	DFRC-B4830A	HVAC		0:45
68044	TC	4876-TOO COLD IN OFFICE AREA; VENT BLOWING COLD AIR.	DFRC-B4876	HVAC		2:00
67906	TC	B/4800 Rm 3111 - Alarm Sounding	DFRC-B4800-FLOOR3	HVAC		0:30
67912	TC	4825 SECURITY DESK-TOO COLD	DFRC-B4825-POST1	HVAC		5:30
67985	TC	B/4801 Rm 2217 - Too Cold	DFRC-B4801	HVAC		0:00
68136	TC	703-VCC TOO WARM; THERMOSTAT NOT GIVING A READING.	DAOF-B703	HVAC		0:30
68099	TC	703 CHILLER #2 DOWN DUE TO VARIABLE SPEED DRIVE (VSD) FAILURE	DAOF-B703	HVAC		1:00
68119	TC	4840-212 TOO WARM AT 78F; ALSO SURROUNDING AREAS ARE TOO WARM.	DFRC-B4840	HVAC		0:30
68051	TC	B/4800 Rm 3101 - Too Cold	DFRC-B4800-FLOOR3	HVAC		1:00
68061	TC	B/703 Rm 121 - Too Cold	DAOF-B703	HVAC		2:00
68079	TC	B/4800 Rm 2001 - Leak in ceiling	DFRC-B4800-FLOOR2	HVAC		3:15
68102	TC	4800-2100 TOO WARM; CURRENTLY HOLDING A LARGE MEETING. THERMOSTAT READS 76F. NEED TEMP TURNED DOWN TO ALLOW FOR USAGE OF ROOM.	DFRC-B4800-FLOOR2	HVAC		0:15
68104	TC	T-1: HVAC UNIT BLOWING COLD AIR; SEE JAMES ISLES EXT. 3313	DFRC-T-01	HVAC		0:30
68162	TC	703-S122 TOO COLD; HEATER OFF	DAOF-B703	HVAC		1:00
68176	TC	B/703 - Too Cold	DAOF-B703	HVAC		5:00
68131	TC	B/4840 Rms 209 & 212 - Too Hot	DFRC-B4840	HVAC		5:45
68141	TC	4840-113A AND 113B-TOO WARM; CONFERENCE BEING HELD PRESENTLY	DFRC-B4840	HVAC		0:30
68052	TC	B/4820 Rm 204/208 - Too Cold	DFRC-B4820	HVAC		3:15
68152	TC	4832 REPAIR HEATER	DFRC-B4832	HVAC	201040	9:00
68153	TC	4832 REPAIR HEATER	DFRC-B4832	HVAC	201047	8:30
68156	TC	B/4806 - Too Cold	DFRC-B4806	HVAC	304032	8:20
68177	TC	703 FABRICATION SHOP-HEATERS INOPERABLE	DAOF-B703	HVAC		5:00
67932	TC	B/4822 - Too Cold	DFRC-B4822-MEDICAL	HVAC		1:30
67970	TC	4800-2217 TOO COLD AT 57F	DFRC-B4800-FLOOR2	HVAC		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

68030	TC	703-N111 TOO COLD	DAOF-B703	HVAC		5:00
67993	TC	4800-2213 TOO COLD	DFRC-B4800-FLOOR2	HVAC		0:30
68003	TC	4820-TURN OFF BREAKER FOR CHILLER COMPRESSOR #1; IN SUPPORT OF ANOTHER CONTRACTOR'S WORK.	DFRC-B4820	HVAC		1:00
68089	TC	B/703 - AHU #4 - Troubleshoot Vibration	DAOF-B703	HVAC	90504	0:00
68053	TC	B/4830 C - Too Cold	DFRC-B4830C	HVAC		0:30
68075	TC	B/4840 1st flr - Too Cold	DFRC-B4840	HVAC		3:00
68143	TC	B/4800 Rm 3302A - Too Hot	DFRC-B4800-FLOOR3	HVAC		2:00
68154	TC	4832 REPAIR HEATER	DFRC-B4832	HVAC	201046	9:00
68170	TC	4800-1029 TOO COLD AT 67F	DFRC-B4800-FLOOR1	HVAC		0:00
68184	TC	4800-1704 TOO COLD; THERMOSTAT READS 69F BUT ROOM FEELS LIKE A REFRIGERATED 60F	DFRC-B4800-FLOOR1	HVAC		2:00
67996	TC	703-N232 TOO COLD	DAOF-B703	HVAC		4:00
67997	TC	B/4801 - Cooling air system	DFRC-B4801	HVAC		3:00
68012	TC	703-S122 & S111 TOO COLD; NO HEAT IN BOTH ROOMS.	DAOF-B703	HVAC		0:30
68017	TC	4800-1512 TOO COLD	DFRC-B4800-FLOOR1	HVAC		0:15
68018	TC	B/4985 - AC UNIT ICED UP	DFRC-B4985	HVAC		9:00
68041	TC	4850-113 MECH RM-HOT WATER CIRCULATION PUMP IS VERY NOISY	DFRC-B4850	HVAC		0:45
68042	TC	4800-3209 & 3204 MISSION CONTROL CENTERS ONE AND TWO- ROOMS HAVE GONE UP 8DEGREES IN 4 HRS. NOW AT 75F.	DFRC-B4800-FLOOR3	HVAC		8:15
68072	TC	B/4833 - Board up Heaters	DFRC-B4833	HVAC		0:00
68049	TC	B/703 Life Support - Heater cycling on/off	DAOF-B703	HVAC		0:30
67935	TC	4801-104A/103 too warm	DFRC-B4801	HVAC		0:00
67988	TC	4845-YELLOW LIGHT ON THERMOSTAT LIT UP AND THE HEATER IS NOT COMING ON.	DFRC-B4845	HVAC		13:00
68138	TC	4823 SECOND FLOOR TOO WARM	DFRC-B4823	HVAC		0:00
68165	TC	4802 ICE MACHINE INOPERABLE	DFRC-B4802	HVAC	1098002	2:15
67971	TC	4825 CAFETERIA-TOO COLD AT 58F-SEE GEMMA BURRESS	DFRC-B4825-GIFT-SHOP	HVAC		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

67998	TC	B/4833 - Hangar heaters	DFRC-B4833	HVAC		2:00
68020	TC	4808-TOO COLD ON THE LOCKER ROOM SIDE OF THE BLDG	DFRC-B4808-LIFE-SUPPORT	HVAC		5:00
68132	TC	4800-1426 TOO COLD; ROOM NEXT DOOR HAS THERMOSTAT AND READS 68F BUT DOES NOT SEEM TO SERVICE RM 1426 WELL	DFRC-B4800-FLOOR1	HVAC		1:00
68133	TC	4830C CHECK THERMOSTAT AND HEATER. THEY DO NOT SEEM TO BE WORKING AFTER WEEKEND OUTAGE.	DFRC-B4830C	HVAC		0:30
70030	TC	4825 ISF AUDITORIUM TOO COLD	DFRC-B4825-GIFT-SHOP	HVAC		0:30
70164	TC	B/4837 - Too Cold	DFRC-B4837	HVAC	304057	5:00
70082	TC	192 REPAIR A/C HALF OF ENVIRONMENTAL UNIT AS THE SURROUNDING EQUIPMENT IS GETTING TOO WARM	DFRC-B192	HVAC		3:00
70147	TC	4800-2001 PLACE A DIVERTOR ABOVE CARMEN AREVALO'S DESK	DFRC-B4800-FLOOR2	HVAC		0:30
70161	TC	B/4810 Code F Area - Too Hot/Too Cold	DFRC-B4810	HVAC		23:30
70175	TC	B/4823 - Closed Loop Water System	DFRC-B4823	HVAC		10:00
70288	TC	703 NORTHWEST AREA SECOND FLOOR - INSIGHT IS SHOWING THAT VARIABLE AIR VOLUME BOX (VAV) 64 IS 100% OPEN AND AT 0 CUBIC FEET OF AIR PER MINUTE (CFM)	DAOF-B703	HVAC		2:00
70308	TC	703-221S TOO COLD	DAOF-B703	HVAC		1:00
70120	TC	4800-1013 SIX OCCUPANTS ALL WANT DIVERTORS OVER THEIR VENTS	DFRC-B4800-FLOOR1	HVAC		1:30
70145	TC	4870 SOUTH END OF BLDG; TOO COLD - HEATERS DO NOT SEEM TO BE WORKING	DFRC-B4870	HVAC		1:15
70146	TC	703 AGE SHOP/KAY & ASSOC. - TWO HEATERS INOP; ONE IS NOT ON AND ONE IS BLOWING AIR AT 55F.	DAOF-B703	HVAC		1:00
70250	TC	4810-2A THERMOSTAT IS INACCURATE	DFRC-B4810	HVAC		1:30
70251	TC	4822 PSSF - TOO WARM	DFRC-B4822-PSSF	HVAC		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

70263	TC	4800-1714 FOR ABOUT ONE WORK WEEK THE ROOM HAS CONSISTENTLY BEEN BETWEEN 77F-79F; THE OCCUPANTS ARE MUCH TOO WARM, THERE IS NO THERMOSTAT IN THE ROOM THAT THEY CAN SEE.	DFRC-B4800-FLOOR1	HVAC		1:45
70227	TC	B/4838 - Repair CRAC Unit	DFRC-B4838	HVAC	1046016	12:30
70240	TC	B/703 RM 311- Too Hot	DAOF-B703	HVAC		2:00
70277	TC	B/703 RMS 311/312 - Too Cold	DAOF-B703	HVAC		2:00
70140	TC	4833 FINISH REPAIRING HANGAR HEATERS; GET ASSET NUMBERS WHERE APPLICABLE; REFERENCE TROUBLE CALL #67998 - SEE WILL FYLER FOR SPECIFICS	DFRC-B4833	HVAC		7:00
70301	TC	4825 ISF AUDITORIUM IS TOO COLD AT 50F	DFRC-B4825-GIFT-SHOP	HVAC		9:00
70022	TC	B/4830A Comm Rm - Too Hot	DFRC-B4830A	HVAC		7:15
70097	TC	4838 THREE VAV's ARE SET AT 78F INSTEAD OF THE DESIGNATED 68F; VAV's 104 AND 106 ARE IN OCCUPIED AREAS, VAV 108 IS NOT	DFRC-B4838	HVAC		1:00
70098	TC	4820 TROUBLESHOOT AND REPAIR BOILER; MAY NEED TO BE RESET	DFRC-B4820	HVAC		4:00
70176	TC	B/4840 - Closed Loop Water System	DFRC-B4840	HVAC		23:00
70299	TC	B/4825 Cafe- Freezer Icing Up	DFRC-B4825-GIFT-SHOP	HVAC		3:45
70112	TC	B/4857 - Heater Noise	DFRC-B4857	HVAC		3:30
70130	TC	703-S142A TOO COLD	DAOF-B703	HVAC		0:00
70241	TC	B/4833 RM 100 - AC unit noisy	DFRC-B4833	HVAC		3:30
70267	TC	4825 SECURITY FRONT DESK AREA TOO COLD	DFRC-B4825-GIFT-SHOP	HVAC		1:00
70297	TC	B/4838 - Siemens Support	DFRC-B4838	HVAC		0:00
70307	TC	B/4801 RM 2217 - Too Hot	DFRC-B4801	HVAC		3:45
71185	TC	4840-222A TOO COLD IN THIS ROOM AT 68F. SETPOINT IS AT 77F	DFRC-B4840	HVAC		8:30
70153	TC	B/4826 - AC Compressor	DFRC-B4826	HVAC		3:00
70034	TC	703-S136 CHECK HVAC SYSTEM FOR ACCURACY; THIS IS A LAB AND TESTING REQUIRES A 60F ROOM TEMPERATURE	DAOF-B703	HVAC		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

70053	TC	4800-1114 PLACE A DIVERTOR OVER THE VENT BLOWING ON RUSSELL BROAD	DFRC-B4800-FLOOR1	HVAC		1:30
70173	TC	4800-2527 COMPUTER ROOM TOO WARM; APPROX. 80F AND RISING	DFRC-B4800-FLOOR2	HVAC		2:00
70177	TC	B/4800 - Closed Loop Water System	DFRC-B4800	HVAC		10:00
70280	TC	B/4870 - No Heat	DFRC-B4870	HVAC		0:30
70234	TC	703 #1 BOILER HAS SAFETY LIGHT ON	DAOF-B703	HVAC		2:00
70287	TC	B/4800 FH7A - Remove Air Compressor	DFRC-B4800	HVAC	1032003	5:30
70088	TC	B/4857 - No Heat	DFRC-B4857	HVAC	201003	5:45
70178	TC	B/4820 - Closed Loop Water System	DFRC-B4820	HVAC		3:30
70313	TC	B/703 - Chiller & CRAC alarm points	DAOF-B703	HVAC		0:00
72427	TC	4800-2215 LARGE MEZZANINE IS TOO WARM	DFRC-B4800-FLOOR2	HVAC		0:15
72570	TC	4800-1733 CONFERENCE ROOM TOO HOT	DFRC-B4800-FLOOR1	HVAC		0:15
72439	TC	B/4820 - Evap Cooler Panel	DFRC-B4820	HVAC		2:30
72468	TC	703-323F SOUTH SIDE - TOO HOT AT 80F	DAOF-B703	HVAC		1:30
72493	TC	4800 CHECK THE HALL/ROOMS WHERE CODE RI IS LOCATED; THEY ARE TOO HOT: 2304, 2231, 2230, 2305, 2309, ETC	DFRC-B4800-FLOOR2	HVAC		0:45
72380	TC	4800 SECOND FLOOR MEZZANINES - TOO COLD	DFRC-B4800-FLOOR2	HVAC		1:00
72351	TC	4839 CHECK THE HEATERS AT THE BACK OF THE BUILDING AS IT IS QUITE COLD BACK THERE	DFRC-B4839	HVAC		3:45
72353	TC	703 SECOND FLOOR WEST CONFERENCE ROOM AND SURROUNDING AREA IS TOO WARM FOR WORKERS DOING CONSTRUCTION IN AREA	DAOF-B703	HVAC		1:00
72327	TC	4800-2219 CHECK ON IRREGULARITIES IN HEATING AND COOLING CYCLES	DFRC-B4800-FLOOR2	HVAC		11:00
72328	TC	4800-2215 CHECK ON IRREGULARITIES IN HEATING AND COOLING CYCLES	DFRC-B4800-FLOOR2	HVAC		9:00
72352	TC	703-122A NORTH SIDE - TOO COLD; THERMOSTAT NOT WORKING, TEMP NOT RESPONDING	DAOF-B703	HVAC		1:00
72436	TC	B/4839 - Too cold	DFRC-B4839	HVAC		2:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72472	TC	4800 FAN HOUSE 6, AIR HANDLER UNIT 01 - SUPPLY FAN INOPERABLE	DFRC-B4800	HVAC	1003011	17:00
72517	TC	4800-2407 HUMAN RESOURCES IS TOO HOT	DFRC-B4800-FLOOR2	HVAC		1:00
72425	TC	4800 SECOND FLOOR ROOF OVER ROOM 2407 - THE WIND IS CAUSING SOMETHING TO BANG AND SLAM AROUND, IT SOUNDS LIKE IT IS METAL.	DFRC-B4800	HVAC		3:00
72508	TC	4825 CAFETERIA DINING AREA TOO WARM - SEE GEMMA BURRESS x3689	DFRC-B4825-GIFT-SHOP	HVAC		1:00
72497	TC	T-47 REINSTALL FLASHING	DFRC-T-47	HVAC		5:00
72374	TC	4864 OFFICES OR BLDG TOO COLD; SEE GARY MCNEELY OR BRIAN LEVAN. IF NEITHER IS FOUND THEN SEE PHIL BURKHARDT IN 4833-100	DFRC-B4864	HVAC	304027	1:15
72531	TC	4800-1303 CHECK THE AIR CIRCULATION; THERE SEEMS TO BE NONE	DFRC-B4800-FLOOR1	HVAC		3:45
72422	TC	4846 CHECK ACCESS PANEL ON ROOF; MAY HAVE BLOWN OFF IN WIND AS DAYLIGHT CAN BE SEEN THROUGH THE ROOF FROM INSIDE THE BLDG	DFRC-B4846	HVAC		1:45
73625	TC	4820-122 TOO COLD	DFRC-B4820	HVAC		8:00
72314	TC	B/4822 PSSF - Too Cold	DFRC-B4822-PSSF	HVAC		2:00
72390	TC	4840 SECOND FLOOR, FRONT END OF BLDG; TOO WARM	DFRC-B4840	HVAC		6:30
72319	TC	4800-2213 LARGE MEZZANINE - CHECK THE HEATING AND COOLING SYSTEM. THERE SEEMS TO BE SOME IRREGULARITY WITH HOW IT CYCLES	DFRC-B4800-FLOOR2	HVAC		9:45
72438	TC	B/4830A - Too Cold	DFRC-B4830A	HVAC		1:45
72489	TC	T-72 CHECK THE HVAC UNIT; THE COMPRESSOR OR PUMP WAS ICED OVER	DFRC-T-72	HVAC		6:30
72537	TC	4830D - THERMOSTAT NOT READING OR SHOWING READING	DFRC-B4830D	HVAC		0:30
72538	TC	4800-2808 TOO COLD; THERMOSTAT READS 65F AND SOME OFFICES FEEL COLDER THAN 65F	DFRC-B4800-FLOOR2	HVAC		4:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72539	TC	4823 REPLACE FALLEN, RUINED CEILING TILE IN ENTRY WAY HALL	DFRC-B4823	HVAC		0:45
72443	TC	B/4800 Rm 1405 - Replace Ceiling Tiles	DFRC-B4800-FLOOR1	HVAC		0:30
72481	TC	4800-1412 PLACE A DIVERTOR ON THE VENT OVER THE DESK OF REBECCA LOPEZ	DFRC-B4800-FLOOR1	HVAC		4:45
72506	TC	B/4820 - Too Hot	DFRC-B4820	HVAC		0:15
74193	TC	4876 CHECK TEMPERATURE IN METAL ROOM COOL BOX - USED FOR STORAGE; BATTERIES CORRODED AND IT MAY BE THE TEMPERATURE	DFRC-B4876	HVAC		9:15
74196	TC	B/4838 Rm 201 - Environmental Control Unit Fan Inop	DFRC-B4838	HVAC	1046016	3:00
74805	TC	703-222, 221 TOO WARM	DAOF-B703	HVAC		0:00
74785	TC	B/4800 VITS - Troubleshoot HVAC unit	DFRC-B4800-FLOOR2	HVAC		3:00
75357	TC	B/4876 - Troubleshoot HVAC issues	DFRC-B4876	HVAC		2:00
75415	TC	NASA - Create Dual Temp Set Points	DFRC	HVAC		0:00
75419	TC	NASA - Create Dual Temp Set Points	DFRC	HVAC		0:00
75418	TC	B/4800 Rm 2526 - Too Hot	DFRC-B4800-FLOOR2	HVAC		0:30
75521	TC	4840-230 CONFERENCE ROOM TOO WARM	DFRC-B4840	HVAC		0:30
75429	TC	4800-2228, 2108, 2109 TOO COLD AT 66F	DFRC-B4800-FLOOR2	HVAC		2:30
75454	TC	B/4876 - Noisy Heater	DFRC-B4876	HVAC	201044	6:00
75572	TC	B/703 - Repair Leaking Chiller	DAOF-B703	HVAC	31260194	10:00
75317	TC	B/4838 Rm 212A - AHU loud	DFRC-B4838	HVAC		8:00
75385	TC	4838-206 CHECK HUMIDITY; VERY LOW	DFRC-B4838	HVAC		2:30
75420	TC	NASA - Create Dual Temp Set Points	DFRC	HVAC		0:00
75499	TC	B/4800 - Lg Mezz Too Hot	DFRC-B4800-FLOOR2	HVAC		1:15
75360	TC	B4825 Gift Shop - Too Cold	DFRC-B4825-GIFT-SHOP	HVAC		0:30
75376	TC	703-123S TOOL CRIB - HEATER MAKING A SQUEALING SOUND	DAOF-B703	HVAC		11:30
75567	TC	B4838 UPS Rm - Air Conditioner not working	DFRC-B4838	HVAC		3:30
75300	TC	T-79 CHECK THE FAN ON THE AIR CONDITIONING UNIT	DFRC-T-79	HVAC		1:30
75303	TC	4810-3A OFFICE IS TOO HOT	DFRC-B4810	HVAC		1:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

75488	TC	4845 AIR CONDITIONER NOT WORKING AND THE FAN IS INOPERABLE	DFRC-B4845	HVAC		7:00
75308	TC	B/4838 - Siemens System	DFRC-B4838	HVAC		0:00
75312	TC	4800 FIRST FLOOR 1100's CORRIDOR - THE OFFICES ARE TOO COLD; IT SEEMS AS THOUGH THE A/C HAS BEEN ON STEADILY FOR 1 1/2 DAYS.	DFRC-B4800-FLOOR1	HVAC		1:00
75362	TC	B/4838 - Humidifier Repair	DFRC-B4838	HVAC	1096001	6:24
75584	TC	B/4838B UPS Rm - AC unit not working	DFRC-B4838B	HVAC	1003028	0:00
75496	TC	4800-1409 TOO WARM	DFRC-B4800-FLOOR1	HVAC		3:00
75352	TC	SUBSTATION 26 SECURE EQUIPMENT AND DISCONNECT TEMPERATURE ALARM	NASA-DRYDEN	HVAC		0:45
75353	TC	4800-2345, 2347, 2349 TOO COLD	DFRC-B4800-FLOOR2	HVAC		0:00
75467	TC	4820-102 NO AIR FLOW	DFRC-B4820	HVAC		2:00
75527	TC	4800-2301 AND 2231 ADJACENT ROOMS TOO WARM	DFRC-B4800-FLOOR2	HVAC		1:30
75423	TC	4800-2100 ECR - TOO WARM	DFRC-B4800-FLOOR2	HVAC		4:00
75513	TC	B4800 Rm 1028 - Too Hot	DFRC-B4800-FLOOR1	HVAC		2:00
75605	TC	4863 TOO WARM; A/C NOT COMING ON HARDLY	DFRC-B4863	HVAC		0:45
75469	TC	703-S142A TOO WARM; TOO WARM IN AFTERNOONS	DAOF-B703	HVAC		0:00
75531	TC	B/4800 Rm 1810 - Too Hot	DFRC-B4800-FLOOR1	HVAC		3:00
75318	TC	4800-2231 TOO HOT - FEELS LIKE 90F; THE ENTIRE HALLWAY IS FAR TOO WARM AND THE OFFICE IS EVEN HOTTER.	DFRC-B4800-FLOOR2	HVAC		2:30
75533	TC	B/4800 - Too Hot/No Air Flow	DFRC-B4800-FLOOR2	HVAC		2:00
75566	TC	B/703 Security - Air Conditioner	DAOF-B703	HVAC		5:00
75314	TC	4800-1406 CHECK JENNIFER PENROD'S OFFICE; TOO WARM	DFRC-B4800-FLOOR1	HVAC		3:00
75495	TC	4800-2116 TOO WARM ESPECIALLY IN THE MORNINGS AND THERE IS NO AIR CIRCULATION	DFRC-B4800-FLOOR2	HVAC		1:00
75328	TC	4800-1806 TOO COLD AGAIN	DFRC-B4800-FLOOR1	HVAC		1:00
75341	TC	4800-2215 LARGE MEZZ TOO COLD	DFRC-B4800-FLOOR2	HVAC		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

75412	TC	4800-2340 FAN BLOWER TOO LOUD; OCCUPANT CANNOT EVEN HEAR TELECONFERENCE.	DFRC-B4800-FLOOR2	HVAC		1:00
75436	TC	4825 CAFETERIA - ANTHONY'S PIZZA MAKE-UP TABLE IS ONLY 70F	DFRC-B4825	HVAC	1153001	1:15
75450	TC	4825 ISF AUDITORIUM - TOO WARM	DFRC-B4825-GIFT-SHOP	HVAC		0:30
75585	TC	B/4838B UPS Rm - AC unit not working	DFRC-B4838B	HVAC	1003029	16:30
75511	TC	4825 CAFETERIA ANTHONY'S PIZZA - MAKE UP TABLE SEAL IS COMING APART	DFRC-B4825-GIFT-SHOP	HVAC		7:15
77717	TC	B/4859 - (Service Call) - Ice Machine Inop	DFRC-B4859	HVAC		2:00
79532	TC	B4801 Lg Mezz - Too Hot	DFRC-B4801	HVAC		0:30
79418	TC	4800-2407 Human Resources - too warm especially in the afternoons	DFRC-B4800-FLOOR2	HVAC		0:45
79423	TC	4822 Medical Clinic too cold at 65F	DFRC-B4822-MEDICAL	HVAC		2:00
79429	TC	4809 North evaporative cooler started to smell like burning belt so it was turned off.	DFRC-B4809	HVAC		0:30
79578	TC	4844 Too warm; check thermostat	DFRC-B4844	HVAC		1:00
79582	TC	703-222 Too warm	DAOF-B703	HVAC		1:00
79441	TC	B/4800 Rm 2221 - Air Handler Noisy	DFRC-B4800-FLOOR2	HVAC		8:30
79622	TC	4825 ISF Conference room too warm	DFRC-B4825-POST1	HVAC		0:30
79623	TC	4822 Clinic too cold	DFRC-B4822-MEDICAL	HVAC		0:30
79472	TC	4825 Security Desk too warm	DFRC-B4825-POST1	HVAC		0:33
79477	TC	4838-133 Room too warm and air circulation is poor. Customer thinks perhaps a vent is closed.	DFRC-B4838	HVAC		2:30
79478	TC	4820-207 Room much too warm, office next door is 79F; Please call Joanne if this cannot be fixed.	DFRC-B4820	HVAC		0:15
79479	TC	4833 Reno alert for PA Modules at 84.2F, critical temperature is below 84; Chuck Rogers needs a call back regarding the matter: 661-810-7069	DFRC-B4833	HVAC		0:30
79540	TC	4720 A/C not operating correctly	DFRC-B4720	HVAC	304248	8:00
79541	TC	4802 A/C not operating - 304065	DFRC-B4802	HVAC		6:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

79542	TC	703-322S too warm; no air circulation. Room tends to be around low 80's by 15:00 every day	DAOF-B703	HVAC		0:00
79544	TC	4810 Code F - Too warm	DFRC-B4810	HVAC		0:30
79586	TC	B/4851 - Too Hot	DFRC-B4851	HVAC		1:15
79588	TC	B/4838 Rm 201- RENO Alarms	DFRC-B4838	HVAC	1046008	4:30
79440	TC	4822 Medical Clinic - too warm at 86F	DFRC-B4822-MEDICAL	HVAC		2:00
79442	TC	4800-1409 Loose stair tread on middle entry step; Safety issue, trip hazard.	DFRC-B4800-FLOOR1	HVAC		2:45
79383	TC	4820-204 TOO COLD AT 68F	DFRC-B4820	HVAC		0:30
79701	TC	B/4840 Rm 224 - CRAC Unit	DFRC-B4840	HVAC	1046027	1:00
79389	TC	4833-100 Removable thermostat fell off wall and the cover broke into several pieces.	DFRC-B4833	HVAC		0:45
79572	TC	4822 Medical Clinic - Too warm and temperature is rising; no air has come on at all.	DFRC-B4822-MEDICAL	HVAC		2:00
79575	TC	703-221A Too warm; no air circulation	DAOF-B703	HVAC		1:00
79632	TC	4820-122 Thermostat may have a faulty sensor because the heat is always "blasting" and it can only be turned off by remove the t-stat from the wall	DFRC-B4820	HVAC		8:45
79382	TC	4800-2215 LARGE MEZZANINE - SUDDENLY TOO WARM	DFRC-B4800-FLOOR2	HVAC		1:00
79611	TC	nasa-dryden bldgs: 4801, 4809, 4808, 4806, 4807, 4810, 4876, 4832 - Remove scale and debris from rotating copper mesh cooling media on various evaporative coolers	NASA-DRYDEN	HVAC		5:00
79615	TC	B4808 - Panel	DFRC-B4808	HVAC	1002048	0:30
79417	TC	B4822 PSSF - Too Hot	DFRC-B4822-PSSF	HVAC		11:00
79424	TC	4830B Mens and Ladies rest rooms are too warm at 92F	DFRC-B4830B	HVAC	1002060	2:30
79648	TC	4800-2228, 2231, 2301, 2304 are all too warm	DFRC-B4800-FLOOR2	HVAC		1:00
79681	TC	B/4801 - Excess Water	DFRC-B4801	HVAC	1002027	2:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

79655	TC	B/4800 Rm 1708 - Too Hot	DFRC-B4800-FLOOR1	HVAC		1:30
79511	TC	B/703 Rm 111 - Cold	DAOF-B703	HVAC		0:00
79257	TC	4800-1028 TOO WARM	DFRC-B4800-FLOOR1	HVAC		0:15
79258	TC	703-S142A TOO WARM	DAOF-B703	HVAC		1:00
79253	TC	4820 COOLING TOWER AT REAR OF BLDG IS MAKING EXCESSIVE NOISE	DFRC-B4820	HVAC		1:30
79259	TC	703-342 CONFERENCE ROOM TOO WARM	DAOF-B703	HVAC		1:00
79528	TC	4823 Second floor too warm	DFRC-B4823	HVAC		0:30
79529	TC	4800-2231, 2301, 2309 and hall are too warm	DFRC-B4800-FLOOR2	HVAC		0:30
79409	TC	703-221C South - Remount thermostat outside of room in hall.	DAOF-B703	HVAC		1:00
79410	TC	703-322 Too warm	DAOF-B703	HVAC		1:00
79411	TC	703-241 Conference room - Too warm	DAOF-B703	HVAC		1:00
79583	TC	4825 Security front desk area too warm	DFRC-B4825-POST1	HVAC		0:30
79438	TC	4800 Roof - A/C panel came off of unit and needs to be put on ASAP	DFRC-B4800	HVAC		0:30
79439	TC	703 AHU #4 is making a loud noise	DAOF-B703	HVAC		3:00
79709	TC	B/4826 - Water Leak	DFRC-B4826	HVAC		1:00
79669	TC	4800-1426 No air circulation and too warm at 79F; the other end of the offices at 1422 are comfortable	DFRC-B4800-FLOOR1	HVAC		0:00
79676	TC	4800 Fan House 8A - Pneumatic supply air pressure low; needs repair.	DFRC-B4800	HVAC		1:00
81624	TC	B4800 Rm 1426 - Air Movement	DFRC-B4800-FLOOR1	HVAC		0:30
81745	TC	B/4808 - Remove Media from HVAC unit	DFRC-B4808	HVAC		2:00
81814	TC	4825 ISF Auditorium too warm for large group meeting in one hour	DFRC-B4825	HVAC		0:15
81625	TC	4820 High bay too cold; evaporative coolers on non-stop	DFRC-B4820	HVAC		1:00
81628	TC	4720 UPS bldg/room on east side of ATF1 the air conditioner is not working	DFRC-B4720	HVAC		1:00
81732	TC	4838 Roof - air conditioner condenser unit making a bad noise; this condenser feeds a/c in room 202	DFRC-B4838	HVAC		2:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

81655	TC	4801 Room 103 Heat and Air unit - valve is sticking	DFRC-B4801	HVAC		2:15
83006	TC	4800 cooling tower #1 has a leaky valve	DFRC-B4800	HVAC	1181002	13:45
81942	TC	4846 through the up duct the sky can be seen allowing for the controlled air to escape and let hot air in	DFRC-B4846	HVAC		1:30
81943	TC	4825 Cafeteria Anthony's Pizza - refrigerator is too warm; see Young for specifics	DFRC-B4825-GIFT-SHOP	HVAC		0:30
81944	TC	703-2NGame room - is hot and stuffy	DAOF-B703	HVAC		1:00
81969	TC	4823 too hot in the shop on the first floor	DFRC-B4823	HVAC		6:30
81741	TC	B/4801 - Remove Media from HVAC unit	DFRC-B4801	HVAC		0:15
81909	TC	4800-2412 Research Library is too warm, too humid and earlier in the morning there was a burned smell like crossed wires but disipated quickly	DFRC-B4800-FLOOR2	HVAC		0:45
81946	TC	4800-2217 and area - temperature is in the low 80's with NO air circulation and uncomfortable humidity; evap coolers below may be the cause of the humidity	DFRC-B4800-FLOOR2	HVAC		6:00
81945	TC	4870 Robert Jones' office A/C is not working. The thermometer says 70F but the office is 78F. The A/C to the main office is working correctly.	DFRC-B4870	HVAC		0:00
81961	TC	4800 HR AHU03 not operating correctly	DFRC-B4800-FLOOR2	HVAC		2:00
82146	TC	4822 Medical Clinic fridge containing meds is running too warm according to it's thermometer; need confirmation and possible troubleshoot	DFRC-B4822-MEDICAL	HVAC		0:30
81988	TC	B/4823 - Troubleshoot / Repair AC unit	DFRC-B4823	HVAC	1002049	2:00
82023	TC	B/4982 - Too Hot	DFRC-B4982	HVAC		6:00
81951	TC	T-1 north end air conditioner, the one closest to the parking lot, is not working properly; see James for specifics.	DFRC-T-01	HVAC		3:00
82007	TC	B/4826 - AC unit is not working	DFRC-B4826	HVAC		4:15
82162	TC	B4825 Conf Rm - Too Hot	DFRC-B4825	HVAC		0:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

82167	TC	4982 north side exterior a/c unit is icing over badly - it is the unit that cools the office area across from the ops area	DFRC-B4982	HVAC		1:45
82114	TC	4801 too hot - check evaporative coolers	DFRC-B4801	HVAC	1002027	3:00
81927	TC	4800 Second floor north east area has various rooms that are much too warm including 2301 and 2231	DFRC-B4800-FLOOR2	HVAC		0:15
82207	TC	4876 Records Room - A/C is not working properly and the room is supposed to be temperature controlled	DFRC-B4876	HVAC		0:45
82204	TC	4801 Coolers do not seem to be blowing cool air any longer	DFRC-B4801	HVAC	1002027	3:00
81955	TC	B/703 Rm 140 - Troubleshoot AC	DAOF-B703	HVAC		1:00
82006	TC	B/4822 - Too Hot	DFRC-B4822-MEDICAL	HVAC		0:30
81749	TC	B/4832 - Remove Media from HVAC unit	DFRC-B4832	HVAC		3:30
81742	TC	B/4806 - Remove Media from HVAC unit	DFRC-B4806	HVAC		2:00
81634	TC	4800-2314 too warm	DFRC-B4800-FLOOR2	HVAC		1:00
81635	TC	703-322S room too warm	DAOF-B703	HVAC		1:00
81665	TC	4820 exterior north side of bldg an evaporative cooler panel has come off due to the wind	DFRC-B4820	HVAC		1:00
81743	TC	B/4807 - Remove Media from HVAC unit	DFRC-B4807	HVAC		1:30
81959	TC	B/4826 - Investigate Fire Alarm	DFRC-B4826	HVAC	305040	8:45
81800	TC	Substation 4 - check on air conditioner for substation	DFRC-NB084	HVAC		2:30
81801	TC	4820 warehouse evaporative cooler is giving off an electrical smell	DFRC-B4820	HVAC		0:30
81802	TC	4820 turn Siemens controlled air conditioning back on; was turned off temporarily until weather warmed up	DFRC-B4820	HVAC		2:55
81804	TC	703-221 and corresponding conference room are much too warm and the conference room is being used presently	DAOF-B703	HVAC		1:00
81806	TC	4800-2015 office too warm; in the 80's	DFRC-B4800-FLOOR2	HVAC		0:20
81895	TC	4823 second floor is up over 80Fby 8AM	DFRC-B4823	HVAC		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

81899	TC	4838-201 CRAC unit is down completely	DFRC-B4838	HVAC	1046016	0:45
81901	TC	4825 VCC is too warm - having a large group meeting	DFRC-B4825-POST1	HVAC		12:15
81765	TC	4833 water dripping into the sewer pipe all day yesterday, likely through the night, and presently; may be a float on an evaporative cooler causing drain off	DFRC-B4833	HVAC	305087	9:30
82016	TC	4800-2340 the office is too warm and has poor air circulation; when the ceiling tiles have been moved the office has gotten air and cooled down	DFRC-B4800-FLOOR2	HVAC		0:30
82017	TC	4825 cafeteria - two door reach in fridge for Anthony's and Robin Hood is getting warm fast and it is during lunch service	DFRC-B4825	HVAC	1004001	3:45
82026	TC	B/4826 - Evap Cooler Noisy	DFRC-B4826	HVAC		3:15
81903	TC	4851 too warm	DFRC-B4851	HVAC		0:30
81904	TC	703-133S troubleshoot and correct airflow in SOFIA Lab #4.	DAOF-B703	HVAC		1:00
81907	TC	4801-102 too warm	DFRC-B4801	HVAC		1:15
81978	TC	4800-3302 and surrounding office area has been around 85F+ degrees; it is much too warm	DFRC-B4800-FLOOR3	HVAC		1:30
82037	TC	4810 Code F area is too cold	DFRC-B4810	HVAC		0:15
82042	TC	Fan house 1A Chiller #2 repair an oil leak on the piping from the oil reservoir to the filters	DFRC-B4800	HVAC		21:00
82031	TC	B4800 Rm 1115 - Verify Air Supply / Temperature	DFRC-B4800-FLOOR1	HVAC		0:00
81979	TC	4800-1720 need to place a divertor over occupants desk as the air blowing down on him is much too cold	DFRC-B4800-FLOOR1	HVAC		0:30
82015	TC	4846 HR office is too cold but if the thermostat is altered the rest of the building gets too warm; See Maria for specifics	DFRC-B4846	HVAC		2:00
82169	TC	B/4800 FH1A - Replace Pressure Relief Valve	DFRC-B4800	HVAC	1019001	0:00
82143	TC	B/4839 Rm 6 - Too Warm	DFRC-B4839	HVAC	304151	5:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

82150	TC	4838-213 Tape Library is too warm in the mid 80's; may have it's own air handler that needs looking at	DFRC-B4838	HVAC		2:15
81813	TC	4800-2100 ECR is too warm; having a meeting presently need temp turned down now.	DFRC-B4800-FLOOR2	HVAC		4:30
81936	TC	703-S332 the east end of the room gets much hotter than the rest of the room	DAOF-B703	HVAC		1:00
82012	TC	B/4981 - Replace Air Conditioning Unit	DFRC-B4981	HVAC		6:15
82021	TC	4846 air conditioning unit blowing warm air	DFRC-B4846	HVAC		1:30
82126	TC	B/4840 Rm 239 - Too Hot	DFRC-B4840	HVAC		1:30
81731	TC	B/4801 Rm 112 - Water Leak	DFRC-B4801	HVAC		4:00
81746	TC	B/4809 - Remove Media from HVAC unit	DFRC-B4809	HVAC		1:00
81748	TC	B/4810 - Remove Media from HVAC unit	DFRC-B4810	HVAC		1:00
81750	TC	B/4876 - Remove Media from HVAC unit	DFRC-B4876	HVAC		29:30:00
81772	TC	B/4800 AH2 - Filter Alarm	DFRC-B4800	HVAC	1003014	4:00
82027	TC	B/703 Rm 131D - Too Hot	DAOF-B703	HVAC		1:00
82030	TC	703-N111 Logistics is too warm	DAOF-B703	HVAC		1:00
81787	TC	4802 under Bay 2 a domestic water pipe going to an evaporative cooler is knocking making noise; the employees thought it was an AFFF pipe and BWerner responded initially making determination	DFRC-B4802	HVAC		0:00
81793	TC	B/4800 Rm 1716 - Replace Cover	DFRC-B4800-FLOOR1	HVAC		1:30
81794	TC	B/4856 - Evaporative Cooler	DFRC-B4856	HVAC		2:00
81807	TC	B/4820 - Air Handlers	DFRC-B4820	HVAC		1:30
81824	TC	B4876 - Evap Coolers Not Working	DFRC-B4876	HVAC		0:30
81873	TC	4822 Clinic is too warm	DFRC-B4822	HVAC		0:30
81919	TC	4840 Bay 4 aircraft cooling air is down creating a work stoppage	DFRC-B4840	HVAC		1:30
81651	TC	B/4838 Rm 212A - CRAC Unit Shut down	DFRC-B4800	HVAC	1046001	3:30
81925	TC	4820 first and second floor chillers are not working	DFRC-B4820	HVAC		0:45
81928	TC	4822 Clinic is too warm	DFRC-B4822-MEDICAL	HVAC		0:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

81933	TC	4820-222 the thermostat in 122 controls the temp in 222. when the thermostat is set for 78F in 122 the temp rises to 88F in 222. the occupants would like the t-stat set to make it 78F in 222.	DFRC-B4820	HVAC		4:00
81965	TC	4820 rooms 103-107 & 204-209 are all too warm and there is no air circulation; this has been the case since an A/C unit was disconnected and reconnected approx a week ago	DFRC-B4820	HVAC		0:45
81975	TC	B/4839 - Set Programmable T-Stats	DFRC-B4839	HVAC		2:00
81976	TC	B/703 Rm 241L - Troubleshoot AC	DAOF-B703	HVAC		1:00
84230	TC	B/4845 - AC is not working	DFRC-B4845	HVAC		1:30
84231	TC	B/4801 - Coolers Not Working	DFRC-B4801	HVAC		1:30
84237	TC	B/4822 - AC unit not on	DFRC-B4822-MEDICAL	HVAC		1:00
84281	TC	B/4720 - AC unit not working	DFRC-B4720	HVAC		2:00
84328	TC	B4823 Weld Shop - Adjust Temperature/T-Stat Control	DFRC-B4823	HVAC		0:30
84255	TC	4820 air handlers leaking onto the second and third floors	DFRC-B4820	HVAC		6:00
84257	TC	4863 too warm; no air circulation	DFRC-B4863	HVAC		0:30
84306	TC	B/4800 RM 1732 - No AC	DFRC-B4800-FLOOR1	HVAC		0:15
84318	TC	B/4800 Rm 1811 - Too Cold	DFRC-B4800-FLOOR1	HVAC		0:30
84346	TC	4840 Condenser pump is leaking, possibly at the seals	DFRC-B4840	HVAC	1140010	1:30
84264	TC	B/703 Rm 111 - No power to AC unit	DAOF-B703	HVAC		0:00
84245	TC	4839 the front half of the bldg seems to have no air conditioning	DFRC-B4839	HVAC	304150	6:34
84311	TC	B/4800 Rm 1115 - Adjust Temperature	DFRC-B4800-FLOOR1	HVAC		1:30
84351	TC	4825 Cafeteria food court - two ice makers are not working	DFRC-B4825	HVAC		3:30
84295	TC	4825 Anthony's kitchen and back area as well as food court office are too hot and the a/c does not feel like it's working; see Young for specifics	DFRC-B4825-GIFT-SHOP	HVAC		0:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

84296	TC	4840 Bay 4 aircraft cooling air is in alarm and creating a work stoppage	DFRC-B4840	HVAC		2:15
84297	TC	4876 a cooler in the middle of the warehouse is blowing hot air	DFRC-B4876	HVAC		5:00
84300	TC	4845 the air conditioner servicing the area George Grimshaw and another gentleman sit in rapidly cycled on and off all morning than never came back on	DFRC-B4845	HVAC		6:45
84301	TC	4800-1412 unblock blocked vent	DFRC-B4800-FLOOR1	HVAC		0:30
84302	TC	703-111 repair/replace toggle switch to air conditioner	DAOF-B703	HVAC		0:45
84357	TC	B4800 Rm 1720 - Too Hot	DFRC-B4800-FLOOR1	HVAC		0:30
84359	TC	B/4800 Rm 2225 - Too Hot	DFRC-B4800-FLOOR2	HVAC		1:00
84285	TC	4820-122/222 no air conditioning in rooms	DFRC-B4820	HVAC		20:00
84261	TC	B/4823 - AC units not working	DFRC-B4823	HVAC		1:30
84176	TC	4820 remove oil at chiller compressor B1	DFRC-B4820	HVAC		2:00
84177	TC	4838 Reno Alarm	DFRC-B4838	HVAC		2:30
84179	TC	4838 increase the temperature on 3 VAV's by 7 degrees as it is too cold in this location; VAV #'s 102, 103, 104	DFRC-B4838	HVAC		0:30
84185	TC	4820 FanHouse 8 - return air fan motor is much too hot	DFRC-B4820	HVAC		13:00
84314	TC	4820 Hydraulic Pump Room evaporative cooler is not working	DFRC-B4820	HVAC		1:00
84269	TC	4837 a/c tripping breaker on connex	DFRC-B4837	HVAC		4:45
84316	TC	4870 too cold. a/c cycles on long for cold and blows too much and when cycled off is very short	DFRC-B4870	HVAC		2:15
84323	TC	4825 ISF Auditorium is too warm for the Blood Drive	DFRC-B4825	HVAC		0:45
84246	TC	4830E the thermostat may be inoperable as there is no air movement and it is too hot	DFRC-B4830E	HVAC		0:00
84381	TC	4825 Security too warm; check temp in range	DFRC-B4825-POST1	HVAC		0:30
84382	TC	4800-1720 too warm; a/c blowing warm air	DFRC-B4800-FLOOR1	HVAC		0:30
84248	TC	4877 too warm	DFRC-B4877	HVAC		12:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

84171	TC	T-47 too cold in one part of the trailer but if the thermostat is raised the other part of the trailer gets too warm	DFRC-T-47	HVAC		1:00
84404	TC	B/4826 - Evap Coolers Leaking	DFRC-B4826	HVAC	305040	1:30
84405	TC	B/4985 Van - AC Unit	DFRC-B4985	HVAC		12:00
84409	TC	703-322 too warm	DAOF-B703	HVAC		0:00
84410	TC	703-S142A too warm	DAOF-B703	HVAC		0:30
84414	TC	B/703 Rm 221 - Too Hot	DAOF-B703	HVAC		1:30
84407	TC	4844 Payload Side too hot at 78F large group till Friday John Torres given go ahead to lower to 75F. if still to hot lower to 73F. return to 78F COB 7/22/11	DFRC-B4844	HVAC		0:45
86783	TC	4802 - 5 evaporative coolers are not working	DFRC-B4802	HVAC	1047004	6:00
86790	TC	4833 the evaporative coolers do not seem to be working; also, the coolers are needed Sat. 7/30/11 as the occupants will be there working.	DFRC-B4833	HVAC		2:30
86695	TC	703-142 too warm in the mornings	DAOF-B703	HVAC		1:00
86844	TC	B/4820 - AC Unit not working	DFRC-B4820	HVAC		2:00
86920	TC	4800-1700's too warm in block of offices	DFRC-B4800-FLOOR1	HVAC		0:45
86757	TC	4876 evaporative cooler - the second one in going south to north is blowing hot air	DFRC-B4876	HVAC		7:30
86831	TC	NASA - Siemens System Repairs	DFRC	HVAC		2:00
86832	TC	B/703 Rm 222S - Too Hot	DAOF-B703	HVAC		0:30
86923	TC	4985 Mobile Ops Trailer MOF1 is 107F; the cooler is running but not working and stopped cooling around 11am	DFRC-B4985	HVAC		9:00
86995	TC	4820-104 A/C NOT WORKING	DFRC-B4820	HVAC		6:00
87019	TC	4846 CHECK A/C; THE CONFERENCE ROOM RUNS TOO WARM WHILE THE SURROUNDING ROOMS RUN MUCH TOO COOL	DFRC-B4846	HVAC		3:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

86706	TC	4825 Cafeteria - American Eatery - a fridge in the front of the eatery has a seal/stripping coming loose that needs repair/replacement. See Young for specifics	DFRC-B4825	HVAC	31260076	0:30
86913	TC	4809 middle evaporative cooler is not working	DFRC-B4809	HVAC		7:30
86712	TC	4802 the evaporative coolers feel as though they are not working	DFRC-B4802	HVAC		9:15
86750	TC	703-322 office too warm at 79.7F	DAOF-B703	HVAC		0:30
86752	TC	4838-212A CRAC unit inoperable - 85F	DFRC-B4838	HVAC		2:30
86753	TC	4844 COMM room is too warm	DFRC-B4844	HVAC		23:30
86754	TC	4850 too cold	DFRC-B4850	HVAC		1:30
86856	TC	703-142 check room temp; see Renee for specifics	DAOF-B703	HVAC		0:45
86858	TC	4838-212A air handler/conditioner not working still or again	DFRC-B4838	HVAC		1:00
86892	TC	4800-2215 MSO office is too warm at 81F	DFRC-B4800-FLOOR2	HVAC		4:45
86906	TC	B/4823 - Evap Cooler Leaking	DFRC-B4823	HVAC	305015	2:15
86930	TC	4820-222 remove portable a/c unit that is no longer being used	DFRC-B4820	HVAC		1:30
86764	TC	703 SOFIA Science Labs - investigate reported high temperatures	DAOF-B703	HVAC		7:30
86781	TC	B/4800 Rm 2407 - Rattle in Ceiling	DFRC-B4800-FLOOR2	HVAC		0:30
86825	TC	4840 second floor opposite the sims has little if any air circulation	DFRC-B4840	HVAC		0:30
86851	TC	B/4845 - Troubleshoot T-stat/Ac units	DFRC-B4845	HVAC		1:00
86894	TC	4876 TRAILER IN REAR OF BLDG - THE A/C IS RUNNING BUT NOT BLOWING ANY AIR, THE THERMOSTAT IS SET FOR 68F BUT READS 85F. SEE RICK FOR SPECIFICS	DFRC-B4876	HVAC		4:00
86786	TC	4820 check high bay evaporative coolers	DFRC-B4820	HVAC	1047018	4:30
86692	TC	4800-2407 acrid smell coming into office possibly through the vents causing eyes to water and like symptoms	DFRC-B4800-FLOOR2	HVAC		0:30
86718	TC	B/4800 Rm 1732 - No Air Flow	DFRC-B4800-FLOOR1	HVAC		0:25

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

86773	TC	B/4800 Finance Office - Too Hot	DFRC-B4800-FLOOR1	HVAC		2:00
86886	TC	B/703 - Check Exhaust Fan / Chiller Refrigerant Monitor	DAOF-B703	HVAC		0:45
86862	TC	703-322S check room temperature; see Brennan for specifics	DAOF-B703	HVAC		0:30
86938	TC	4810 NORTH SIDE NEAR JEAN MANNING'S OFFICE TWO WALL VENTS NEED DIVERTORS	DFRC-B4810	HVAC		1:00
86674	TC	T-17 a/c inoperable; see Carol Hunt x5851	DFRC-T-17	HVAC		3:00
86683	TC	Exhaust Fan 44 South - replace I-Line thermostat (temp rise 120V) Attn: Will	DAOF-B703	HVAC		0:00
86703	TC	B/4839 - No Air Flow	DFRC-B4839	HVAC		1:00
86743	TC	4833 HANGAR - EVAPORATIVE COOLERS HAVE BEEN CYCLING ON AND OFF AS THOUGH CONTROLLED BY A FAULTY THERMOSTAT. SOME ARE NOT WORKING AT ALL.	DFRC-B4833	HVAC		3:15
86745	TC	703-311 OFFICE IS TOO WARM AND HAS NO AIR CIRCULATION	DAOF-B703	HVAC		0:30
86756	TC	B/4833 Hangar - No Air Flow	DFRC-B4833	HVAC		0:00
86915	TC	4840 Bay 4 - Aircraft cooling air not working	DFRC-B4840	HVAC		0:45
86687	TC	4801-102 a/c stopped working altogether	DFRC-B4801	HVAC		2:30
86800	TC	4822 Clinic - a/c not coming on	DFRC-B4822-MEDICAL	HVAC		0:30
86819	TC	4877 warm air coming out of a/c; thermostat set for 68F but reading 72F	DFRC-B4877	HVAC		6:00
87023	TC	B/4820 Rm 100-102 - Too Hot	DFRC-B4820	HVAC		3:00
86829	TC	703 fourth floor south west mezzanine - fan return air motor making noise	DAOF-B703	HVAC	90603	1:30
86822	TC	4823 high bay evaporative cooler closest to the lakebed side; pads totally dry, something smells like it's burning up	DFRC-B4823	HVAC	305014	2:45
86830	TC	NASA - Troubleshoot HVAC Units	DFRC	HVAC		0:45
86853	TC	B/4824 - AC not working	DFRC-B4824	HVAC		3:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

86826	TC	4800-2407 Human Resources Patsy Smith's office the ceiling, ilght fixtures, fire suppression system, etc is vibrating so badly that it has become unbearable for the occupant	DFRC-B4800-FLOOR2	HVAC		1:00
86863	TC	B/4840 Rm 158 - Replace Haloguard II Sensors	DFRC-B4840	HVAC		5:00
86929	TC	4800-1720 the sounds of water drops falling onto ceiling tiles is repeating around the office though no ceiling tiles are wet yet	DFRC-B4800-FLOOR1	HVAC		5:45
86957	TC	4800 Rooms 2108-2120 have been too warm all week and are especially warm today	DFRC-B4800-FLOOR2	HVAC		0:15
86917	TC	4863 Jose Rivera's office is much too hot	DFRC-B4863	HVAC		2:30
86965	TC	B/4839 - Too Hot	DFRC-B4839	HVAC		1:00
86971	TC	B/4800 Rms 1409, 1012, 1013 - Adjust Temperatures	DFRC-B4800-FLOOR1	HVAC		1:00
87021	TC	B/4838 - RENO Alarm	DFRC-B4838	HVAC		6:30
86984	TC	B/703 Rm 322 - Too Hot	DAOF-B703	HVAC		1:00
89651	TC	703-241, 242 NORTH - ROOMS ARE TOO WARM	DAOF-B703	HVAC		0:30
89667	TC	4825 SECURITY POST 1 IS TOO WARM	DFRC-B4825-POST1	HVAC		7:30
89677	TC	4877 A/C UNIT LEAKING REFRIGERANT	DFRC-B4877	HVAC		2:00
88755	TC	B/4838 - Actuator Repair/Replacement	DFRC-B4838	HVAC		0:00
89465	TC	4802 EVAPORATIVE COOLER LEAKING WATER	DFRC-B4802	HVAC		4:15
89471	TC	4800 replace the seal on the leaking condenser water pump in fan house 1A that was discovered on Saturday, 8/27	DFRC-B4800	HVAC		3:00
89474	TC	703-221, 222 BOTH OFFICES ARE TOO COLD ESPECIALLY BRENT COBLEIGH'S OFFICE IN 222	DAOF-B703	HVAC		0:00
89476	TC	4800-2504, 2506, 2508 TOO COLD. THERMOSTAT IN ROOM 2508 FOR ALL THREE ROOMS READS 65F	DFRC-B4800-FLOOR2	HVAC		0:00
89278	TC	B/4800 Rm 3209 - Too Hot	DFRC-B4800-FLOOR3	HVAC		3:00
89506	TC	SUB 4 - A/C NOT WORKING	DFRC-NB084	HVAC		0:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89513	TC	B703A Visitors trailer- AC unit stopped working	DAOF-B703A	HVAC		0:15
89527	TC	703-122 CHECK AIR CONDITIONING	DAOF-B703	HVAC		0:30
89292	TC	4800-1012, 1013 TOO COLD AND 1409 TOO WARM	DFRC-B4800-FLOOR1	HVAC		1:00
89537	TC	B/4839 - No Air Flow	DFRC-B4839	HVAC		2:00
89549	TC	4825 SECURITY - TOO WARM AND THE AIR IS NOT COMING ON	DFRC-B4825	HVAC		0:30
89331	TC	4823 CHECK A/C; HOT AND NO AIR CIRCULATION	DFRC-B4823	HVAC		2:00
89335	TC	703-322 MUCH TOO WARM AT 80.1; CANNOT HEAR OR FEEL AIR MOVING	DAOF-B703	HVAC		0:30
89362	TC	B/4800 Rm 2613 - Too Cold	DFRC-B4800-FLOOR2	HVAC		1:00
89374	TC	4825 ISF AUDITORIUM TOO WARM DURING LARGE GROUP MEETING	DFRC-B4825	HVAC		1:30
89375	TC	4820 SECOND FLOOR AIR CONDITIONING NOT WORKING	DFRC-B4820	HVAC		3:00
89387	TC	4825 ISF AUDITORIUM TOO WARM	DFRC-B4825	HVAC		1:30
89388	TC	B/703 South - A/C Not Working	DAOF-B703	HVAC		0:00
89397	TC	4720 NORTH CONNEX AIR CONDITIONING IS INOPERABLE; NEED ASSISTANCE FOR MISSION SUPPORT	DFRC-B4720	HVAC		4:30
89413	TC	4838-117, 119, 120 AND POSSIBLY SURROUNDING AREA IS TOO WARM	DFRC-B4838	HVAC		0:30
89593	TC	4820 NO SUB-FLOOR COOLING WORKING	DFRC-B4820	HVAC		1:45
89605	TC	B/4800 Rm 2407 - Too Cold	DFRC-B4800-FLOOR2	HVAC		0:30
89611	TC	4800-1122 WATER TOWER OUTSIDE SHAKER LAB IS MAKING A BAD NOISE	DFRC-B4800-FLOOR1	HVAC		1:00
89614	TC	B703 Rm 111- AC blowing hot air	DAOF-B703A	HVAC		1:00
89523	TC	4838-135 ROOM IS TOO WARM CONSISTENTLY AT A STEADY 79F. IT IS NEARLY IDENTICAL TO A ROOM ON THE SAME SIDE OF THE BLDG THAT RUNS COOLER. TROUBLESHOOT/ ADJUST COOLING TO CONSISTENTLY BE WITHIN 78F	DFRC-B4838	HVAC		6:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89378	TC	4876 TWO EVAPORATIVE COOLERS ARE INOPERATIVE; ONE IS BLOWING HOT AIR AND ONE IS NOT COMING ON AT ALL.	DFRC-B4876	HVAC		4:30
89390	TC	NASA - Siemens Outage	DFRC	HVAC		16:30
89307	TC	4800-2323, RI CONFERENCE ROOM, AND SURROUNDING AREA IS MUCH TOO WARM	DFRC-B4800-FLOOR2	HVAC		0:15
89282	TC	4840 BAY 4 WARNING LIGHT TO AIRCRAFT COOLING AIR NEEDS TO BE RESET	DFRC-B4840	HVAC		0:45
89319	TC	4800-2301, 2305, 2231 ROOMS ARE ALL MUCH TOO WARM	DFRC-B4800-FLOOR2	HVAC		1:00
89309	TC	B/4842 - Too Hot	DFRC-B4842	HVAC		1:00
89380	TC	4834 A/C NOT WORKING	DFRC-B4834	HVAC		5:30
89381	TC	703-142 TOO WARM	DAOF-B703	HVAC		1:30
89334	TC	4800-2100 CORRIDOR AND IT'S OFFICES ARE MUCH TOO WARM	DFRC-B4800-FLOOR2	HVAC		1:00
89338	TC	B/4982 - Noisy Water Pump	DFRC-B4982	HVAC		3:00
89366	TC	B/4846 - Too Hot	DFRC-B4846	HVAC		2:00
89396	TC	B/4832 - Troubleshoot Evap Cooler	DFRC-B4832-COMPUTER-SUPPORT	HVAC		0:00
89418	TC	4800-1422 TOO COLD	DFRC-B4800-FLOOR1	HVAC		0:00
89419	TC	703-231S OFFICE IS VERY WARM; SEE WALT MILLER	DAOF-B703	HVAC		0:20
89300	TC	4844 THE A/C IS BLOWING HOT AIR IN THE MIDDLE AREA OF THE BLDG BY THE GLASS DOUBLE DOORS	DFRC-B4844	HVAC		2:00
89365	TC	B/4720 - No AC to Global Hawk Connex	DFRC-B4720	HVAC		3:00
89426	TC	B4838 Computer Rm - Temperature Concern	DFRC-B4838	HVAC		0:30
89323	TC	B/4823 - Noisy AC Unit	DFRC-B4823	HVAC		2:00
89266	TC	4825 CAFETERIA - ROBIN HOOD REACH-IN FREEZER IS ABOVE TEMPERATURE; GOT UP TO 52F AND LOWERED TO 40F BUT NOT COLD ENOUGH	DFRC-B4825	HVAC		3:00
89423	TC	B/4820 2ND FL - Air Handlers Vibrating	DFRC-B4820	HVAC		3:30
89514	TC	703-221 TOO COLD; HAS BEEN TOO COLD FOR SEVERAL DAYS - OR IT WILL BE TOO WARM BUT NO IN BETWEEN	DAOF-B703	HVAC		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89468	TC	4800-2520 TOO COLD AS THE THERMOSTAT READS 66F AND HAS FOR ABOUT TWO WEEKS	DFRC-B4800-FLOOR2	HVAC		1:00
89517	TC	B4852- AC unit is not working	DFRC-B4852	HVAC		6:00
89438	TC	B/4800 Rm 1505,1504,1422 - Too Cold	DFRC-B4800-FLOOR1	HVAC		0:30
89294	TC	4839 STILL TOO WARM IN LAST ROW AREA OF TRAILER/BLDG	DFRC-B4839	HVAC		11:00
89486	TC	4982 THERMOSTAT IN BATTERY ROOM IS INOPERABLE. IT SAYS LOW. SPECULATE IT NEEDS NEW AA BATTERIES. A/C IS NOT COMING ON AS NEEDED.	DFRC-B4982	HVAC		2:00
89509	TC	4823-205, 202 AND SURROUNDING AREA IS TOO WARM; 202 HAS NO AIR CIRCULATION AT ALL	DFRC-B4823	HVAC		1:00
89546	TC	4822 CLINIC - AIR CONDITIONING NOT COMING ON. NEEDS TO BE RESET DUE TO THE POWER GOING OUT OVER THE WEEKEND	DFRC-B4822-MEDICAL	HVAC		1:30
89526	TC	4825 ISF AUDITORIUM IS TOO WARM FOR LARGE GROUP MEETING	DFRC-B4825	HVAC		0:30
89612	TC	703-322 THE ROOM IS TOO WARM AT 79.6F	DAOF-B703	HVAC		1:00
89626	TC	703-241N AND 242N THE AIR CONDITIONING IS BLOWING HOT AIR	DAOF-B703	HVAC		0:30
89665	TC	B/4825 ISF - Too Hot	DFRC-B4825-POST1	HVAC		1:30
89367	TC	B/4822 - AC Unit Not Working	DFRC-B4822-MEDICAL	HVAC		1:00
89401	TC	4826 OFFICES TOO WARM, THERMOSTAT LOCATED OUT OF OFFICES IN HALLWAY AND READS 77F BUT THE OFFICE FEELS MUCH WARMER.	DFRC-B4826	HVAC		1:30
89414	TC	703-222 TOO COLD	DAOF-B703	HVAC		0:20
89532	TC	4825 POST 1 - A/C NOT RESPONDING	DFRC-B4825-POST1	HVAC		1:00
89584	TC	B4800 RM 2228,2227,2108,2111 Room temp 80	DFRC-B4800	HVAC		1:00
89635	TC	4800-2228, 2112, 2111 ARE ALL TOO WARM	DFRC-B4800-FLOOR2	HVAC		0:15
91675	TC	B/4800 Rm 1006 - Audible Alarm	DFRC-B4800-FLOOR1	HVAC		0:15
91680	TC	B/4824 - Fire Investigation & System Start Up	DFRC-B4824	HVAC		3:00
91491	TC	B/4800 - AC Unit Squealing	DFRC-B4800	HVAC		9:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

91501	TC	4820 SEVERAL ROOMS ON THE SECOND FLOOR ARE TOO WARM AND THE THERMOSTAT READS 80F - ROOMS: 204, 205, 206, 207, 208, 209	DFRC-B4820	HVAC		1:00
91693	TC	4841 THERMOSTAT INSTALLED 10/12/11HAS FAN ON CONSTANTLY AND MAKING THE AREA TOO COLD	DFRC-B4841	HVAC		0:00
91558	TC	B/4825 ISF - No Air Flow	DFRC-B4825-POST1	HVAC		0:30
91507	TC	4822 CLINIC A/C HAS NOT COME ON FOR THE DAY YET	DFRC-B4822-MEDICAL	HVAC		6:00
91461	TC	B/4846 - Too Hot	DFRC-B4846	HVAC		4:00
91697	TC	4809 ALL THE COOLERS ARE NOT WORKING	DFRC-B4809	HVAC		0:00
91514	TC	4840-239 AIR HANDLER IS MAKING A LOUD NOISE	DFRC-B4840	HVAC		3:00
91572	TC	B/4825 - Too Cold	DFRC-B4825-POST1	HVAC		0:30
91517	TC	B/4801 Rm 112A - HVAC Unit Leaking	DFRC-B4801	HVAC		0:55
91520	TC	B/4825 - AC Unit Noisy	DFRC-B4825	HVAC		4:00
91580	TC	B/4800 Rm 2108-2228- Too Hot	DFRC-B4800-FLOOR2	HVAC		0:30
91585	TC	4840-239 F-18 ROOM CRAC UNIT IS MAKING NOISE	DFRC-B4840	HVAC		18:00
91537	TC	4822 CLINIC - NO AIR CONDITIONING HAS COME ON AND IT IS 78F	DFRC-B4822-MEDICAL	HVAC		5:00
91540	TC	4843 A/C STILL BLOWING EVEN AFTER BEING TURNED OFF.	DFRC-B4843	HVAC		0:15
91586	TC	703-211 CONFERENCE ROOM GETTING TOO WARM DURING A MEETING	DAOF-B703	HVAC		0:30
91609	TC	B/4820 Rm 204 - Too Cold	DFRC-B4820	HVAC		2:00
91612	TC	B/4800 Rm 2407 - Too Cold	DFRC-B4800-FLOOR2	HVAC		0:30
91619	TC	4826 WATER GUSHING INTO EVAPORATIVE COOLER	DFRC-B4826	HVAC		0:30
91625	TC	4870 TOO WARM IN THE VAULT AT ABOUT 100F; A/C NOT WORKING WELL	DFRC-B4870	HVAC		0:00
91630	TC	4838-214 IS TOO COLD AT 70F AND THE ROOMS BELOW IT ARE TOO COLD AS WELL	DFRC-B4838	HVAC		0:30
91649	TC	703-322 TOO WARM AT 80F AROUND 9:00AM	DAOF-B703	HVAC		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

91652	TC	4800-2100 ECR IS TOO WARM DURING MEETINGS	DFRC-B4800-FLOOR2	HVAC		0:30
91665	TC	4800-1720 TOO WARM IN OFFICE; HVAC UNIT BLOWING HOT AIR	DFRC-B4800-FLOOR1	HVAC		0:00
93840	TC	703-322S TOO WARM AT 79°F	DAOF-B703	HVAC		1:00
93886	TC	703-S221 OFFICE IS TOO COLD DUE A CONSTANT BLAST OF COLD AIR BY THE AIR CONDITIONER	DAOF-B703	HVAC		0:00
93889	TC	4982 RATS NEST AND WASTE IN THE AIR CONDITIONER ON THE WEST SIDE OF THE BUILDING	DFRC-B4982	HVAC		0:00
93863	TC	4840-225 CRAC UNIT MAKING AREA TOO COLD	DFRC-B4840	HVAC		0:00
93864	TC	4877 ADJUST THE THERMOSTAT SO THE FAN IS RUNNING	DFRC-B4877	HVAC		0:00
93845	TC	4834 GUARD POST 2 REMOVE TEMPORARY AIR CONDITIONER	DFRC-B4834	HVAC		0:00
93847	TC	B/4800 Rm 1006 - Deliver Port AC unit / De-energize CRAC Units	DFRC-B4800-FLOOR1	HVAC		0:00
93815	TC	4985 A/C NOT BLOWING ANY AIR	DFRC-B4985	HVAC		0:00
93838	TC	4823 CHEM CRIB IS GETTING TO WARM AND IT FEELS LIKE THE FANS ARE OFF	DFRC-B4823	HVAC		2:00
93853	TC	4825 CAFETERIA ROBIN HOOD MAKE UP TABLE IS AT 48°-50°F; SEE GEMMA BURRESS x3689	DFRC-B4825	HVAC		0:00
65724	TC	B/703 - Floor Mopping	DAOF-B703	JAN		0:30
65773	TC	B/4800 Rm 2802 - Water extracted	DFRC-B4800-FLOOR2	JAN		4:00
65781	TC	B/703 Rm 332S - Vacuum	DAOF-B703	JAN		0:15
65720	TC	4800 PARKING LOT-BLOOD SPILL CLEAN UP	DFRC-B4800	JAN		1:00
68055	TC	B/4800 Rm 1013 - Carpet Shampooing	DFRC-B4800-FLOOR1	JAN		2:00
68058	TC	B/4800 - Sanitizer refills	DFRC-B4800-FLOOR1	JAN		0:15
68192	TC	4800-1731/1733 CONFERENCE ROOM-REMOVE A SPOT LEFT FROM A SODA POP SPILL; SEE KATE PAVLOCK (EXT 3363/ROOM 2134) FOR SPECIFICS	DFRC-B4800-FLOOR1	JAN		1:00
68054	TC	B/703 - Vacuum Office	DAOF-B703	JAN		0:20

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

68120	TC	4800-1413 LADIES ROOM FIRST STALL-CLEAN UP SOME BLOOD THAT IS ON THE FLOOR.	DFRC-B4800-FLOOR1	JAN		0:30
68122	TC	B/4840 Rm 216 - Cardboard boxes	DFRC-B4840	JAN		1:00
70066	TC	4802 HANGAR - ON 2/7/11 AT 7:30AM THERE WILL BE A BREAKFAST PARTY FOR ABOUT 200 GUESTS. ON 2/4/11 IN THE LATE AFTERNOON 3-4 VERY LARGE TRASH CANS NEED TO BE SET IN THE LOCATION IN PREPARATION THEN	DFRC-B4802	JAN		1:00
70166	TC	B/703 RM N122 - Mop and Dust	DAOF-B703	JAN		1:00
70311	TC	4833-104 CLEAN UP RODENTS AND/OR RODENT FECAL MATTER TAKING PROPER PROTECTIVE MEASURES.	DFRC-B4833	JAN		0:30
70136	TC	B/4810 - Remove residue/spill	DFRC-B4810	JAN		0:30
70172	TC	4800-2804 CLEAN UP SPILLED MEATLOAF	DFRC-B4800-FLOOR2	JAN		0:30
70186	TC	4876 NEED ANTIBACTERIAL REFILL IN OFFICE AREA OF BLDG	DFRC-B4876	JAN		0:30
72432	TC	4800-2215 LARGE MEZZANINE - ON THE FLOOR JUST OUTSIDE THE DOORWAY AND FOR A WAYS DOWN THE HALL THERE IS A TRAIL OF BLOOD DROPS THAT NEED TO BE CLEANED UP	DFRC-B4800-FLOOR2	JAN		0:30
72324	TC	4800-2213 LARGE MEZZANINE - CLEAN UP MESS FROM HVAC WORK; WILL NEED VACUUM AND RAGS FOR FALLEN INSULATION : THIS NEEDS TO BE COMPLETED BY 12:30PM ON 2/24/11	DFRC-B4800-FLOOR2	JAN		0:30
72461	TC	4840-107 OUTSIDE MENS ROOM ON HALL FLOOR SOMEONE GOT SICK AND IT NEEDS TO BE CLEANED UP.	DFRC-B4840	JAN		0:30
72512	TC	4800-2314 VACUUM UP SOME SPILLED TRASH	DFRC-B4800-FLOOR2	JAN		0:05
72532	TC	4800-2215 LARGE MEZZ - VACUUM FLOOR AND WIPE DOWN TABLES IN A COUPLE OF CONFERENCE ROOMS WHERE THE HVAC TECHS LEFT DUST AND A MESS FROM WORKING	DFRC-B4800-FLOOR2	JAN		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72355	TC	4820 SECOND FLOOR HALL WAY - SPILL NEEDS TO BE CLEANED UP; SLIPPING HAZARD	DFRC-B4820	JAN		0:30
74768	TC	703-331 EMPTY FULL RANCID TRASH CAN	DAOF-B703	JAN		0:15
75526	TC	703-222 WET CARPET NEEDS TO BE CLEANED UP	DAOF-B703	JAN		0:32
75350	TC	703-111 TRASH PICK UP	DAOF-B703	JAN		0:20
75518	TC	703-111 DAMP MOP DRIED SPILL ON FRIDAY 4/22/11 WHEN NO ONE IS IN OFFICE	DAOF-B703	JAN		1:30
75366	TC	B/4850 - Vacuum Toner	DFRC-B4850	JAN		0:30
75465	TC	4840 SECOND FLOOR COPIER ROOM - NEED JANITORIAL CLEAN UP OF SMOOTHIE SPILLED ON FLOOR	DFRC-B4840	JAN		0:30
75464	TC	4800-2100 NEED JANITORIAL CLEAN UP AFTER HVAC WORK	DFRC-B4800-FLOOR2	JAN		0:30
75329	TC	4876 MENS ROOM - AN AREA DIRTY IN THE MENS ROOM NEEDS TO BE CLEANED AGAIN	DFRC-B4876	JAN		0:30
75345	TC	703-134S SWEEP FLOORS IN LABS; SEE ZAHEER ALI FOR ACCESS x2567 OR 650-417-8405	DAOF-B703	JAN		1:00
79559	TC	4840-103 Clean a mess of packing material that is on the floor	DFRC-B4840	JAN		0:30
79651	TC	4800-2702 Nearby copier machine has spilled toner behind it and it needs to be cleaned up; copier will need to be moved to access the mess.	DFRC-B4800-FLOOR2	JAN		0:10
82025	TC	B/703 Rm 111 - Spill Clean Up	DAOF-B703	JAN		0:20
81739	TC	4840-112 mop up wet floor from roof leak	DFRC-B4840	JAN		0:30
81964	TC	703-111 empty gondola	DAOF-B703	JAN		0:20
84392	TC	4838 behind gem carts by yellow stripes on ground there is broken glass that needs to be cleaned up	DFRC-B4838	JAN		0:15
84181	TC	4825 support for Vendor's Fair - collecting trash from the isles to prevent tripping hazards, etc	DFRC-B4825-GIFT-SHOP	JAN		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

84395	TC	4825 ISF Auditorium- middle/center aisle carpet has a coffee stain that needs to be cleaned before a possible shuttle landing	DFRC-B4825	JAN		0:00
84361	TC	4800-2221 need gondola for extra trash and packing materials	DFRC-B4800-FLOOR2	JAN		1:00
86771	TC	4800-2225 VITS Room - grease stain on carpet	DFRC-B4800-FLOOR2	JAN		0:05
86885	TC	4810 WORK CONTROL LADIES ROOM TOILET NEEDS EXTRA CLEAN UP	DFRC-B4810	JAN		0:06
86993	TC	4800-2004 REMOVE USED PACKING BOXES	DFRC-B4800-FLOOR2	JAN		0:40
86989	TC	4809-19 sweep up room	DFRC-B4809	JAN		1:00
86668	TC	703-111 empty gondola, need tall trash bags, empty waste someone put in recycle bin	DAOF-B703	JAN		0:20
86943	TC	B/4800 Rm 1720 - Hallway Flooded	DFRC-B4800-FLOOR1	JAN		0:15
86680	TC	4810-Ali Morey's cubicle has rodent droppings and needs to be cleaned.	DFRC-B4810	JAN		0:05
86958	TC	4800-2228 SPILLED WATER NEEDS CLEANING UP	DFRC-B4800-FLOOR2	JAN		1:30
89615	TC	703-333 KITCHEN HAS SOME BROKEN GLASS THAT NEEDS TO BE CLEANED UP	DAOF-B703	JAN		0:10
89356	TC	4800-1115 MOP UP SPILLED WATER	DFRC-B4800-FLOOR1	JAN		0:15
89377	TC	703-SCC REMOVE LARGE AMOUNT OF UNPACKED BOXES	DAOF-B703	JAN		2:20
89590	TC	4820 WATER TUNNEL - CLEAN UP RODENT DEBRIS; COORDINATE WITH CLINT TO CLEAN _AFTER_ THE PEST CONTROL COMPANY VISITS THE WATER TUNNEL.	DFRC-B4820	JAN		0:00
89660	TC	4840-137 OFFICE NEEDS TO BE SWEEPED, DUSTED, AND HAVE THE TRASH REMOVED	DFRC-B4840	JAN		0:45
89576	TC	703-111 LAB NEEDS FLOOR MOPPED BY 9/15/11	DAOF-B703	JAN		1:15
89669	TC	B/4810 - Mouse Excrement Clean Up	DFRC-B4810	JAN		0:15
89574	TC	B 4800 RM 2404- Slip hazard	DFRC-B4800	JAN		0:10

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89580	TC	703A VCC WAS FLOODED SOME LEAVING THE CARPET A MESS AND IT NOW NEEDS SHAMPOOING	DAOF-B703A	JAN		1:00
91677	TC	B/4824 - Fire Clean Up	DFRC-B4824	JAN		3:00
91505	TC	B/4876 - Pest Control (Ants)	DFRC-B4876	JAN		0:20
91620	TC	4800-2701 SOUP SPILLED ON THE CARPET NEEDS TO BE CLEANED UP	DFRC-B4800-FLOOR2	JAN		4:00
91623	TC	4800-2213 LARGE MEZZANINE HAS TWO BAD SPOTS ON THE CARPET THAT NEED TO BE REMOVED IF POSSIBLE	DFRC-B4800-FLOOR2	JAN		2:00
91637	TC	B/4800 Rm 2143 - Vacuum & Dust	DFRC-B4800-FLOOR2	JAN		0:20
91654	TC	703-S332 MOP UP SPILLED COFFEE	DAOF-B703	JAN		0:15
93797	TC	B/4800 Rm 1732 - Grease on Carpet	DFRC-B4800-FLOOR1	JAN		0:15
65666	TC	4838-114 MENSROOM-CLOGGED SINK	DFRC-B4838	MECH		0:45
65593	TC	B/4820 Mens R/R - Sewer Smell	DFRC-B4820	MECH		0:30
65626	TC	4800-2327 and 2329 BAD CEILING LEAK	DFRC-B4800-FLOOR2	MECH		6:00
65638	TC	4820 TROUBLESHOOT RESTROOMS HOT WATER FAUCETS	DFRC-B4820	MECH		0:00
65661	TC	B/4802 - NorthWest Roll Up Door	DFRC-B4802	MECH		1:00
65664	TC	4831-NO WATER TO BLDG	DFRC-B4831	MECH		0:30
65676	TC	B/4824 - Clogged Sink	DFRC-B4824	MECH		1:30
65685	TC	4823 LADIESROOM LOCK INOP	DFRC-B4823	MECH		2:00
65581	TC	B/703 Sofia Maint. Ofc - Pest Control	DAOF-B703	MECH		0:10
65674	TC	4800-CHECK DOOR CLOSERS AND SWEEPS	DFRC-B4800-FLOOR1	MECH		4:15
65707	TC	4823 **URGENT** WATER COMING OUT OF MANHOLE COVER	DFRC-B4823	MECH		13:00
65640	TC	B/4982 - Urinal Running	DFRC-B4982	MECH		0:45
65667	TC	B/4800 West Roof - Roof Drains	DFRC-B4800	MECH		36:30:00
65743	TC	4800-2501 MENSROOM SINK CLOGGED	DFRC-B4800-FLOOR2	MECH		1:30
65732	TC	703-LOOSE CHAIN DRIVE TO VEHICLE GATE	DAOF-B703	MECH		0:00
65772	TC	B/4800 Rm 1413 - Clogged toilet	DFRC-B4800-FLOOR1	MECH		0:45
65783	TC	B/703 - Rain Leaks	DAOF-B703	MECH		0:00
65706	TC	4800**URGENT** NW EXTERIOR CORNER-SMELL OF GAS	DFRC-B4800	MECH		0:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

65759	TC	4833 MENSROOM EXHAUST FAN	DFRC-B4833	MECH		0:30
65680	TC	4800 REMOVE TARPS; REPLACE CEILING TILES	DFRC-B4800	MECH		9:15
65682	TC	4825 REMOVE TARPS; REPLACE CEILING TILES	DFRC-B4825-POST1	MECH		3:15
65742	TC	703-S142A NEED MORE MOUSE TRAPS	DAOF-B703	MECH		0:10
65572	TC	4820-101 VERY LEAKY SINK FAUCET	DFRC-B4820	MECH		5:30
65660	TC	FLIGHTLINE-OXYGEN SERVICING AREA	NASA-DRYDEN	MECH		2:00
65761	TC	4800-1412 CHANGE WATER FILTER	DFRC-B4800-FLOOR1	MECH		0:30
65574	TC	B/4826 - Toilet running	DFRC-B4826	MECH		0:30
65604	TC	4859-MENSROOM EXHAUST FAN DYING	DFRC-B4859	MECH		1:00
65608	TC	4847-ENTRYWAY DOOR SLAMMING SHUT; BAD CLOSER	DFRC-B4847	MECH		3:00
65678	TC	B/4800 Rm 1125 (Mens) - Toilet running	DFRC-B4800-FLOOR1	MECH		1:15
65733	TC	4800-1611 REPLACE DAMAGED TILE; TRIP HAZARD	DFRC-B4800-FLOOR1	MECH		4:00
65736	TC	4800-1729 TOILET SLOW FLUSHING	DFRC-B4800-FLOOR1	MECH		1:00
65716	TC	4800-2704 CABLE KNOCKING CEILING TILE DOWN	DFRC-B4800-FLOOR2	MECH		0:30
65717	TC	4809-CEILING LEAK IN LADIESROOM	DFRC-B4809	MECH		2:00
65584	TC	NASA (B/P300) - Disconnect Ice Machine	NASA-DRYDEN	MECH		1:30
65602	TC	B/4825 Cafe - Door repair	DFRC-B4825-GIFT-SHOP	MECH		0:00
65702	TC	T-20 LEAKING SINK	DFRC-T-20	MECH		0:45
65735	TC	4825 SECURITY-CLOGGED MENSROOM TOILET	DFRC-B4825-POST1	MECH		0:30
65758	TC	4833-100 CHECK DOOR CLOSER AND FLOOR TILE	DFRC-B4833	MECH		3:00
65752	TC	4840 "SIM ALLEY" DOORS NEED REPAIR- SECOND FLOOR	DFRC-B4840	MECH		0:00
65754	TC	4840-221 RIPPED CARPET; TRIP HAZARD	DFRC-B4840	MECH		0:45
65755	TC	4840-113C RIPPED CARPET; TRIP HAZARD	DFRC-B4840	MECH		0:15
65771	TC	4859-ELECTRICAL SMOKE SMELL FROM RESTROOM EXHAUST FAN	DFRC-B4859	MECH		1:45
65789	TC	4823-MACHINE SHOP-WATER LEAK FROM FLOOR	DFRC-B4823	MECH		1:00
65656	TC	703 NEED FIRE VAULTS PUMPED OUT	DAOF-B703	MECH		4:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

65692	TC	B/4800 - Outage #965 - 4" Water Line Repair	DFRC-B4800	MECH		6:00
65727	TC	4800- NO HOT WATER TO RESTROOM FAUCETS	DFRC-B4800-FLOOR1	MECH		2:30
65728	TC	4800-1421 INSTALL DRAIN PLUGS AND DRAIN COVER	DFRC-B4800-FLOOR1	MECH		3:30
65612	TC	4800-1413 MIDDLE FAUCET INOP	DFRC-B4800-FLOOR1	MECH		0:00
65613	TC	703-TOILET RUNNING	DAOF-B703	MECH		0:10
65617	TC	4825-REPLACE YELLOW PADS; SAFETY HAZARD	DFRC-B4825	MECH		4:00
65749	TC	4854-PULL TOILET & PLUG SEWER HOLE	DFRC-B4854	MECH		1:30
65777	TC	4840 BAY 6-CHECK AIR LINE FITTING	DFRC-B4840	MECH		0:30
65780	TC	4802-FLOOR DRAIN HAS VERY BAD ODOR; MAY NEED ENZYMES	DFRC-B4802	MECH		0:30
66253	TC	703 FABRICATION SHOP-WATER IN AIR LINE	DAOF-B703	MECH		0:00
67237	TC	4820 SUMP PUMP CLAMP CAME OFF PIPE; SPRAYING WATER EVERYWHERE	DFRC-B4820	MECH		1:00
68035	TC	4852 ROOF LEAK NEXT TO VENT	DFRC-B4852	MECH		0:00
68066	TC	4840 BAY 6-NEED MORE MOUSE TRAPS	DFRC-B4840	MECH		0:30
67982	TC	B/703 - Ramp Gate Inop	DAOF-B703	MECH		0:00
68077	TC	NB101 - Sewer Ejector Station #3	DFRC	MECH		22:00
68081	TC	4823 HM3-CONNEX DOOR WILL NOT OPEN	DFRC-B4823	MECH		0:30
68083	TC	4826 PROVIDE AN AIR FILTER REGULATOR FOR APPLYING SOME SEALANT; 35-55PSI NEEDED AT 90PSI PRESENTLY. WORK STOPPAGE. NEEDED ASAP	DFRC-B4826	MECH		0:30
67950	TC	4720-Please check the slide gate. The alignment seems to be off. It is not closing properly. Thank you.	DFRC-B4720	MECH		1:15
68023	TC	B/4820 - Overhead Crane inop	DFRC-B4820	MECH	1301005	1:00
67963	TC	B/4810 - Clogged drain	DFRC-B4810	MECH		15:45
68085	TC	4800-1418 MENSROOM-CHECK URINAL FURTHEST TO THE RIGHT; GUSHES WATER WHEN FLUSHED. SEE PEDRO IF UNSURE OF LOCATION.	DFRC-B4800-FLOOR1	MECH		2:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

68088	TC	4841 MENSROOM: RE-HANG THE PAPER TOWEL DISPENSER THAT HAS FALLEN OFF THE WALL	DFRC-B4841	MECH		0:45
68164	TC	4800-1806 SMELL BURNING/SMOKE-LIKE SMELL-MAYBE ELECTRICAL - IN THE AREA	DFRC-B4800-FLOOR1	MECH		0:30
68166	TC	703-N221 AND N233-REPAIR BASE COVING IN TWO ROOMS; CUSTOMER ALREADY HAS MATERIALS	DAOF-B703	MECH		0:00
68148	TC	4806 ANCHOR A CONTROL PANEL	DFRC-B4806	MECH		0:45
68149	TC	4800-1413 LADIES ROOM-CLOGGED TOILET	DFRC-B4800-FLOOR1	MECH		0:30
68171	TC	B/703 - N/E Hangar Door	DAOF-B703	MECH		7:30
67940	TC	4800-1016 sink faucet running intermittently	DFRC-B4800-FLOOR1	MECH		0:30
67990	TC	703-N233 REPAIR DOUBLE ENTRY DOORS; DOOR HAS BROKEN OR MISSING "PINS" SO IT CANNOT BE SECURED.	DAOF-B703	MECH		0:00
68057	TC	B/4823 Break Room - Sink Leaking	DFRC-B4823	MECH		1:30
68108	TC	4810 REPLACE BROKEN TOILET SEAT IN BACK RESTROOM	DFRC-B4810	MECH		0:30
68113	TC	4801 NE CORNER- CHECK PERSONNEL DOOR THAT IS STUCK OPEN	DFRC-B4801	MECH		2:45
67922	TC	4840 REPAIR RAIN GUTTER	DFRC-B4840	MECH		0:00
67960	TC	4839 LADIESROOM-TOILET NOT DRAINING WELL WHEN FLUSHED; OTHER TWO TOILETS BUBBLING WHEN IT FLUSHES.	DFRC-B4839	MECH		1:00
67967	TC	4800-2008 LADIESROOM HAS A CLOGGED TOILET	DFRC-B4800-FLOOR2	MECH		1:15
67968	TC	703-SCC REPLACE DOORSTOP THAT GOT KNOCKED OFF.	DAOF-B703	MECH		0:25
68009	TC	B/4825 - Handicap doors	DFRC-B4825-GIFT-SHOP	MECH		0:30
68050	TC	B/4826 Mens r/r - Exhaust Fan	DFRC-B4826	MECH		2:00
67909	TC	4801 NEED FITTING FOR COMPRESSED AIR	DFRC-B4801	MECH		1:30
67915	TC	4800-1418 MENSROOM-PAPER TOWEL DISPENSER	DFRC-B4800-FLOOR1	MECH		1:45
67919	TC	B/4823 - Shop Air Down	DFRC-B4823	MECH		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

68115	TC	703-N241 & N242 REPAIR SINGLE DOOR TO RM N241 AND DOUBLE DOORS AT RM N242	DAOF-B703	MECH		0:00
68129	TC	B/703 Rm 111S - Untangle Curtain	DAOF-B703	MECH		1:00
67947	TC	4800-3102 Mensroom-Please check a toilet that overflows when it is flushed. OR it may be the small restroom INSIDE room 3103. The note left on my desk was unclear. Thank you.	DFRC-B4800-FLOOR3	MECH		0:00
67949	TC	703-234N Please replace a door stop. See Kathleen for which door. Thank you.	DAOF-B703	MECH		0:00
67952	TC	4720 UPS Room-Please lay provisions to catch a rodent that seems to be inhabiting the room. This is of concern because the rodent may chew on wiring. Thank you.	DFRC-B4720	MECH		0:00
68101	TC	4800-1028 NEARBY DRINKING FOUNTAIN LEAKING DOWN BACK OF UNIT	DFRC-B4800-FLOOR1	MECH		1:45
68121	TC	4840 BAY 6 REPAIR TWO DOORS THAT ARE NOT WORKING PROPERLY. FIRST DOOR IS A PEDESTRIAN DOOR THAT IS HAVING PROBLEMS WITH IT'S PNEUMATIC CLOSER AND SETTING OFF AN ALARM IN SECURITY	DFRC-B4840	MECH		1:15
68103	TC	4865 SOUTH DOOR-REPAIR DOOR LOCK	DFRC-B4865	MECH		0:45
68175	TC	B/4850 - Repair Flush Valve	DFRC-B4850	MECH		0:15
68140	TC	4802-DRAIN SMELLS BADLY; MAY NEED ENZYMES	DFRC-B4802	MECH		0:30
68142	TC	4800-1714 CHECK A VIBRATION IN THE CEILING	DFRC-B4800-FLOOR1	MECH		0:15
67942	TC	4820 Ladiesroom: re-mount soap dispenser	DFRC-B4820	MECH		2:45
67945	TC	4800-2407 Please repair a roof leak. Thank you.	DFRC-B4800-FLOOR2	MECH		1:30
67965	TC	4840 BAY6-REPLACE A 2,000mL SOAP DISPENSER. SEE RAUL (JANITORIAL) FOR SPECIFICS.	DFRC-B4840	MECH		1:45
67969	TC	GUARD POST 2: RE-MOUNT AND ADJUST SENSORS ON GATE ARM	DFRC-B4834	MECH		4:00
67972	TC	4842-ROOF LEAK	DFRC-B4842	MECH		2:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

67995	TC	4852-PLEASE CHECK A GATE THAT IS OPENING AND CLOSING ON IT'S OWN. THIS STARTED ON 1/3/10 AND WAS LOCKED OUT. WHEN LEFT ON IT'S OWN THIS MORNING IT SEEMED FINE AT THE TIME	DFRC-B4852	MECH		0:30
68027	TC	4832 ODIN SIDE- CHECK A BAD ODOR THAT IS MAKING THE OCCUPANTS UNCOMFORTABLE	DFRC-B4832-COMPUTER-SUPPORT	MECH		4:15
68029	TC	4982 CHECK CONTINUOUSLY FLUSHING TOILET; CONCERN THAT IT MAY DRAIN THE BLDG'S WATER TANK	DFRC-B4982	MECH		1:00
68031	TC	703 SECOND FLOOR EAST MENSROOM-PUDDLE OF CLEAN WATER ON THE FLOOR; CANNOT TELL WHERE IT IS COMING FROM	DAOF-B703	MECH		1:00
67979	TC	B/703 - Flag stuck	DAOF-B703	MECH		0:00
67983	TC	B/703 - Repair vehicle gate	DAOF-B703	MECH		0:00
67992	TC	4800-SMALL MEZZANINE-THERE IS A DUCT-TAPED SECTION OF CARPET THAT HAS SEVERAL STRANDS NEEDING TO BE CUT AS THEY ARE A TRIP HAZARD.	DFRC-B4800-FLOOR2	MECH		1:00
68043	TC	4820 COMPRESSOR ROOM-REPAIR ROOF TO PREVENT RAIN LEAKS FROM WETTING THE COMPRESSORS OR ELECTRICAL CABINETS	DFRC-B4820	MECH		2:00
68147	TC	4800-1716 SPRAY NOZZLE NOT WORKING; FILTER UNDER SINK NEEDS TO BE CHANGED.	DFRC-B4800-FLOOR1	MECH		2:45
68178	TC	4840-216 CUBICLE 2-REPAIR KEYBOARD TRAY; THE TRAY IS DESIGNED TO PIVOT AS WELL AS RAISE AND LOWER. IT CAN BARELY MOVE.	DFRC-B4840	MECH		1:00
68179	TC	703-SCC REPAIR/REPLACE SINK FAUCET	DAOF-B703	MECH		1:00
67941	TC	4800-1013 window sill leaking and soaking drywall during rain	DFRC-B4800-FLOOR1	MECH		0:00
67944	TC	4800-1413 sink faucet running intermittently	DFRC-B4800-FLOOR1	MECH		0:30
67958	TC	Gate 11-Please check the gate. It is stuck open. Thank you. (Corrected - from Gate 12 to Gate 11)	DFRC-GATE-12	MECH		0:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

67981	TC	4838-210 CLOGGED AND OVERFLOWING TOILET	DFRC-B4838	MECH		0:45
67994	TC	4800-1029 REPLACE OLD BANNER WITH NEW ONE. SEE GABY IN RM 1029 FOR BANNER.	DFRC-B4800-FLOOR1	MECH		0:30
68015	TC	NASA Dryden__DE-ICE THE WALKWAYS AND ANY AREAS THAT MAY BE SLIP HAZARDS.	NASA-DRYDEN	MECH		1:20
68016	TC	4840-BAY5 BRING MOUSE TRAPS	DFRC-B4840	MECH		0:15
68067	TC	4809 REMOVE 2 CRUMBLED PARKING BLOCKS; FOD ISSUE	DFRC-B4809	MECH		0:30
68086	TC	B/703 2nd Fl R/R - Restore Restrooms	DAOF-B703	MECH		0:00
67936	TC	Gate 12-stuck half way open	DFRC-GATE-12	MECH		0:10
67977	TC	B/4810 - Clogged toilet	DFRC-B4810	MECH		0:30
68002	TC	4823-CHEM CRIB_COLLECT AND REMOVE SAND BAGS LEFT FROM LAST STORM; SEE CHRISSE URIAS.	DFRC-B4823	MECH		0:15
67924	TC	4820-113 MENSROOM SHOWER LEAK	DFRC-B4820	MECH		0:45
68091	TC	B/4859 Womens r/r - Toilet handle problem	DFRC-B4859	MECH		0:45
68137	TC	4800-1413 LADIESROOM-FIRST STALL HAS A CLOGGED TOILET	DFRC-B4800-FLOOR1	MECH		0:30
68004	TC	B/703 - Safety Repairs	DAOF-B703	MECH		0:00
68019	TC	4825 SECURITY-REPLACE MISSING CEILING TILE	DFRC-B4825-POST1	MECH		0:30
68116	TC	4800-2407 WATER SPOT ON CEILING THAT LOOKS WET; IT IS OVER SANDY'S DESK.	DFRC-B4800-FLOOR2	MECH		4:45
70116	TC	703 FOURTH FLOOR MEZZANINE - REPLACE INOPERABLE HOT WATER RECIRCULATING PUMP	DAOF-B703	MECH		1:05
70119	TC	703-N131D LIFE SUPPORT-NEED MOUSE TRAPS TO START; THE RODENTS ARE NESTING IN LIFE SUPPORT. THEY ARE ALSO EATING VERY PRICEY HIGH ALTITUDE FOOD	DAOF-B703	MECH		15:30
70090	TC	B/4800 Rm 2008 - Toilet not flushing	DFRC-B4800-FLOOR2	MECH		0:15
70093	TC	4820-109 MENSROOM NEEDS ENZYMES POURED DOWN THE DRAINS	DFRC-B4820	MECH		0:15
70137	TC	4840 REAR EXTERIOR - CHECK GAS SMELL	DFRC-B4840	MECH		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

70138	TC	4800-1125 MENS ROOM - TOILET OUT OF SERVICE DUE TO NO WATER	DFRC-B4800-FLOOR1	MECH		3:00
70181	TC	4840 BAYS 4 AND 5 - EXTERIOR SOUTH SIDE CHECK A CHEMICAL SMELL THAT IS SO STRONG IT OVERWHELMED A COUPLE OF OCCUPANTS	DFRC-B4840	MECH		0:15
70185	TC	4820-101 BREAK ROOM SINK CLOGGED ON SIDE OPPOSITE THE DISPOSAL; SEE GABY (JANITORIAL) FOR SPECIFICS	DFRC-B4820	MECH		1:00
70261	TC	4800-1016 LADIES ROOM - TOILET LEAKS AROUND BASE AT FLOOR WHEN FLUSHED; CHECKED AFTER WATER CLEANED UP	DFRC-B4800-FLOOR1	MECH		1:45
70027	TC	4820 ELEVATOR CEILING (METAL GRATE) HAS FALLEN	DFRC-B4820	MECH		0:45
70031	TC	703 SECOND FLOOR NORTH BREAK ROOM-HANG SOAP AND PAPER TOWEL DISPENSERS; SEE DEIDA FOR SPECIFICS	DAOF-B703	MECH		0:30
70052	TC	B/703 - Repair Hangar Door	DAOF-B703	MECH		1:00
70148	TC	4820 LADIES ROOM - AUTO FAUCET WHEN ACTIVATED SPRAYS BADLY UNDER THE SINK AND AT THE VALVE	DFRC-B4820	MECH		6:00
70291	TC	4857 MENS ROOM TOILET LEAKING ON FLOOR AT BASE SEAL WHEN FLUSHED	DFRC-B4876	MECH		2:15
70076	TC	703 SECURITY MAIN GATE - THE CHAIN IS LOOSE AND THE GATE IS HANGING IMPROPERLY; SECURITY IS WORRIED SOMETHING IS BROKEN AND THE GATE WILL BE COMPROMISED LEADING TO A VULNERABILITY IN SAFETY	DAOF-B703	MECH		1:00
70110	TC	B/4840 Bay 4 - Hangar Door	DFRC-B4840	MECH	4059002	3:30
70179	TC	4824 COMPRESSOR-REPLACE BROKEN PRESSURE GAGE AND BROKEN PRESSURE RELIEF VALVE	DFRC-B4824	MECH	401001	1:45
70189	TC	B/4800 Rm 1303 - Sink Leaking	DFRC-B4800-FLOOR1	MECH		2:00
70222	TC	703 AGE SHOP - CHECK ROLL UP DOOR; NOT WORKING PROPERLY	DAOF-B703	MECH		1:00
70167	TC	B/4848 - Replace door sweeps	DFRC-B4848	MECH		3:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

70228	TC	4823 CHEMICAL CRIB OFFICES - UNISEX RESTROOM HAS SLOW DRAINING OR CLOGGED SINK	DFRC-B4823	MECH		1:15
70252	TC	4830A BLDG LEAKED BADLY DURING LAST RAIN; NEED TO PREP FOR ONCOMING RAIN. OVER KELLY SNAP'S DESK THE LEAKS WERE THE WORST WHERE THERE IS A DIVIDE WITH THE KITCHEN ON THE OTHER SIDE	DFRC-B4830A	MECH		0:15
70143	TC	4825 SECURITY BREAK ROOM - REPLACE SEVERAL DAMAGED CEILING TILES; SEE DORIS KEELER FOR SPECIFICS	DFRC-B4825-POST1	MECH		6:00
70195	TC	4800-1016 LADIES ROOM HAS A TOILET CLOGGED AND IT WILL NOT FLUSH; THE TOILET IS TO THE LEFT WHEN ENTERING THE ROOM	DFRC-B4800-FLOOR1	MECH		0:15
70289	TC	4809 SHOP SINK HAS NO HOT WATER ANY MORE	DFRC-B4809	MECH		0:45
70100	TC	703 THIRD FLOOR SOUTHEAST MENS ROOM - CLOGGED SINK	DAOF-B703	MECH		1:05
70109	TC	4854 BROKEN GAS PUMP NOZZLE; UNLEADED GAS NOZZLE POPPED OFF TANK. NEEDS LOCK OUT/TAG OUT	DFRC-B4854	MECH		0:30
70188	TC	B/4800 Rm 1125 - Mens Restroom Urinal	DFRC-B4800-FLOOR1	MECH		0:15
70305	TC	4825 AMERICAN EATERY/ROBIN HOOD SERVICE AREA SINK(S) ARE LEAKING UNDERNEATH AGAINST THE WALL; SEE GEMMA BURRESS x3689	DFRC-B4825-GIFT-SHOP	MECH		2:00
70306	TC	4826 EXTERIOR SOUTHWEST DOOR IS NOT SECURING PROPERLY; LATCH AND STRIKE PLATE NOT MEETING	DFRC-B4826	MECH		0:30
70024	TC	4864 WATER LEAK AT AN EXTERIOR COMM ROOM DOOR; MAY BE A WATER HEATER.	DFRC-B4864	MECH		2:15
70036	TC	B/4850 - Faucet Repair	DFRC-B4850	MECH		4:15
70051	TC	703 URINAL LEAKING IN THE NORTHWEST MENS ROOM OF THE HANGAR	DAOF-B703	MECH		0:27

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

70102	TC	4820-123 "WATER TUNNEL" CHECK ROLL UP DOOR; THE DOOR IS SHAKY, IT CATCHES, AND MAY NEED LUBING. SEE KNUT ROEPEL (661-802-1567)	DFRC-B4820	MECH		1:00
70103	TC	4800-3103 CHECK A SINK DISPOSAL THAT SEEMS TO BE STUCK; OCCUPANTS CAN HEAR THE MOTOR BUT CANNOT TELL THE BLADE IS TURNING	DFRC-B4800-FLOOR3	MECH		0:30
70174	TC	4876 CHECK DOOR CLOSER ON PERSONNEL DOOR IN THE WAREHOUSE PART OF THE BLDG	DFRC-B4876	MECH		1:30
70286	TC	4838 EXTERIOR WHITE SIGN AND POST ARE READY TO BREAK IN THE WIND	DFRC-B4838	MECH		0:15
70303	TC	B/703- Repair Door Handle	DAOF-B703	MECH		0:45
70080	TC	4827 PIPE TO WASHING MACHINE IS LEAKING BADLY	DFRC-B4827	MECH		0:30
70124	TC	NASA Dryen-repair pothole on exit side between Guard Post #1 and stop sign (near the SR-71).	NASA-DRYDEN	MECH		1:30
70128	TC	703-S142A AND B - NEED FOUR THINGS: MOUSE TRAPS; ADJUST DOOR SWEEP ON HANGAR-SIDE DOOR; REPLACE DOOR SWEEP ON REAR DOOR. S142B DARYL TOWNSEND'S OFFICE:DOOR TO HANGAR NEEDS DOOR SWEEP	DAOF-B703	MECH		1:10
70129	TC	703 FIRST FLOOR SOUTH BREAK ROOM - UNDER-SINK WATER HEATER INOP	DAOF-B703	MECH		1:35
70157	TC	703 SAFETY RELATED -EAST END: 2ND, 3RD, AND 4TH FLOORS- REPAIR SIX DOOR SAFETY SECURITY BARS: SEE RALPH FOR MATERIALS	DAOF-B703	MECH		0:00
70171	TC	4800-1018 MENS ROOM HAS A VERY BAD ODOR THAT THE JANITOR CANNOT CLEAN AWAY. PERHAPS THE DRAINS NEED ENZYMES.	DFRC-B4800-FLOOR1	MECH		0:30
70223	TC	B/4800 Rm 1016 - Intermittent Faucet	DFRC-B4800-FLOOR1	MECH		1:00
70237	TC	703-341 BOB MEYER'S OFFICE HAS A FAUCET/SINK FILTER THAT NEEDS TO BE CHANGED: SEE BRIANA FOR SPECIFICS	DAOF-B703	MECH		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

70238	TC	4800-1729 LADIES ROOM - TOILET TO THE RIGHT SPLASHES UP QUITE HIGH WHEN FLUSHED SPRAYING ALL AROUND AND THE WALLS	DFRC-B4800-FLOOR1	MECH		0:30
70242	TC	NASA - Turnstile Checks	DFRC	MECH		3:45
70249	TC	703 SECOND FLOOR NORTH - FIVE DOORS NEED TO BE REPLACED. DOORS PROVIDED BY CODE O.	DAOF-B703	MECH		0:00
70268	TC	4830E ENTRY WAY DOOR BENT AT TOP HINGE PERHAPS DUE TO WIND; THE DOOR FRAME MAY BE BENT AS WELL	DFRC-B4830E	MECH		1:00
70282	TC	4810 REPLACE LEAKING VALVE IN KITCHEN CLOSET	DFRC-B4810	MECH		0:00
70296	TC	B/703 - Replace Compressor Valve	DAOF-B703	MECH	403005	1:00
70029	TC	4800-2120 AND 2108-IN ROOM 2120 A CEILING LEAK THAT WAS TAKEN CARE OF LEFT A SMUDGE ON THE WALL THAT NEEDS TO BE CLEANED UP. IT'S IN THE CORNER TO THE RIGHT. ROOM 2108 STILL HAS PLASTIC UP AND NEEDS	DFRC-B4800-FLOOR2	MECH		2:00
70273	TC	4800-1115 DOOR STICKING SO BADLY VISITORS THINK IT IS LOCKED	DFRC-B4800-FLOOR1	MECH		1:15
70285	TC	4810 secure the loose angle brackets that hold the wooden panels in place on the wind break at the north side entrance	DFRC-B4810	MECH		0:15
70072	TC	4852 A MANUAL ROLL-UP DOOR HAS A BROKEN LINK IN IT'S CHAIN AND CANNOT BE USED.	DFRC-B4852	MECH		1:00
70074	TC	703 NORTHEAST HANGAR - SMALL ROLL-UP DOOR NEEDS WEATHERSTRIPPING	DAOF-B703	MECH		3:00
70086	TC	4800-3305 MENS ROOM HAS A CLOGGED URINAL THAT OVERFLOWED AND SPILLED ONTO THE FLOOR	DFRC-B4800-FLOOR3	MECH		9:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

70231	TC	4840-144 MENSROOM - THIRD URINAL TO THE LEFT; AFTER THE FLOOR IS MOPPED AND THE URINAL IS FLUSHED A COUPLE OF TIMES A PUDDLE COLLECTS AROUND IT ON THE FLOOR. THIS REPEATS. THERE IS NO CLEAR SOURCE	DFRC-B4840	MECH		28:45:00
70232	TC	4810 CODE F LADIESROOM - THE TOILET IS CLOGGED	DFRC-B4810	MECH		0:30
70236	TC	703-S123B CHECK DOOR CLOSER	DAOF-B703	MECH		0:00
70293	TC	4825 SECURITY MENS ROOM - TWO TOILETS ARE CLOGGED.	DFRC-B4825-POST1	MECH		2:00
70091	TC	B/703 S/E end - Rpr door frame	DAOF-B703	MECH		0:15
70101	TC	4810 CHECK TOILET IN BACK DOCK; LEAKING SEALS AT WALL AND WHERE INCOMING WATER MEETS TANK. SEE BLANCA (JANITORIAL)FOR SPECIFICS	DFRC-B4810	MECH		4:00
70198	TC	703 EAST PARKING LOT-ROTO GATE ON THE WEST SIDE IS SPINNING FREELY AND LOCKING AT THE WRONG TIMES	DAOF-B703	MECH		4:05
70208	TC	4822 MEDICAL CLINIC- TWO RESTROOMS BACK FROM THE FRONT DESK THE TOILET SEEMS CLOGGED AS THE WATER RISES WITH EACH FLUSH	DFRC-B4822-MEDICAL	MECH		1:00
70257	TC	4810 CODE F MENS ROOM TOILET HAS BROKEN SEAT	DFRC-B4810	MECH		0:00
70258	TC	Flightline (Behind B/4820) Spotlight	DFRC-FLIGHTLINE	MECH		0:15
72312	TC	4820 EXTERIOR - NEAR THE COOLER CLOSEST TO BLDG 4800 THERE IS A BROKEN LATCH THAT NEEDS ATTENTION	DFRC-B4820	MECH		0:15
72412	TC	4802 CHECK HANGAR DOOR; NOT OPERATING CORRECTLY	DFRC-B4802	MECH		18:30
72429	TC	4876 CHECK A CANOPY IN THE LOT TO THE REAR OF THE BLDG; THE WIND IS TEARING IT OFF AND IT IS GETTING PROGRESSIVELY WORSE.	DFRC-B4876	MECH		1:30
72431	TC	4840 ENTRY WAY DOORS MALFUNCTIONING; MAY BE THE WIND	DFRC-B4840	MECH		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72434	TC	B/T-17 - Troubleshoot Doors	DFRC-T-17	MECH		0:15
72449	TC	703 SOUTHWEST END OF HANGAR; CHECK PERSONNEL DOUBLE DOORS. HYDRAULICS MAY NEED ADJUSTMENT	DAOF-B703	MECH		0:25
72348	TC	4800-1729 LADIES ROOM TOILET OVER-FLOWING	DFRC-B4800-FLOOR1	MECH		1:00
72435	TC	B/4802 - Repair Sign/Railing	DFRC-B4802	MECH		0:15
72446	TC	B/4830E -- Repair door	DFRC-B4830E	MECH		1:15
72464	TC	4809 A 6'x6' AREA OF FLOOR TILE IS COMING UP CREATING A TRIPPING HAZARD; LOCATED IN MAIN HALL	DFRC-B4809	MECH		2:00
72467	TC	4840-163 THERE IS A MINOR LEAK ABOVE A WATER HEATER BUT NEAR A POWER STRIP	DFRC-B4840	MECH		0:30
72469	TC	4864 PUT MOUSE TRAPS IN ALL OFFICE AREAS OF THE BLDG. SEE PHIL FOR ACCESS AND LOCATIONS	DFRC-B4864	MECH		1:00
72470	TC	4982 CHECK THE TOILET; IT IS RUNNING NON-STOP	DFRC-B4982	MECH		1:00
72325	TC	B/4800 Rm 1729 - Repair Sanitizer	DFRC-B4800-FLOOR2	MECH		1:00
72373	TC	4800-1016 LADIES ROOM TOILET CLOGGED	DFRC-B4800-FLOOR1	MECH		0:45
72403	TC	4833 RUPTURED PIPE IN MENS ROOM	DFRC-B4833	MECH		0:15
73621	TC	4808 NORTH DOOR LATCH GUARD COMING OFF	DFRC-B4808	MECH		0:30
73623	TC	GATE 5 - WHEELS ARE COMING OFF TRACK	DFRC-GATE-05	MECH		0:15
73627	TC	4800-2149 LADIES ROOM - FAUCET INOPERABLE; THIRD FAUCET FROM THE ENTRY DOOR	DFRC-B4800-FLOOR2	MECH		2:00
72318	TC	4820-120 A KNOB ON THE DOOR FROM EXTERIOR TO INTERIOR OF ROOM IS NOT WORKING; THE KNOB SPINS WITHOUT TURNING TO OPEN THE DOOR	DFRC-B4820	MECH		1:15
72329	TC	4850-110 CHANGE SINK FILTER	DFRC-B4850	MECH		0:45
72332	TC	NASA-Dryden ESCORT AF CIV. ENG. REP WHO WILL BE CHECKING FOR GAS LEAKS	NASA-DRYDEN	MECH		1:00
72335	TC	T-72 ROOF LEAK; REPAIR BEFORE RAIN. SEE DANNY FOR SPECIFIC LOCATION OF LEAK	DFRC-T-72	MECH		1:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72437	TC	B/4825 Cafe - Troubleshoot Doors	DFRC-B4825-GIFT-SHOP	MECH		0:00
72444	TC	B/4837 - Repair / Replace Roof Baffle	DFRC-B4837	MECH		0:00
72455	TC	B/703 - Repair Loose Panel	DAOF-B703	MECH		0:00
72564	TC	4840 FIRST FLOOR MENS ROOM - URINAL TO THE LEFT HAS BADLY LEAKING SUPPLY LINE THAT IS LEAKING DOWN AND ACROSS THE REST ROOM FLOOR	DFRC-B4840	MECH		0:15
72565	TC	4841 EXTEIROR; TO THE RIGHT SIDE OF THE ENTRANCE THERE IS A RAIN GUTTER DRAIN THAT HAS A LOOSE/BROKEN BRACE THAT MAY CAUSE THE DRAIN TO BECOME A SAFETY HAZARD	DFRC-B4841	MECH		0:15
72566	TC	4820 FIRST FLOOR MENS ROOM - THE FIRST TOILET WHEN WALKING INTO THE REST ROOM IS LEAKING BADLY AT THE BASE ON THE FLOOR; THE LEAK IS BAD AND NEEDS IMMEDIATE RESPONSE	DFRC-B4820	MECH		2:45
72569	TC	T-47 DRIPPING FAUCET IN KITCHEN SINK	DFRC-T-47	MECH		6:00
72356	TC	4810 LADIES TOILET NEXT TO WORK CONTROL IS CLOGGED AND WASN'T FLUSHING WELL BEFORE CLOG	DFRC-B4810	MECH		0:30
72413	TC	4800-3202 CHECK A "STIFF" DOOR THAT WILL NOT CLOSE ALL THE WAY VERY WELL AND THEREFORE CANNOT ENGAGE THE LYNX SYSTEM; CHECK THE LATCH IT IS NOT MOVING WITH THE TURNING OF THE DOOR KNOB	DFRC-B4800-FLOOR3	MECH		1:00
72415	TC	4840 BAY 6 - ROLL UP DOOR INOP	DFRC-B4840	MECH		0:00
72416	TC	4840 CHECK REAR EXTERIOR DOORS. THEY ARE NOT LATCHING AND THE WIND IS CAUSING PROBLEMS WITH THEM	DFRC-B4840	MECH		1:45
72419	TC	703 FIRST FLOOR SOUTH EAST LADIES ROOM SINK DRAINING SLOWLY	DAOF-B703	MECH		1:07
72420	TC	4839 WATER LINE BROKEN; WATER GOING ALL OVER	DFRC-B4839	MECH		10:00
72320	TC	4831 CHECK CLOSER ON ENTRY WAY DOOR; IT IS COMING OFF AND APART SO THAT IT MAY BECOME A SAFETY HAZARD SOON	DFRC-B4831	MECH		1:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72426	TC	4825 CAFETERIA FRONT DOOR - CHECK DOOR AS IT IS COMING APART; PERHAPS FROM THE WIND. SEE GEMMA BURRESS x3689 FOR SPECIFICS	DFRC-B4825-GIFT-SHOP	MECH		1:15
72485	TC	B/4800 Rm 1018 - Urinal Running	DFRC-B4800-FLOOR1	MECH		0:30
72563	TC	B4876 - Repair downspouts/gutters	DFRC-B4876	MECH		32:30:00
72509	TC	4810 REPLACE DOOR CLOSER ON DOOR GOING TO CODE F ON THE WEST SIDE ENTRY WAY	DFRC-B4810	MECH		1:30
72549	TC	4810 NORTH MENS ROOM NEAR CODE F - THE ENTRY DOOR TO THE MENS ROOM IS COMING OFF AT THE HINGES	DFRC-B4810	MECH		0:15
72552	TC	4854 REPAIR JPTS TANK	DFRC-B4854	MECH		0:00
72511	TC	4850 MENS ROOM - URINAL TO THE RIGHT RUNS FROM THE HANDLE STICKING "OPEN"; TOILET KEEPS CLOGGING FREQUENTLY AND MAY NEED TO BE SNAKED (THE STALL WITH THE PLUNGER IN IT)	DFRC-B4850	MECH		2:30
72528	TC	T-79 REPAIR ROOF LEAK; WATER STAINS SHOW WHERE THE RAIN SEEPS IN	DFRC-T-79	MECH		0:30
72501	TC	T-47 BREAK ROOM- REPLACE APPROX. SIX FLOOR TILES	DFRC-T-47	MECH		9:15
72502	TC	4840-242 MENS ROOM MIDDLE URINAL IS LEAKING WHEN FLUSHED; IT LEAKS AT THE HANDLE AND AT THE "SHOULDERS" WHERE THE NECK MEETS THE BODY OF THE URINAL	DFRC-B4840	MECH		1:45
72579	TC	4840-144 MENS ROOM - URINAL LEAKING AGAIN; THE LEAK IS UP AND OPPOSITE THE HANDLE, JUST SLOW DRIPPING BUT CONSTANT	DFRC-B4840	MECH		2:00
72407	TC	4800-2515 MENS ROOM FIRST TOILET HAS BECOME VERY NOISY WHEN FUNCTIONING	DFRC-B4800-FLOOR2	MECH		1:00
72321	TC	4876 DOOR KNOB TO BACK OFFICE DOOR IS NOT WORKING PROPERLY	DFRC-B4876	MECH		0:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72340	TC	4800 STAIRWELL 7 - THE STAIRWELL DOOR GOING TO THE SECOND FLOOR IS LOCKING WHEN SHUT SO THAT UPON EXITING THE SECOND FLOOR ONE CANNOT THEN RE-ENTER IT.	DFRC-B4800-FLOOR2	MECH		0:30
72388	TC	4846 REPOSITION KEYBOARD TRAY APPROX 6" TO THE RIGHT; CENTER THE TRAY	DFRC-B4846	MECH		0:30
72399	TC	4824 WATER LEAK ON DOMESTIC MAIN LINE TO THE LOT	DFRC-B4824	MECH		16:30
72402	TC	703 THIRD FLOOR EAST MENS ROOM HANDICAPPED STALL TOILET LEAKING FROM THE BACK OF THE TANK DOWN TO THE FLOOR	DAOF-B703	MECH		0:40
72423	TC	4840 TRASH OR RECYCLING RECEPTACLE NEAR DUMPSTERS HAS BLOWN OVER IN THE WIND AND HAS LET LOOSE A LOT OF FOD	DFRC-B4840	MECH		0:15
72424	TC	4800-1029 NEED DOOR SWEEPS PUT ON DOORS; OFFICE NEXT TO EXTERIOR DOORS AND SUBJECT TO RODENT, REPTILE, AND PEST ENTRY	DFRC-B4800-FLOOR1	MECH		0:30
73624	TC	703 THIRD FLOOR LADIES ROOM ADA STALL TOILET OVERFLOWING	DAOF-B703	MECH		0:25
72478	TC	B/4839 - Repair Door Latch	DFRC-B4839	MECH		0:30
72433	TC	4800-3305 MENS ROOM CHECK URINALS; WHEN ONE URINAL IS FLUSHED IT BACKWASHES UP THROUGH BOTH URINAL DRAINS.	DFRC-B4800-FLOOR3	MECH		3:00
72442	TC	B/4859 East Door - Door Won't Open/Close	DFRC-B4859	MECH		1:00
72450	TC	4800-1016 LADIES ROOM - OVERFLOWING TOILET	DFRC-B4800-FLOOR1	MECH		0:30
72534	TC	GATE 50 - WHEELS FELL OFF GATE	NASA-DRYDEN	MECH		7:00
72541	TC	4820 NEED AT LEAST 3 PACKS OF MOUSE TRAPS	DFRC-B4820	MECH		0:15
72542	TC	703 PUMP WATER OUT OF VAULTS	DAOF-B703	MECH		4:00
72543	TC	4825 NORTHEAST CORNER OF ROOF HAS A BACKED UP DRAIN LINE; ROOF FLOODED OVER CAFETERIA PART OF ROOF	DFRC-B4825	MECH		7:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72379	TC	4810 ADJUST DOOR TO HANG FLUSH WITH DOOR FRAME; DOOR NEAR WATER FOUNTAIN GOING TO KITCHEN AND CODE F	DFRC-B4810	MECH		2:30
72405	TC	703 TOOL CRIB - CHECK DIFFICULT DOOR KNOB ON DOOR GOING TO THE OFFICE AREA FROM THE WAITING AREA; SEE SCOTT OR DANIEL	DAOF-B703	MECH		0:25
72441	TC	B/4838 2nd Flr - Adjust Doors	DFRC-B4838	MECH		0:15
72453	TC	4800 THIRD FLOOR FAN DECK - DOOR NEEDS PLATE ON LATCH PART OF DOOR TO KEEP DOOR FROM BEING FORCED OPEN.	DFRC-B4800-FLOOR3	MECH		1:00
72476	TC	4800-3103 DOUBLE DOORS LEFT OF ELEVATOR ARE STIFF, DIFFICULT TO CLOSE, AND THE LATCH IS DIFFICULT ALSO; CHECK BEFORE REFERRING TO LOCKSMITH.	DFRC-B4800-FLOOR3	MECH		1:00
72477	TC	4800-2515 SECOND TOILET HAS A LEAK AT THE BASE ON THE FLOOR WHEN FLUSHED	DFRC-B4800-FLOOR2	MECH		3:00
72482	TC	4843 EXTERIOR - A "STOP AHEAD" SIGN NEAR THIS CONNEX IS ABOUT TO BECOME A WIND HAZARD. IT IS FLOPPING AROUND LIKE IT HAS BROKEN BOLTS	DFRC-B4843	MECH		1:30
72483	TC	4820 MENS ROOM (ONLY WORKING ONE DURING CONSTRUCTION) HAS A BROKEN, MANUAL, OLD BROWN PAPER TOWEL DISPENSER THAT NEEDS REPAIR OR REPLACEMENT	DFRC-B4820	MECH		1:00
72484	TC	703 THREE REPAIRS: 1) 2ND FL RM 220A LADIES ROOM THE FIRST TOILET SPRAYS WATER, 2) SW CORNER DOOR INTO THE HANGAR IS BLOCKED OPEN DUE TO A BENT PLATE, 3) INCOMING SPEED LIMIT SIGN COMING DOWN	DAOF-B703	MECH		1:45
72516	TC	4864 CHECK MICE TRAPS; DISPOSE OF MICE	DFRC-B4864	MECH		0:30
72524	TC	4720 TWO EXTERIOR DOORS, ONE DOUBLE AND ONE SINGLE, NEED TO HAVE DOOR SWEEPS AND WEATHER STRIPPING PUT ON THE DOORS	DFRC-B4720	MECH		4:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

72526	TC	4826 ROLL-UP DOOR WILL NOT CLOSE	DFRC-B4826	MECH		5:30
74195	TC	B/4840 Bay 3 - Hangar Door	DFRC-B4840	MECH	4059001	3:00
73995	TC	4808 LIFE SUPPORT - CHECK DOOR CLOSER ON ENTRY WAY DOOR; DOOR IS SLAMMING SHUT. SEE SEAN x3837	DFRC-B4808-LIFE-SUPPORT	MECH		1:45
74190	TC	4820 FIRST FLOOR BREAK ROOM - FAUCET DRIPPING CONSTANTLY	DFRC-B4820	MECH		1:45
74191	TC	4822 PSSF - ENTRY WAY DOOR IS STICKING AT THE TOP	DFRC-B4822-PSSF	MECH		1:15
74192	TC	4830C - REPLACE WET CEILING TILES; SEE MARIA OR TONY KAWANO	DFRC-B4830C	MECH		0:00
74801	TC	4840-156 CUBICLE 7 JESSICA PETERSON HAS A TRAY FOR HER COMPUTER MOUSE THAT NEEDS TO BE REMOVED FROM HER DESK.	DFRC-B4840	MECH		0:15
74802	TC	NB106 REMOVE AND REPLACE SEWER LID SO THE G-2 LAVATORY DUMP CART COULD BE EMPTIED.	DFRC-NB106	MECH		0:15
74803	TC	4838-201 PLUGGED DRAIN LINE ON CRAC UNIT	DFRC-B4838	MECH		1:30
74804	TC	4820 FLOOR DRAIN PLUGGED IN THE COMPRESSOR ROOM	DFRC-B4820	MECH		10:00
74794	TC	4800-2008 LADES ROOM HAS A CLOGGED TOILET	DFRC-B4800-FLOOR2	MECH		1:00
74761	TC	B/703 N/E Mens rm - Toilet running	DAOF-B703	MECH		0:20
74776	TC	703 INVESTIGATE NEED FOR RESTRICTED AIRFLOW/ PEST CONTROL WHERE DOORS AND ENTRY WAYS ARE CONCERNED; INCLUDING TAKING A COUNT OF DOORS THAT MAY NEED THIS ATTENTION	DAOF-B703	MECH		0:00
74779	TC	T-70 WATER LEAKING FROM UNDER EAST SIDE OF TRAILER	DFRC-T-70	MECH		4:30
74780	TC	4800 NEAR 1012 CHECK *EXTERIOR* DOOR NEAR CFO'S OFFICE; THE DOOR IS SLAMMING THOUGH THERE IS NO WIND. CHECK DOOR CLOSER.	DFRC-B4800-FLOOR1	MECH		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

74769	TC	4825 ISF AUDITORIUM - PICTURE HAS FALLEN PRECARIOUSLY ONTO A LEDGE AND IS A SAFETY ISSUE	DFRC-B4825-GIFT-SHOP	MECH		1:30
74770	TC	4800-3206 THE DOOR IS NOT SHUTTING PROPERLY; THE DOOR USUALLY SWINGS FREELY AND PULLS CLOSED ON IT'S OWN TO LATCH INTO THE LYNX SYSTEM. DOOR #3206	DFRC-B4800-FLOOR3	MECH		0:15
74800	TC	B/703 Rm S333 - Troubleshoot Water Filter	DAOF-B703	MECH		0:35
74773	TC	4810 "CODE F" MENS ROOM ON NORTH END OF BLDG HAS AN OVERFLOWING TOILET.	DFRC-B4810	MECH		0:30
74782	TC	4830 BLDGS A-E ASSESS ALL BLDGS FOR ROOF LEAK DAMAGE, CEILING TILE DAMAGE, FLOORING IN DISREPAIR, FOR PEST INFESTATIONS	DFRC	MECH		0:00
74765	TC	B/4800 RM 1418 - Toilet Running	DFRC-B4800-FLOOR1	MECH		0:15
75400	TC	703 VCC - WATER FILTRATION LIGHT ON	DAOF-B703	MECH		0:30
75426	TC	B 4830E-Please check the flooring in the unisex restroom. It is pulling up creating a tripping hazard. Thank you.	DFRC-B4830E	MECH		20:30
75425	TC	4800-1422 ONE SIDE OF THE ROOM SMELLS LIKE A RODENT DIED	DFRC-B4800-FLOOR1	MECH		0:45
75480	TC	4870 COVER OR CLOSE OFF THREE CONDUIT THAT ARE IN AN ELECTRICAL BOX IN THE KITCHEN AREA; LIKEWISE, UNDER THE FLOOR THERE ARE THREE CONDUIT THAT NEED TO BE SEALED. THIS IS FOR RODENT-PROOFING	DFRC-B4870	MECH		0:30
75519	TC	4825 CAFETERIA REST ROOM TOILET RUNNING	DFRC-B4825-GIFT-SHOP	MECH		0:30
75520	TC	703 SOUTHWEST STAIRWELL - THE ELEVENTH STEP FROM THE BOTTOM IS LOOSE CREATING A SAFETY HAZARD	DAOF-B703	MECH		1:40
75431	TC	4800-1714 DOUBLE DOORS HYDRAULIC CLOSER ALLOWING DOORS TO SLAM SHUT; SAFETY HAZARD	DFRC-B4800-FLOOR1	MECH		0:15
75359	TC	B/4800 - Handicap Door Jammed	DFRC-B4800-FLOOR1	MECH		5:45
75565	TC	B/703 Rm 141B - Troubleshoot Air line	DAOF-B703	MECH		0:35

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

75482	TC	703 ROOM NEXT TO ROOM 126 NEEDS SAFETY STRIP MARKING THE SWING PATTERN ON THE FLOOR	DAOF-B703	MECH		0:30
75497	TC	B/4809 - Open Manhole Cover	DFRC-B4809	MECH		0:15
75406	TC	NASA - Troubleshoot Pressure Relief Valves	DAOF	MECH		0:00
75416	TC	B/703 Mens R/R - Clogged Sink	DAOF-B703	MECH		0:00
75462	TC	4809 EXTERIOR EAST SIDE - PART OF RAIN GUTTER OVER DOOR IS COMING OFF; SAFETY HAZARD.	DFRC-B4809	MECH		2:30
75523	TC	4825 SEWER BACKED UP	DFRC-B4825	MECH		8:30
75502	TC	4876 ROLL-UP DOOR ON THE DOCK JERKS AND MAKES NOISE WHEN IT GOES ABOVE THE RED MARK.	DFRC-B4876	MECH		0:30
75503	TC	703 MAIN HANGAR DOORS - REPAIR CABLE BRACKET.	DAOF-B703	MECH		11:25
75525	TC	4825 THREE LEAKING SINKS; ONE AT ANTHONY'S PIZZA AND TWO AT AMERICAN EATERY	DFRC-B4825-GIFT-SHOP	MECH		2:00
75365	TC	B/4825 - Patio Doors - Troubleshoot & Repair doors	DFRC-B4825-GIFT-SHOP	MECH		0:30
75477	TC	703 S by Room 344 – ceiling tile needs to be placed back into position	DAOF-B703	MECH		0:10
75478	TC	703 2nd fl North/West by the restrooms – the door in the hallway needs to have the “safety zone” sticker placed stating which way the door opens to prevent a hazard.	DAOF-B703	MECH		0:30
75479	TC	703-332 and first floor breakroom - hang 3 posters; see Sandy	DAOF-B703	MECH		0:25
75372	TC	4840-226 WATER LEAKING FROM CEILING	DFRC-B4840	MECH		1:00
75382	TC	703 FIRST FLOOR NORTH SIDE BETWEEN SHEET METAL SHOP AND LIFE SUPPORT - MENS ROOM - SEVERAL TOILETS ARE NOT FLUSHING	DAOF-B703	MECH		0:30
75401	TC	4870 DISPOSE OF RODENT AND SET MORE TRAPS IN KITCHEN	DFRC-B4870	MECH		0:45
75404	TC	4825 SECURITY MENS ROOM - TWO BROKEN TILE CREATING TRIPPING HAZARD	DFRC-B4825-POST1	MECH		5:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

75534	TC	703 THIRD FLOOR WEST LADIES ROOM - MIDDLE STALL TOILET IS RUNNING	DAOF-B703	MECH		0:15
75304	TC	4822 WATER FOUNTAIN LEAKING; THE LEAK IS JUST BELOW THE DRAIN RUNNING DOWN TO THE FLOOR.	DFRC-B4822-MEDICAL	MECH		2:15
75305	TC	4838-105 DOOR HANDLE ON DOOR BETWEEN ROOMS 105 AND 106 IS BROKEN; PART COMES OFF IN YOUR HAND	DFRC-B4838	MECH		1:00
75307	TC	4800-1016 LADIES ROOM TOILET NOT FLUSHING	DFRC-B4800-FLOOR1	MECH		0:30
75322	TC	4840-242 MENS ROOM MIDDLE URINAL IS LEAKING WHEN FLUSHED; IT LEAKS AT THE HANDLE AND AT THE "SHOULDERS" WHERE THE NECK MEETS THE BODY OF THE URINAL	DFRC-B4840	MECH		0:30
75348	TC	700E - PUMP RAIN WATER OUT OF VAULTS INTO ADJACENT EVAPORATION POND	DAOF-B700E	MECH		4:30
75349	TC	703 NORTHWEST CORNER PERSONNEL DOOR HANDLE NOT WORKING	DAOF-B703	MECH		0:00
75351	TC	4800-1029 REPLACE OLD BANNER WITH NEW ONE. SEE GABY IN RM 1029 FOR BANNER.	DFRC-B4800-FLOOR1	MECH		0:15
75311	TC	4876 REPAIR INSULATION IN FRONT OF THE OFFICE AREA; SEE DEE FOR SPECIFICS.	DFRC-B4876	MECH		2:45
75361	TC	B/T-01 - Clogged toilet	DFRC-T-01	MECH		0:45
75446	TC	B703 - Test and Certify Gas Meter	DAOF-B703	MECH		13:15
75457	TC	4809 HISTORY OFFICE - DISPOSE OF TRAPPED RODENT AND SET MORE TRAPS	DFRC-B4809	MECH		0:05
75489	TC	T-1 CLOGGED TOILET; SEE SANDY GROOVER x5511	NASA-DRYDEN	MECH		0:45
75517	TC	703 SECOND FLOOR NORTH WEST NEAR ELEVATOR A CLOSET NEEDS A DOOR CLOSER; SEE BOB FOR SPECIFICS.	DAOF-B703	MECH		0:55
75556	TC	4825 SMOKING BUTT CAN	DFRC-B4825-POST1	MECH		0:15
75609	TC	4825 CAFETERIA - SEATING BOOTH IS LOOSE AND NAILS ARE EXPOSED; SAFETY ISSUE. SEE GEMMA x3689 FOR SPECIFICS	DFRC-B4825-GIFT-SHOP	MECH		3:00
75553	TC	B/4801 - Repair Leaking Urinal	DFRC-B4801	MECH		2:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

75568	TC	4810 SET MOUSE TRAPS IN TECIA SMALLING'S OFFICE AND SURROUNDING AREAS	DFRC-B4810	MECH		1:00
75330	TC	703 PERSONNEL DOOR NEAR THE U2 - CHECK DOOR CLOSER; WIND CAUGHT THE DOOR AND THE DOOR DAMAGED THE CARD READER. CHECK INTO TAKING PREVENTATIVE MEASURES TO AVOID A REPEAT	DAOF-B703	MECH		0:25
75334	TC	4840-107 CHECK EXHAUST FAN, APPEARS INOPERABLE	DFRC-B4840	MECH		0:45
75507	TC	B703 - Outage #1036 - Domestic Water Leak Repair	DAOF-B703	MECH		0:00
75516	TC	4800-1012 DOOR SQUEAKS LOUDLY	DFRC-B4800-FLOOR1	MECH		0:15
75299	TC	4801 MENS ROOM - PAPER TOWEL DISPENSER FELL OFF THE WALL.	DFRC-B4801	MECH		1:00
75383	TC	4801 LADIES ROOM - LEFT STALL - TOILET LEAKING AT BASE	DFRC-B4801	MECH		2:00
75522	TC	4825 SECURITY LADIES ROOM TOILET AND BREAK ROOM TOILET NOT WORKING CORRECTLY	DFRC-B4825-POST1	MECH		1:15
75530	TC	B/703 - Hangar Door Repair	DAOF-B703	MECH		7:30
75396	TC	4800-1511 CODE A CONFERENCE ROOM - VERY LARGE WHITE BOARD LOOSE ON THE RIGHT SIDE AND COMING DOWN; CREATING A SAFETY ISSUE	DFRC-B4800-FLOOR1	MECH		1:30
75397	TC	4800-1409 FLOOR DRAIN NEEDS ENZYMES	DFRC-B4800-FLOOR1	MECH		0:30
75405	TC	NASA - Troubleshoot Pressure Relief Valves	DFRC	MECH		15:00
75408	TC	DAOF - Replace Flag Pole Rope	DAOF	MECH		2:50
75427	TC	703 FIRST FLOOR SOUTH WEST WOMENS REST ROOM CENTER STALL TOILET CLOGGED	DAOF-B703	MECH		0:30
75595	TC	703 MEDICAL OFFICE - CHECK FAUCET WATER; COMING OUT BROWN WITH LOTS OF AIR	DAOF-B703	MECH		0:15
75297	TC	4857 DISPOSE OF RODENT AND RESET MORE TRAPS	DFRC-B4857	MECH		0:05
75395	TC	4826 CHECK "PROPANE" SMELL IN RESTROOM	DFRC-B4826	MECH		9:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

75316	TC	B/4838 Rm 212A - Door repair	DFRC-B4838	MECH		0:45
75555	TC	4800-1422 ONE SIDE OF THE ROOM SMELLS LIKE A RODENT DIED ESPECIALLY IN THE SUPPLY ROOM; SEE MAIKEYZA FOR SPECIFICS	DFRC-B4800-FLOOR1	MECH		1:30
75574	TC	4800-1418 SHOWER HEAD IS LEAKING BADLY AND CANNOT BE TURNED OFF	DFRC-B4800-FLOOR1	MECH		0:30
75448	TC	B/4840 Bays 1-3 - Faucet Repair	DFRC-B4840	MECH		5:00
75481	TC	4827 REPLACE BROKEN HASP ON DOORS AT SOUTH END OF BUILDING.	DFRC-B4827	MECH		0:15
75313	TC	4840 CHECK SWARMING BEES; THEY SEEM TO BE IN THE FRONT MOSTLY.	DFRC-B4840	MECH		2:15
75498	TC	4810 NORTH MENS ROOM - EXHAUST FAN BLOWING AIR IN NOT OUT	DFRC-B4810	MECH		0:30
75500	TC	4833-100 INSTALL AUTO DOOR SEAL ON BOTTOM OF DOOR	DFRC-B4833	MECH		0:45
75569	TC	B/4840 2nd Fl - Door Handle	DFRC-B4840	MECH		0:30
75342	TC	4825 CAFETERIA - SET LARGE CLOCK TO DAYLIGHT SAVINGS	DFRC-B4825-GIFT-SHOP	MECH		0:30
75411	TC	703-N131 A-E: PUT DOOR SWEEPS ON ALL LIFE SUPPORT DOORS ESPECIALLY THE EXTERIOR DOORS TO KEEP RODENTS OUT.	DAOF-B703	MECH		0:50
75413	TC	703 SOUTHWEST ELEVATOR PHONE NEEDS TO HAVE BROKEN RECEIVER BUTTON CHECKED	DAOF-B703	MECH		1:00
75439	TC	4876 REPLACE A DOOR STOP THAT HAS COME OFF A DOOR INTO THE WAREHOUSE	DFRC-B4876	MECH		0:15
75443	TC	4870 DISPOSE OF DEAD RODENT	DFRC-B4870	MECH		0:15
75449	TC	703-VCC REPAIR POTHOLE AS SOON AS POSSIBLE AS IT IS A HAZARD AND LIKELY TO INCREASE IN SIZE	DAOF-B703	MECH		0:00
75434	TC	703-221B SOUTH SIDE - REPAIR/REPLACE DOOR STOP	DAOF-B703	MECH		1:27
75508	TC	B703 - (Outage # 1036) Isolation Valve Repair	DAOF-B703	MECH		0:00
75510	TC	4825 CAFETERIA AMERICAN EATERY - LEAKING FAUCET	DFRC-B4825-GIFT-SHOP	MECH		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

75549	TC	4822 REPAIR UNDER EAVES WHERE THERE ARE SOME GAPS; WASPS ARE GETTING IN THROUGH THE EAVES	DFRC-B4822	MECH		0:45
76984	TC	4824 NORTHEAST EXTERIOR DOOR HANDLE IS TURNING BUT WILL NOT OPEN THE DOOR	DFRC-B4824	MECH		1:30
78233	TC	4800 NORTHEAST EXIT - TRASH CAN ON FIRE; SECURITY CALLED THIS IN	DFRC-B4800	MECH		0:05
78998	TC	4800 REMOVE PINE NEEDLES FROM DRAINS AROUND BLDG	DFRC-B4800	MECH		0:30
78993	TC	4870 FIRBERGLASS SAFETY RAIL IS MISSING A CENTER SUPPORT	DFRC-B4870	MECH		2:45
79263	TC	B/4838 Rm 212A - Dead Animal Smell	DFRC-B4838	MECH		0:45
79400	TC	Gate 7 - Check bolt/nut that have fallen out of gate and caused the gate to fall on someone; the customer suggested a longer bolt and or a lock and key mechanism.	DFRC-GATE-07	MECH		4:00
79555	TC	4845 Check pot hole at the side rear of the bldg; may be sink hole	DFRC-B4845	MECH		1:15
79564	TC	703-140B Ladies room sink is leaking from the base	DAOF-B703	MECH		0:00
79565	TC	703-140A Hallway door that swings out needs swing pattern taped onto floor	DAOF-B703	MECH		0:10
79566	TC	703 Change all sink filters in the building; see Ralph for the filters	DAOF-B703	MECH		0:35
79401	TC	4810 Check mouse traps for rodents; Customer smells bad odor but cannot find the source.	DFRC-B4810	MECH		0:05
79402	TC	4825 Cafeteria - Rear exterior door need sweep to keep out rodents	DFRC-B4825-GIFT-SHOP	MECH		5:30
79403	TC	4825 Auditorium - Glass door on left side of opening and facing the parking lot has a loose bolt on the push bar. The push bar will come off when used exposing hardware creating a safety hazard	DFRC-B4825	MECH		0:15
79430	TC	4879 Kay & Assoc shop in Area A - Roll-up door not staying up when opened	NASA-DRYDEN	MECH		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

79431	TC	4820 Water pump between two evaporative coolers has come loose and is spraying water all over	DFRC-B4820	MECH		1:30
79432	TC	4800-2204 Mens room near mezzanines - paper towel dispenser dispensing towel segments that are too large and using towel rolls too quickly	DFRC-B4800-FLOOR2	MECH		0:15
79433	TC	4800-2501 Mens room toilet has a loose seat	DFRC-B4800-FLOOR2	MECH		0:15
79579	TC	703-123S Tool Crib door to office area is not working correctly	DAOF-B703	MECH		1:00
79638	TC	B/T-47 Mens Room - Toilet Overflowing	DFRC-T-47	MECH		1:00
79652	TC	4859 East door has not cover over closer; the cover is in the 747 office	DFRC-B4859	MECH		0:30
79653	TC	4859 West door is sticking	DFRC-B4859	MECH		0:15
79388	TC	4840-232 Vault door not opening correctly, too slow, has to be finished manually; same for closing and locking. See Bob for specifics.	DFRC-B4840	MECH		7:15
79592	TC	703 Northwest Hangar mens room has a clogged toilet	DAOF-B703	MECH		0:25
79604	TC	4800-2149 No water in Ladies room toilet	DFRC-B4800-FLOOR2	MECH		0:30
79610	TC	4720 Very bad smell	DFRC-B4720	MECH		0:00
79614	TC	Gate 51 - Sign	DFRC-GATE-51	MECH		0:45
79626	TC	703 Second floor northwest ladies room - repair falling shelf in stall	DAOF-B703	MECH		0:30
79620	TC	703-S142A Water leaking from undetermined source creating puddle on floor	DAOF-B703	MECH		1:20
79470	TC	4800-1413 Ladies room - middle stall toilet is running badly	DFRC-B4800-FLOOR1	MECH		0:15
79473	TC	4809 Mens room urinal running	DFRC-B4809	MECH		0:15
79475	TC	4800-1728 Check a couple of keyboard trays; see Kelly for specifics	DFRC-B4800-FLOOR1	MECH		1:45
79520	TC	703 Electronics Shop area - check air leak on isolation valve flange	DAOF-B703	MECH		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

79521	TC	Gate 50 - Check gate as it keeps coming off the tracks	NASA-DRYDEN	MECH		0:15
79522	TC	4824 Remove empty birds' nest from interior and then repair the whole in the wall that let the birds in; see Justin for specifics.	DFRC-B4824	MECH		0:00
79518	TC	4720 Need a door stop or some solution to the wind blowing the door and breaking the card reader.	DFRC-B4720	MECH		1:00
79443	TC	4825 Security break room rest room has clogged overflowing toilet.	DFRC-B4825-POST1	MECH		0:30
79637	TC	B/4826 - (Outage #1091) Troubleshoot Domestic Water Line	DFRC-B4826	MECH		14:15
79132	TC	4821 REMOVE OR FLATTEN PROTRUDING OBJECTS THAT MAKE FOR A TRIPPING HAZARD; SEE LEONARD FOR SPECIFICS. NOTE ATTACHMENTS	DFRC-B4821	MECH		2:00
79427	TC	B/703 S/E Mens Rm - Ceiling Repair	DAOF-B703	MECH		0:00
79573	TC	Gate 9 - Card reader box was knocked off of its post	DFRC-GATE-09	MECH		0:45
79619	TC	4810 Code F Tecia Smalling's office has a dead rodent that needs to be disposed of; she needs her traps reset	DFRC-B4810	MECH		0:30
79633	TC	703 Two toilets running - 1st floor northeast mens room ADA stall toilet and 2nd floor northwest ladies room first stall toilet	DAOF-B703	MECH		0:00
79534	TC	703-S332G Replace a wheel/castor on a conference table	DAOF-B703	MECH		0:20
79535	TC	4800-1729 Ladies room toilet is not flushing well as it takes several times to finish up	DFRC-B4800-FLOOR1	MECH		0:15
79386	TC	4800-1029 REPLACE OLD BANNER WITH NEW ONE. SEE GABY IN RM 1029 FOR BANNER.	DFRC-B4800-FLOOR1	MECH		0:30
79602	TC	4801-112 Room has a roof leak; need to go through room 113 to get to leak in 112	DFRC-B4801	MECH		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

79625	TC	703 Tool crib - Troubleshoot controllers for overhead crane Unit #E; See Tim for specifics	DAOF-B703	MECH		1:00
79646	TC	703 Second floor northwest mens room has a clogged sink	DAOF-B703	MECH		7:40
79660	TC	4876 Mens room exhaust fan inoperable	DFRC-B4876	MECH		2:00
79680	TC	4800 Second floor mens room faucet are slow to produce water; may need batteries	DFRC-B4800-FLOOR2	MECH		1:30
79255	TC	4800-1413 LADIES ROOM - ONE OF THE TOILETS FLUSHES SO THAT THE WATER SPLASHES VERY HIGH AND GETS ALL OVER	DFRC-B4800-FLOOR1	MECH		0:15
79509	TC	B/4800 Rm 2149 - Toilet Running	DFRC-B4800-FLOOR2	MECH		0:45
79679	TC	4800-1123 Mens room in room 1123 needs faucets checked as they take a long time to produce water; may need batteries	DFRC-B4800-FLOOR1	MECH		1:00
79682	TC	B/4800 Rm 1418 - Toilet Seat	DFRC-B4800-FLOOR1	MECH		0:45
79594	TC	703 Second floor North Ladies room ADA stall toilet will not flush	DAOF-B703	MECH		0:30
79481	TC	703 Tool crib door not working properly	DAOF-B703	MECH		0:35
79613	TC	4863 Need mouse traps set	DFRC-B4863	MECH		0:15
79657	TC	4800-1413 Ladies room has a clogged toilet	DFRC-B4800-FLOOR1	MECH		0:30
79526	TC	4800-2516 Mens room toilet leaking at auto flush valve	DFRC-B4800-FLOOR2	MECH		2:00
79378	TC	B/703 S/W - Phone non-op in elevator	DAOF-B703	MECH		0:40
79507	TC	703 Second floor north mens room middle stall toilet is running	DAOF-B703	MECH		0:20
79598	TC	4810 Tecia Smalling's office needs more mouse traps set since none were after the last catch	DFRC-B4810	MECH		0:15
79600	TC	4800-1734 The door by Tom Grindles office has a loose hydraulic mechanism	DFRC-B4800-FLOOR1	MECH		0:30
79415	TC	B/4854 - Fuel Station Inop	DFRC-B4854	MECH		1:00
79436	TC	B/4810 - Clogged Sink	DFRC-B4810	MECH		9:15
79616	TC	B/4826 - Shop Air	DFRC-B4826	MECH		0:30
79618	TC	4826 Evaporative cooler #6 - Repair leaking backflow device	DFRC-B4826	MECH	305040	4:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

79636	TC	B/703 - Mens Room - Clogged Sinks	DAOF-B703	MECH		2:00
79647	TC	4838 Auto roll-up door will not go down after collision though it did go up	DFRC-B4838	MECH		5:15
79683	TC	"A" Area - Replace Stop Sign	DFRC	MECH		2:00
79710	TC	B/4825 - Rotogate Inop	DFRC-B4825-GIFT-SHOP	MECH		1:00
81682	TC	B/703 - Troubleshoot lack of water pressure	DAOF-B703	MECH		0:00
81627	TC	4867 portable eyewash is loosing air	DFRC-B4867	MECH		0:30
81653	TC	B.4870 Water heater inop	DFRC-B4870	MECH		3:00
81674	TC	4720 broken hinge on door to generator	DFRC-B4720	MECH		1:30
81683	TC	Gate 9 - Troubleshoot gate	DFRC-GATE-09	MECH		0:15
81656	TC	4840 Drinking Fountain on 2nd floor is making noise	DFRC-B4840	MECH		1:00
81657	TC	Conference Room A & B room divider is hard to operate	DFRC-B4840	MECH		4:00
81658	TC	building 703- repair/replace wall mounts in SCC Room	DAOF-B703	MECH		1:10
81659	TC	Building 703 North East Restroom exhaust fan is out	DAOF-B703	MECH		0:00
81677	TC	4800-1018 or 1418 mens room - water is not coming out of faucet easily; may need batteries. In mens room 1418 glue down veneer on countertop that is coming up.	DFRC-B4800-FLOOR1	MECH		1:15
81679	TC	4800-1812 check around handle on first toilet. Janitorial staff repeatedly finds toilet paper wrapped around the handle as though there were a leak.	DFRC-B4800-FLOOR1	MECH		0:30
81885	TC	4810 back shop urinal is leaking and needs repair	DFRC-B4810	MECH		0:30
81810	TC	T-16 troubleshoot instant water heater that is corroded. Repair/replace as needed.	DFRC-T-16	MECH		3:00
81841	TC	B/4801 Ladies R/R - Toilet Running	DFRC-B4801	MECH		5:30
81934	TC	DAOF - Troubleshoot/Repair Sinkhole	DAOF-LAND	MECH		0:00
81948	TC	4839 propane smell in ladies room	DFRC-B4839	MECH		1:15
82011	TC	Sewer Ejector #4 - Troubleshoot, Repair /Replace Board	DFRC-NB100	MECH	31260232	0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

82013	TC	4825 wire mesh above patio seating has feathers, dead chicks, nesting birds above where there is eating and walking customers	DFRC-B4825-GIFT-SHOP	MECH		3:00
82022	TC	4800-1027 check a leak in the room	DFRC-B4800-FLOOR1	MECH		2:30
81990	TC	4876 change out mice traps that are full and set up new ones	DFRC-B4876	MECH		1:30
82024	TC	B/4809 - Reconnect Parts Washer	DFRC-B4809	MECH		2:00
82209	TC	4801 paper towel dispenser does not work even after changing batteries	DFRC-B4801	MECH		2:30
82113	TC	4800-2701 water soaked tile has fallen from the ceiling	DFRC-B4800-FLOOR2	MECH		1:30
82115	TC	Gate 8 is not opening	DFRC-GATE-08	MECH		0:15
81890	TC	703-S121 break room needs two sweeps placed one on each of the doors	DAOF-B703	MECH		0:00
82216	TC	703-S142A need a couple of packs of mice traps set up throughout the office	DAOF-B703	MECH		0:10
82205	TC	Gate 5 opened but did not close at the proper interval - after some delay it finally closed	DFRC-GATE-05	MECH		5:15
82170	TC	4827 drain pipe in wall for washing machine seems clogged as water is backing up and out of the drain	DFRC-B4827	MECH		0:30
82213	TC	B/4801 - Bad Odor	DFRC-B4801	MECH		0:45
81706	TC	B/4826 - Water Leak	DFRC-B4826	MECH	305042	5:15
81715	TC	B/703 - Sink Filtration	DAOF-B703	MECH		1:25
81760	TC	MDD - Sewer Line Leaking	DFRC	MECH		15:30
81681	TC	4801 Restroom water heater lines are rusting	DFRC-B4801	MECH		4:30
81693	TC	4832 cannot access dead rodent behind storage; need help	DFRC-B4832-COMPUTER-SUPPORT	MECH		0:30
81694	TC	703 south west second floor ladies room middle toilet is leaking	DAOF-B703	MECH		1:30
81695	TC	703 north east first floor hangar mens room the water is shut off on the ADA stall toilet	DAOF-B703	MECH		0:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

81703	TC	4800-2221 VITS room - small but very wet area on the floor looks like it has become wet from beneath or from the side and needs troubleshooting	DFRC-B4800-FLOOR2	MECH		0:15
81631	TC	The floor drain in Bldg 4840, Hanger 4 & 5 is plugged and backing-up onto the floor area in a walkway – this could cause someone to slip and fall. The drain is by the hand washing sink as soon as you	DFRC-B4840	MECH		7:00
81756	TC	B/4840 Bay 1 - Faucet Repair	DFRC-B4840	MECH		1:00
81758	TC	B/703 New Sci Lab - Remove Striping	DAOF-B703	MECH		0:15
81633	TC	4846 water heater in mens room is rusty and leaky	DFRC-B4846	MECH		2:30
81638	TC	4832 dispose of trapped rodents and reset traps or set new ones	DFRC-B4832-COMPUTER-SUPPORT	MECH		0:10
81639	TC	4810 Check ceiling tiles near Fire Tech Lead's office	DFRC-B4810	MECH		1:45
81640	TC	703 Hangar door loosing weather/rubber stripping; See Gary for specifics	DAOF-B703	MECH		1:40
81641	TC	4851 Entry way ceiling tile is broken in half and needs to be replaced	DFRC-B4851	MECH		0:30
81666	TC	4850 set mice traps throughout the building	DFRC-B4850	MECH		0:30
81803	TC	4825 Security COMM room door is on a card reader and not shutting all the way.	DFRC-B4825-POST1	MECH		0:30
81805	TC	4840 second floor ladies room sink has a puddle underneath and the origin of it is unclear	DFRC-B4840	MECH		0:30
81908	TC	4833 mens room ADA toilet is leaking badly at the tile	DFRC-B4833	MECH		1:00
81869	TC	703 place administrative lock out/tag out on blower control	DAOF-B703	MECH		0:00
81891	TC	703-N131D rest room has an overflowing toilet	DAOF-B703	MECH		0:00
81897	TC	4800-1409A office needs several mouse traps set throughout area	DFRC-B4800-FLOOR1	MECH		0:30
81902	TC	4824 rear door strike plate is missing a screw	DFRC-B4824	MECH		0:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

82218	TC	4820-204 outside of office is a leaking drain pipe	DFRC-B4820	MECH		2:00
81762	TC	703-N233 reinstall missing door and replace handle hardware as required.	DAOF-B703	MECH		2:10
82020	TC	4800-1724 office needs mice traps set throughout	DFRC-B4800-FLOOR1	MECH		0:15
81963	TC	Site 9 Northeast vehicle gate motor lock box key will not turn though it goes in; get the key from Security	DAOF	MECH		1:00
81929	TC	703 VCC the two main doors are slamming shut too hard; the door closers may need to be checked	DAOF-B703	MECH		0:00
81991	TC	B/4838 2nd Fl - Clogged Toilet	DFRC-B4838	MECH		0:15
82009	TC	4825 Security Officer Jakobsen needs that clock taken down so the time can be corrected and it is too high	DFRC-B4825-POST1	MECH		0:30
82144	TC	B/4826 - (Facility Inspection Item) Repair Water Leak	DFRC-B4826	MECH		0:15
81874	TC	4824 in the large restroom the soap and paper towel dispensers are not up on the wall as they should be	DFRC-B4824	MECH		0:45
82120	TC	B/4876 - Mice in Traps	DFRC-B4876	MECH		1:00
82149	TC	703 pump water from utility vaults	DAOF-B703	MECH		1:30
82034	TC	703 southeast first floor ladies and mens room have one toilet each that are running	DAOF-B703	MECH		0:00
82035	TC	4832 dispose of dead mice in traps and reset traps or set new ones	DFRC-B4832-COMPUTER-SUPPORT	MECH		1:00
82157	TC	703 two clogged toilets; one in the second floor northwest mensroom, and the other in the first floor west mens room off the hangar	DAOF-B703	MECH		1:00
81977	TC	4800 kitchenette near room 1726 needs the sink filter changed	DFRC-B4800-FLOOR1	MECH		1:00
82214	TC	703 first floor north east ladies room two toilets running: right to left stall three then stall two so that both were running	DAOF-B703	MECH		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

82289	TC	4830A cubicle/office 22 replace non-compliant door handle with NASA approved hardware; thereafter Tony Beggs will install the lock core.	DFRC-B4830A	MECH		1:00
82125	TC	B/703 2nd Flr North - Restroom Sink	DAOF-B703	MECH		0:00
81712	TC	4800-1122 replace/repair existing door stop to rear door of Shaker Lab; see Anthony for specifics	DFRC-B4800-FLOOR1	MECH		0:15
81630	TC	4825 exterior near loading dock is a crack in the asphalt creating a tripping hazard that needs to be filled	DFRC-B4825	MECH		0:15
81637	TC	703 north gate not working - getting stuck	DAOF-B703	MECH		0:40
81675	TC	4823 Machine Shop - a tile fell from the ceiling and there is a leak from that location; see Darryl for specifics	DFRC-B4823	MECH		2:00
81676	TC	4820 repair damaged exterior door on mezzanine	DFRC-B4820	MECH		3:45
81710	TC	B/703 West - Replace Drinking Fountain Filters	DAOF-B703	MECH		1:30
81713	TC	B/703 East - Replace Drinking Fountain Filters	DAOF-B703	MECH		1:25
81721	TC	4820 mens room has a door handle that sticks and a urinal that runs constantly	DFRC-B4820	MECH		0:45
81723	TC	4820 push bar sticks on front entry door to building	DFRC-B4820	MECH		0:30
81751	TC	4800-2205 Ladies room left faucet water pressure is too high as the water is splashing getting everything wet	DFRC-B4800-FLOOR2	MECH		0:30
82014	TC	4825 sliding patio doors are not opening all the way	DFRC-B4825-GIFT-SHOP	MECH		0:45
81812	TC	B/703 NE - Hangar Door	DAOF-B703	MECH	90034	0:00
81860	TC	4800-1412, 1410, 1406 need mouse traps set throughout	DFRC-B4800-FLOOR1	MECH		0:45
81875	TC	4800-2145 mens room first stall toilet has very low water pressure often taking up to 3 flushes to finish	DFRC-B4800-FLOOR2	MECH		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

82124	TC	B/4800 FH 1A - Repair/Replace Corroded Backflow	DFRC-B4800-FLOOR3	MECH		7:45
82166	TC	4826 personnel door closer not closing door all the way - the door is on the taxiway side of the bldg in the T. O. room. See Walt for specifics	DFRC-B4826	MECH		0:15
82187	TC	4823 exhaust fan to chiller is not operating	DFRC-B4823	MECH		2:15
82208	TC	4839 a paper towel dispenser is not working even after changing out the batteries	DFRC-B4839	MECH		0:45
82215	TC	B/4826 - Hangar Door	DFRC-B4826	MECH		11:00
81629	TC	4846 mens room toilet's tank not filling up	DFRC-B4846	MECH		0:15
81632	TC	4800 Exterior louvre needs repair; could become safety issue	DFRC-B4800-FLOOR1	MECH		0:30
81645	TC	4802 Men's Room Main sink batteries dying	DFRC-B4802	MECH		0:45
81646	TC	4870 Utilities sink dripping	DFRC-B4870	MECH		2:00
81650	TC	4876 Extension Dock not working	DFRC-B4876	MECH		1:00
81678	TC	4800-2205 Ladies room faucet has little water coming from it; may need batteries	DFRC-B4800-FLOOR1	MECH		0:45
81684	TC	B/4850 - Install rodent prevention	DFRC-B4850	MECH		1:30
81685	TC	4826 Evaporative cooler #3 - backflow preventor needs repair	DFRC-B4826	MECH	305037	4:00
81962	TC	4840-104 exterior door to stairwell has lost strike plate and it is on the lower window frame next to the door	DFRC-B4840	MECH		1:15
81966	TC	4800-1418 mens room toilet not flushing because it has no water	DFRC-B4800-FLOOR1	MECH		4:15
81973	TC	4876 need mouse traps set throughout	DFRC-B4876	MECH		2:00
84225	TC	4720 the stop sign nearest the bldg has been pulled off the post and needs repair	DFRC-B4720	MECH		1:00
84227	TC	4720 two repairs needed; weatherstripping around the door needs to be replaced and the door stop has lost its rubber pad causing the door to bang against it. See Sandra for specifics	DFRC-B4720	MECH		3:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

84228	TC	4820-124 both doors need weatherstripping installed or replaced	DFRC-B4820	MECH		1:30
84234	TC	B/703 Rm 111 - Pipe Leaking	DAOF-B703	MECH		0:40
84238	TC	4800-1016 ladies room faucet not working - may need batteries	DFRC-B4800-FLOOR1	MECH		0:30
84241	TC	4839 irrigation valve needs to be repaired/replaced	DFRC-B4839	MECH		5:00
84262	TC	B/4800 Rms 2504/2506 - Roof Leak	DFRC-B4800-FLOOR2	MECH		4:30
84256	TC	4846 mens room smells strongly of sulphur	DFRC-B4846	MECH		1:30
84258	TC	4826-104 need mouse traps for room 104 and surrounding rooms	DFRC-B4826	MECH		0:15
84259	TC	4876 dispose of trapped rodent in warehouse	DFRC-B4876	MECH		0:15
84260	TC	4806 broken toilet seat	DFRC-B4806	MECH		0:30
84275	TC	4827 there is water on the floor around the water heater; perhaps it is leaking or the washing machine is leaking	DFRC-B4827	MECH		5:30
84332	TC	PRIORITY=NASA Dryden - NB046 - Manhole 14 or 14A is full of water and needs to be pumped out; check all other manholes in the case they also need water pumped out	DFRC-NB046	MECH		8:00
84223	TC	703 first floor northwest hall in the stairwell is a rodent in a trap that needs to be disposed of	DAOF-B703	MECH		0:15
84263	TC	B/4801 Rm 2217 - Roof Leak	DFRC-B4801	MECH		0:45
84282	TC	4825 Cafeteria/Robin Hood - two sinks are leaking; the hand sink is leaking at the bottom and may be clogged as well since when the faucet runs the sink backs up, also, the kitchen sink is leaking	DFRC-B4825-GIFT-SHOP	MECH		2:00
84251	TC	4810 dispose of trapped rodent	DFRC-B4810	MECH		0:15
84360	TC	4800-1115 need mice traps set	DFRC-B4800-FLOOR1	MECH		0:15
84283	TC	4820-100 Larry Hudson's office - some wet ceiling tiles smell and also may indicate a leak that needs troubleshooting; afterwards replace the ceiling tile with new ones	DFRC-B4820	MECH		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

84284	TC	703-140B mens room middle stall toilet not working	DAOF-B703	MECH		0:30
84319	TC	B/4800 Rm 1418 - Replace Toilet Seat	DFRC-B4800-FLOOR1	MECH		0:30
84178	TC	4876 attach replacement chocks to chains at loading dock	DFRC-B4876	MECH		0:30
84243	TC	4800-1811 need six 2-packs of rodent traps delivered for Life Support personnel to place in 4808 and the LOx yard	DFRC-B4800-FLOOR1	MECH		0:15
84167	TC	4810 north mens and ladies rest rooms have a very bad odor; floor drains may need enzymes	DFRC-B4810	MECH		0:15
84347	TC	4876 warehouse needs at least 4 new traps, perhaps more	DFRC-B4876	MECH		0:15
84348	TC	703 first floor north side mens room has a clogged toilet that is flooding the floor	DAOF-B703	MECH		1:40
84408	TC	Gate 5 will not shut	DFRC-GATE-05	MECH		1:00
84268	TC	4800-1422 need mice traps set	DFRC-B4800-FLOOR1	MECH		0:15
84270	TC	4800-2323 the customer hears a sound like rain drops	DFRC-B4800-FLOOR2	MECH		2:00
84272	TC	4800-1418 mens room has a faucet running in it	DFRC-B4800-FLOOR1	MECH		0:45
84273	TC	4982 door with card reader sticks and once opened it cannot be closed; Security issue	DFRC-B4982	MECH		0:45
84356	TC	4825 check origin of water coming from behind bldg across the parking lot	DFRC-B4825	MECH		0:30
84322	TC	NB007 - Sewer Ejector #4 - replace discharge pressure switch	DFRC-NB007	MECH		1:30
84324	TC	703 North fence - Weed Abatement - clear weeds along north fence and nearby facilities such as the explosives yard to the required distance; see Ralph for specifics	DAOF-B703	MECH		7:40
84367	TC	4823 Sheet Metal Shop first floor mens room has a clogged toilet	DFRC-B4823	MECH		0:30
84397	TC	4800-1016 ladies room sink on right hand side if facing the mirror is not draining	DFRC-B4800-FLOOR1	MECH		4:15
84376	TC	B/4800 Rm 1418 - Handicap Sink	DFRC-B4800-FLOOR1	MECH		1:15
84379	TC	4800-3304 ladies room has a leaking faucet	DFRC-B4800-FLOOR3	MECH		2:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

84383	TC	4800-1704 kitchen sink drain is gurgling and smells overwhelmingly of methane gas	DFRC-B4800-FLOOR1	MECH		2:15
84389	TC	4800-1100 interior door is not lining up with striker plate	DFRC-B4800-FLOOR1	MECH		1:00
84312	TC	Substation 7 repair chain link gate post and broken support hardware on corner	DFRC-NB086	MECH		3:00
84320	TC	B/4825 - Mouse Traps	DFRC-B4825	MECH		0:30
84326	TC	B/4820 Flow Lab - Repair Exhaust Fan	DFRC-B4820	MECH		2:00
84173	TC	4800-1406 there is a foul smell, possibly an unfound dead rodent ; see Chrisann's cubicle	DFRC-B4800-FLOOR1	MECH		0:30
84175	TC	4823 Machine Shop has a clogged sink	DFRC-B4823	MECH		0:00
84182	TC	B/4800 Rm 1418 - Clogged Toilet	DFRC-B4800-FLOOR1	MECH		0:30
84411	TC	4800-1426 office "L" - Maikeyza Brown's office has a trapped rodent in it that needs to be disposed of; if needed call Chuck - office is unlocked	DFRC-B4800-FLOOR1	MECH		0:15
84274	TC	4839 break room - a trapped mouse needs to be disposed of	DFRC-B4839	MECH		0:15
84288	TC	4800-1812 Life Support mens room the first or left urinal is not draining properly	DFRC-B4800-FLOOR1	MECH		3:00
84321	TC	4833 mens room has a broken toilet paper dispenser that needs to be repaired or replaced	DFRC-B4833	MECH		1:00
84362	TC	4840 second floor mens room - middle urinal leaking badly; appears to be running under into the ladies room	DFRC-B4840	MECH		9:15
84398	TC	4982 the NE entry way door lever is sticking in the down position and not latching	DFRC-B4982	MECH		0:45
85711	TC	Gate 50 wheel came off track	NASA-DRYDEN	MECH		0:45
84977	TC	703-142 need rodent traps	DAOF-B703	MECH		0:10
86699	TC	4820 front exterior door to hangar is not closing	DFRC-B4820	MECH		0:30
86701	TC	4851 entry door coming from the side the vehicles are parked on is not latching without a hard push	DFRC-B4851	MECH		0:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

86755	TC	B/4825 ISF - Toilet Overflowing	DFRC-B4825-POST1	MECH		2:30
86789	TC	4800-2407 sink filter needs to be changed	DFRC-B4800-FLOOR2	MECH		1:00
86796	TC	B/4801 Rm 2204 - Restroom Repairs	DFRC-B4801	MECH		1:30
86698	TC	703-142 need 12 mouse traps	DAOF-B703	MECH		0:15
86897	TC	4838-205 SMALL WATER LEAK ; WET CEILING TILE	DFRC-B4838	MECH		0:15
86983	TC	B703 Rm 140B - Urinal Repair	DAOF-B703	MECH		0:10
87031	TC	4820 FLOW LAB - REPLACE SOAP DISPENSER; SEE ERIK FOR SPECIFICS	DFRC-B4820	MECH		0:45
86854	TC	B/4720 - Generator Warning Light	DFRC-B4720	MECH	803012	0:45
86883	TC	4800-2008 LADIES ROOM THIRD STALL TOILET OVERFLOWING	DFRC-B4800-FLOOR2	MECH		0:30
86994	TC	4823 FIRST FLOOR MENS AND LADIES ROOMS EACH HAVE A TOILET THAT IS RUNNING	DFRC-B4823	MECH		2:30
86988	TC	4809-19 dispose of dead rodent; set traps	DFRC-B4809	MECH		0:45
87014	TC	4720 DISPOSE OF TRAPPED DEAD RODENT	DFRC-B4720	MECH		1:00
87015	TC	4850 JANITORIAL CLOSET UTILITY SINK FAUCET NEEDS TO BE REPAIRED/REPLACED AS IT SPRAYS EVERYWHERE WHEN TURNED ON.	DFRC-B4850	MECH		1:30
87028	TC	4863 KITCHEN FAUCET IS NOT TURNING OFF ENTIRELY AND RUNNING	DFRC-B4863	MECH		0:15
87017	TC	4800-1418 TOP OF DOOR CATCHING ON THE UPPER JAMB; TOP HINGE MAY BE LOOSE.	DFRC-B4800-FLOOR1	MECH		0:15
86704	TC	703 stairwell 2 has tread coming off of two stairs; significant trip hazard. See Ralph for specific stairs.	DAOF-B703	MECH		0:50
86705	TC	4800-1016 ladies rest room right side faucet hot water is leaking	DFRC-B4800-FLOOR1	MECH		0:15
86908	TC	703 hang three posters: near elevator second floor, at SOFIA Maintenance office, at SOFIA Project office	DAOF-B703	MECH		0:50
86911	TC	4847 foam around some fire standpipes to seal spaces preventing entrance by rodents	DFRC-B4847	MECH		1:45
86912	TC	4840 first floor rear exit panic bar dangling by one side	DFRC-B4840	MECH		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

86926	TC	4800-3304 ladies room stall has a broken latch	DFRC-B4800-FLOOR3	MECH		0:45
86928	TC	4800-1418 mens room toilet is out of order	DFRC-B4800-FLOOR1	MECH		0:15
86685	TC	Needs mouse traps set in Building 4857	DFRC-B4857	MECH		0:30
86710	TC	4800-1722 leak coming through ceiling fixture at the approx rate of one drop per second	DFRC-B4800-FLOOR1	MECH		7:10
86921	TC	4847 restroom toilet paper dispenser needs to be repaired or replaced	DFRC-B4847	MECH		0:30
86682	TC	4840 second floor mens room urinal to the right drips some when flushed	DFRC-B4840	MECH		0:30
86709	TC	4800-2319 in hall near office the floor is buckling up and creating a tripping hazard; need caution tape across damage.	DFRC-B4800-FLOOR2	MECH		1:00
86749	TC	B/703 2nd Fl - Door Repair	DAOF-B703	MECH		1:15
86843	TC	B/4800 Rm 2332 - Foul Odor	DFRC-B4800-FLOOR2	MECH		1:00
86866	TC	B/703 - IFO Audit Findings 292-076	DAOF-B703	MECH		2:00
86879	TC	B/4840 Bay 4 - Troubleshoot Roll up door	DFRC-B4840	MECH	4060006	0:30
86880	TC	B/4870 - Foul odor	DFRC-B4870	MECH		0:30
86881	TC	B/4841 - Threshold	DFRC-B4841	MECH		0:15
86691	TC	Parking Lot #3 - repaint stripes - per Don Adams on a Safety write-up	DFRC-NB058	MECH		9:30
86714	TC	4841 ladies room toilet running	DFRC-B4841	MECH		0:30
86761	TC	4800-1418 mens room left side urinal is clogged	DFRC-B4800-FLOOR1	MECH		1:45
86827	TC	4800-1016 ladies room toilet clogged and overflowing	DFRC-B4800-FLOOR1	MECH		1:00
86955	TC	4800-3303 THE DOOR LATCH INTO THE UPPER DOOR JAMB OF THE SOUTHEAST DOOR IS BROKEN; SEE WARREN OR RICHARD FOR ACCESS TO ROOM	DFRC-B4800-FLOOR3	MECH		1:00
86932	TC	GATE 5 - THE GATE AFTER BEING CLOSED IS OPENING AGAIN; THIS HAS HAPPENED TWICE	DFRC-GATE-05	MECH		0:30
86941	TC	B4820, 4823 - Installation of Evacuation Chairs	DFRC-B4820	MECH		1:15
86952	TC	4832 mens room has clogged sink	DFRC-B4832-MAIL-ROOM	MECH		0:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

86978	TC	B/4825 - Turnstile Free Spinning	DFRC-B4825	MECH		1:00
86985	TC	4820 repair leak in ejection pump	DFRC-B4820	MECH		4:00
86795	TC	B/4800 - Passenger Elevator	DFRC-B4800-FLOOR1	MECH		0:30
86951	TC	T-1 EDWARDS FCU HAS ONE TOILET AND IT IS CLOGGED	DFRC-T-01	MECH		0:30
87030	TC	FLIGHTLINE LOX YARD - MORE TRAPS AND VERMIN PROOFING. UNITED PEST CONTROL WILL BE COMING TO ASSESS PERHAPS COORDINATE WITH POC BOB PIMOFSKY x5579	DFRC-FLIGHTLINE	MECH		0:15
86850	TC	4800-2219 small mezzanine - a ceiling tile is bowing out and looks as though it will fall very soon; cannot tell if it is wet. See Miriam Rodon x3647 for specifics	DFRC-B4800-FLOOR2	MECH		0:45
86852	TC	B/4825 Cafe - Repair Door Handle	DFRC-B4825-GIFT-SHOP	MECH		0:15
86859	TC	4840-216 carpet coming up at threshold; trip hazard	DFRC-B4840	MECH		0:15
86861	TC	4841 water seeping in large quantities out of a possible manhole cover	DFRC-B4841	MECH		23:30
86864	TC	703-312 resecure white board back up on wall it fell from	DAOF-B703	MECH		1:30
86865	TC	703-211 both doors to room squeak very badly	DAOF-B703	MECH		0:20
86867	TC	4840-113A&B help open and close (as needed) partition between rooms	DFRC-B4840	MECH		0:15
86934	TC	4840-BAYS 4, 5 - REPAIR BROKEN BRACKET ON ROLL-UP DOOR AND INSTALL A BRUSH SEAL	DFRC-B4840	MECH		2:30
86937	TC	4863 DRAIN GRATES ON THE GROUND IN FRONT OF THE BLDG ARE MOVING AROUND MAKING A TRIPPING HAZARD	DFRC-B4863	MECH		0:00
86672	TC	Gate 5 closes 1/2 way, shutters, and re-opens	DFRC-GATE-05	MECH		0:15
86678	TC	4800-1016 ladies room right side sink has no hot water	DFRC-B4800-FLOOR1	MECH		1:15
86679	TC	4810 Ali Morey's cubicle needs mouse traps	DFRC-B4810	MECH		0:10

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

86715	TC	B/4839 - Urinal Running	DFRC-B4839	MECH		0:15
86918	TC	4800 second floor down the hall from room 2128 a drinking fountain is leaking onto the floor	DFRC-B4800-FLOOR2	MECH		1:45
86919	TC	B4800, 4801 - Installation of Evacuation Chairs	DFRC-B4800-FLOOR2	MECH		3:00
86744	TC	4825 SECURITY LADIES ROOM ADA STALL TOILET OVERFLOWING	DFRC-B4825-POST1	MECH		0:45
86828	TC	703 second floor north west ladies room has two clogged sinks	DAOF-B703	MECH		6:20
86282	TC	4876 dispose of trapped rodent and bring more traps	DFRC-B4876	MECH		0:15
86914	TC	Gate 5 not operating correctly	DFRC-GATE-05	MECH		1:15
86916	TC	4830 ladies room first floor left sink is clogged	DFRC-B4838	MECH		0:45
86763	TC	4851 ladies room - a toilet has a broken seat	DFRC-B4851	MECH		0:45
86797	TC	LOX yard - Cart 64-106 is the big green cart on the right rear side of the storage area has a dead rodent in a trap on it that needs to be disposed of.	DFRC-FLIGHTLINE	MECH		0:15
86798	TC	4800-1418 mens room - the forth toilet over to the right side has no water in it; the toilet may need batteries	DFRC-B4800-FLOOR1	MECH		0:30
86942	TC	B4838, 4840 - Installation of Evacuation Chairs	DFRC-B4838	MECH		2:00
86949	TC	703 HANGAR NORTH WALL FORKLIFT MADE SMALL HOLE THAT NEEDS REPAIR	DAOF-B703	MECH		0:40
86969	TC	B/4833 - Door Repair	DFRC-B4833	MECH		1:00
86690	TC	4985 need rat traps	DFRC-B4985	MECH		0:15
86785	TC	4870 the kitchen smells as though a dead rodent were under the floor	DFRC-B4870	MECH		0:30
86776	TC	703 secure main vehicle gate in the closed position	DAOF-B703	MECH		0:00
86784	TC	4800-1811 mens room toilet leaking badly through handle when flushed; toilet on left side closest to showers	DFRC-B4800-FLOOR1	MECH		1:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

86787	TC	4800-1422 need mice traps	DFRC-B4800-FLOOR1	MECH		0:15
86950	TC	4810 NORTH MENS ROOM BY CODE F HAS A TOILET THAT THE TANK DOES NOT REFILL ON WHEN FLUSHED	DFRC-B4810	MECH		1:00
86954	TC	703 FIRST FLOOR SOUTHEAST MENS ROOM THERE IS A CLOGGED	DAOF-B703	MECH		0:20
86991	TC	4856 A TOILET THAT HAS BEEN TURNED OFF WAS RUNNING BADLY	DFRC-B4856	MECH		1:00
86959	TC	4833-100 SMELLS AS THOUGH RODENT DIED IN ROOM	DFRC-B4833	MECH		3:00
87027	TC	B/4820 2nd fl - Door Repair	DFRC-B4820	MECH		1:00
86963	TC	4820 LADIES ROOM TOILET IS RUNNING A LONG TIME AFTER BEING FLUSHED; IT'S THE FIRST TOILET IN FROM ENTERING THE DOOR	DFRC-B4820	MECH		0:30
87020	TC	703 DAOF CAMPUS FILL/REPAIR A GROUND HOLE THAT IS BETWEEN THE VCC AND THE SUBSTATION	DAOF-B703A	MECH		0:55
87035	TC	GATE 5 REAR WHEEL POPPING OUT HITTING TRACK REOPENING GATE	DFRC-GATE-05	MECH		0:30
89653	TC	4824 SHOP DOOR LEADING TO OUTSIDE - THE HANDLE IS STUCK OR LOCKED AND NEEDS TO BE CHECKED.	DFRC-B4824	MECH		1:15
89661	TC	4982 WEST DOOR HAS A CARD READER WHICH APPEARS TO BE WORKING BUT THE DOOR DOES NOT SEEM TO BE OPENING	DFRC-B4982	MECH		2:00
89662	TC	4800-1016 LADIES TOILET OVERFLOWING	DFRC-B4800-FLOOR1	MECH		0:15
89308	TC	4838 DOWN STAIRS MENS ADA STALL TOILET HAS A LEAKING FLUSH VALVE WHEN THE TOILET IS USED	DFRC-B4838	MECH		1:15
89358	TC	4825 VISITOR'S LADIES' ROOM MIDDLE STALL TOILET IS NOT FLUSHING RIGHT; MEN'S ROOM RIGHT SIDE SINK IS DRIPPING	DFRC-B4825	MECH		4:15
89415	TC	DAOF - N/W Gate - Troubleshoot Wheels	DAOF-B703	MECH		1:30
89475	TC	4825 CAFETERIA LADIES ROOM DOOR IS NOT OPENING/CLOSING CORRECTLY; FOUND BROKEN SCREW ON THE FLOOR	DFRC-B4825	MECH		0:30
89277	TC	B/703 VCC - Toilet Running/Overflowing	DAOF-B703A	MECH		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89287	TC	4720 DISPOSE OF DEAD RODENT; SEE SANDRA	DFRC-B4720	MECH		0:30
89288	TC	4801 MENS ROOM FLOOR DRAIN HAS A SNAKE TRYING TO COME OUT OF IT	DFRC-B4801	MECH		0:30
89293	TC	B/4826 - Roll Up Door Inop	DFRC-B4826	MECH		0:45
89491	TC	4859 SOAP DISPENSER LEAKING IN THE KITCHEN	DFRC-B4859	MECH		0:45
89299	TC	B/4844 - LOCKS ON THREE DOORS NEED TO BE REFITTED WITH GOV'T APPROVED HARDWARD; SEE SHIRLEY FOR SPECIFICS	DFRC-B4844	MECH		0:00
89320	TC	4830A IRRIGATION SPRINKLER HEAD BROKEN AND WATER SPRAYING ALL OVER.	DFRC-B4830A	MECH		0:15
89322	TC	B/4844 - Toilet Noise/Running	DFRC-B4844	MECH		1:00
89534	TC	B/4842 - Roof Leak	DFRC-B4842	MECH		0:30
89535	TC	B/4810 - Roof Leak	DFRC-B4810	MECH		0:15
89536	TC	4822 MEDICAL CLINIC - IN THE "HEARING" ROOM THERE IS AN OUT OF DATE SOAP DISPENSER THAT TAKES CARTRIDGE STYLE LIQUID SOAP CONTAINERS. THE CURRENT DISPENSERS TAKE A PLASTIC BAG STYLE LIQUID SOAP	DFRC-B4822-MEDICAL	MECH		1:00
89541	TC	4840 BAY 6 DOOR CANNOT BE OPENED BECAUSE OF A BROKEN BOLT; IS CURRENTLY PROPPED OPEN.	DFRC-B4840	MECH		1:00
89543	TC	4825 SECURITY - DARLENE HOMIAK'S OFFICE HAS A TRAPPED DEAD RODENT THAT NEEDS TO BE DISPOSED OF	DFRC-B4825-POST1	MECH		0:15
89332	TC	MANHOLE E28 NEXT TO SUB 13 HAS A SUMP PUMP THAT NEEDS TROUBLESHOOTING AND REPAIR	DFRC-NB046	MECH		0:30
89336	TC	4720 UNDER THE FLOOR WHERE THE FIBER OPTIC CABLE RUN RODENT TRAPS ARE NEEDED AS THE CABLES HAVE BEEN EATEN THROUGH	DFRC-B4720	MECH		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89553	TC	4850 BLDG NEEDS THREE DISPENSERS REPLACED BECAUSE THEY ARE NO LONGER USABLE AS NEWER DISPENSERS WITH DIFFERENT SOAP BAGS ARE BEING USED. SEE BELOW:	DFRC-B4850	MECH		1:00
89561	TC	B4876- Pest Control	DFRC-B4876	MECH		0:00
89562	TC	4800 EXTERIOR TO 4801 APPROX 10' UP IS A "NO SMOKING" SIGN THAT IS _VERY_ LOOSE AND WILL SOON BECOME A WIND HAZARD	DFRC-B4800	MECH		0:15
89564	TC	B/703N Rm 120B (DR 449) - Restroom Repairs	DAOF-B703	MECH		0:00
89566	TC	B/703S Rm 140B (DR 449) - Restroom Repairs	DAOF-B703	MECH		0:00
89382	TC	4830B MENS ROOM TWO SINKS DRAINING MUCH TOO SLOWLY	DFRC-B4830B	MECH		0:30
89570	TC	4833 LADIES ROOM TOILET IS RUNNING CONSTANTLY	DFRC-B4833	MECH		0:30
89571	TC	4823 NEED A DOOR SEAL GLUED BACK ON	DFRC-B4823	MECH		0:45
89573	TC	4846 MENS ROOM EXHAUST FAN IS NOT RUNNING BUT IS GIVING OFF THE SMELL OF BURNED PLASTIC	DFRC-B4846	MECH		1:00
89587	TC	4800-1115 AN EXTERIOR DOOR LEADING TO THE HORSHOE OF THE THE BLDG IS NOW DRAGGING ON THE GROUND. IT WASN'T DOING THIS YESTERDAY OR EARLIER THIS MORNING.	DFRC-B4800-FLOOR1	MECH		0:30
89406	TC	703 FIRST FLOOR SOUTHEAST MENS ROOM HAS A CLOGGED SINK AND TOILET; IN THE SOUTHWEST MENS ROOM THERE IS A CLOGGED SINK.	DAOF-B703	MECH		0:00
89408	TC	B/4807 - Repair Door Latch	DFRC-B4807	MECH		0:30
89591	TC	B/4825 Cafe - Door Repair (Inner Sensor)	DFRC-B4825-GIFT-SHOP	MECH		1:00
89602	TC	4820 HIGH BAY EXTEIROR DOOR NOT SHUTTING; IT IS NEXT TO THE ICE MACHINE.	DFRC-B4820	MECH		0:45

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89608	TC	4841 AN OFFICE DOOR STAYS LOCKED EVEN AFTER THE KEY IS USED ON IT. CUSTOMER WOULD LIKE THE LOCK REPAIRED OR CHANGED OUT. SEE ANITA FOR SPECIFICS.	DFRC-B4841	MECH		2:00
89618	TC	B/703 Rm S333 - Remove Door	DAOF-B703	MECH		0:50
89625	TC	NASA (Lakebed) - Troubleshoot Water	DFRC	MECH		1:00
89627	TC	4823 SHEET METAL SHOP MENS ROOM TOILET LEAKING FROM THE BASE; WATER WILL BE SHUT OFF BY CUSTOMER	DFRC-B4823	MECH		1:30
89638	TC	B/4800 Rm 1018 (Mens) - Faucet Repair	DFRC-B4800-FLOOR1	MECH		0:45
89639	TC	B/703 VCC - Door Repair	DAOF-B703A	MECH		1:20
89640	TC	B/4876 - Repair Roll Up Door	DFRC-B4876	MECH		0:15
89675	TC	4823 MACHINE SHOP MENS ROOM REPLACE BROKEN OR OLD DISPENSER WITH NEW ONE THAT SOAP BAGS FIT	DFRC-B4823	MECH		0:45
89342	TC	4876 TROUBLESHOOT AND/OR REPAIR A LEAK IN THE COOL BOX; SEE DEE FOR SPECIFICS	DFRC-B4876	MECH		3:30
89563	TC	B/703N Rm 140B (DR 449) - Restroom Repairs	DAOF-B703	MECH		0:00
89286	TC	4800-2412 LIBRARY - TROUBLESHOOT/REPLACE CHAIR HINGE/SCREW UNIT; SEE KARL BENDER FOR SPECIFICS	DFRC-B4800-FLOOR2	MECH		0:15
89305	TC	4823 SHEET METAL SHOP - CHECK CORRODED PIPE OVER THE SINK; SEE PEDRO FOR SPECIFICS	DFRC-B4823	MECH		6:00
89291	TC	4826 EVAP COOLER #8 HAS A LEAKING BACK FLOW PREVENTOR	DFRC-B4826	MECH	305042	4:30
89355	TC	4809 URINAL LEAKING	DFRC-B4809	MECH		0:30
89369	TC	B/4825 Cafe - Doors Not Operating	DFRC-B4825-GIFT-SHOP	MECH		5:30
89445	TC	B/4825 - Cafeteria Door Repair	DFRC-B4825-GIFT-SHOP	MECH		1:00
89485	TC	703 SCC REPLACE 14 BAD CEILING TILES; 6 IN CONTROL ROOM AND 8 IN BREAKROOM.	DAOF-B703	MECH		2:20
89301	TC	B/4800 Rm 2400 - Faucet Repair	DFRC-B4800-FLOOR2	MECH		0:45
89302	TC	4983 REPLACE DAMAGED PUMP COUPLING	DFRC-B4983	MECH	1138008	2:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89315	TC	4857 DISPOSE OF SEVERAL DEAD RODENTS AND RESET TRAPS	DFRC-B4857	MECH		0:30
89317	TC	4840 FIRST FLOOR KITCHENETTE - REPAIR/REPLACE OLD, BROKEN SOAP DISPENSER	DFRC-B4840	MECH		1:00
89328	TC	703 FIRST FLOOR SOUTHEAST LADIES ROOM HAS A RUNNING TOILET	DAOF-B703	MECH		0:50
89330	TC	4844 BLDG HAS NO HOT WATER	DFRC-B4844	MECH		0:45
89326	TC	B/703 REPAINT FADED FIRE LANE MARKINGS. SAFETY ISSUE; DRIVERS CANNOT SEE THE LANE TO BE GUIDED. HAVE HAD A COUPLE NEAR COLLISIONS.	DAOF-B703	MECH		0:00
89393	TC	B/4800 Rm 1125 - Clogged Sink	DFRC-B4800-FLOOR1	MECH		4:00
89321	TC	4847 ADJUST HOIST WEDGE INSTALLING U BOLTS	DFRC-B4847	MECH		4:00
89264	TC	4720 DISPOSE OF DEAD RODENT	DFRC-B4720	MECH		0:15
89402	TC	4800-2515 MENS ROOM SINK FAUCET APPEARS TO BE RUNNING CONTINUOUSLY	DFRC-B4800-FLOOR2	MECH		1:00
89507	TC	4876 NEED MORE RODENT TRAPS SET	DFRC-B4876	MECH		0:45
89512	TC	4840 BAY 3 DISPOSE OF DEAD RODENT AND SET SOME TRAPS. (THIS ONE IS IN THE BASKET OF THE OFFICE SHREDDER)	DFRC-B4840	MECH		0:30
89515	TC	4840-216 NEED RODENT TRAPS	DFRC-B4840	MECH		0:30
89421	TC	4825 VISITOR'S MENS' ROOM HAS A BACKED UP URINAL	DFRC-B4825	MECH		0:30
89469	TC	4826 AN EXTERIOR DOOR WILL NOT CLOSE SO THE BLDG CANNOT BE SECURED FOR THE EVENING	DFRC-B4826	MECH		0:30
89479	TC	B4800 RM 1426- Dead Mouse	DFRC-B4800	MECH		0:30
89480	TC	B4840 Hangar Bay 1,2, and 3	DFRC-B4840	MECH		1:00
89482	TC	B4833 Mens Bathroom	DFRC-B4833	MECH		1:30
89483	TC	B4720- Dead mouse	DFRC-B4720	MECH		0:30
89484	TC	4800-2204 MENS ROOM FAUCET HAS NO WATER PRESSURE	DFRC-B4800-FLOOR2	MECH		0:15
89490	TC	4840-107 CHECK/TROUBLESHOOT EXHAUST FAN - STILL NOT WORKING	DFRC-B4840	MECH		2:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89494	TC	4840-242 MENS ROOM - SINKS CLOGGED	DFRC-B4840	MECH		13:30
89529	TC	4850 MENS ROOM (INTERIOR) PAPER TOWEL DISPENSER IS JAMMED; A WASHER FELL OUT OF IT AND MAY BE PART OF THE PROBLEM.	DFRC-B4850	MECH		0:15
89516	TC	B 4720 Dead Rodent	DFRC-B4720	MECH		2:15
89519	TC	B4810- Domestic water leak	DFRC-B4810	MECH		2:15
89431	TC	B/4840 Rm 161 & 162 - Troubleshoot Water Leak	DFRC-B4840	MECH		0:30
89295	TC	4840-202B DISPOSE OF DEAD RODENT	DFRC-B4840	MECH		0:45
89296	TC	4857 (SERVICE REQUEST) WAREHOUSE REAR BAY DOOR WHEN CHAIN IS PADLOCKED NEED A HOOK OR SOME MECHANISM TO KEEP THE CHAIN FROM MOVING AND HURTING SOMEONE	DFRC-B4857	MECH		1:15
89487	TC	4800-1029 REPLACE OLD BANNER WITH NEW ONE. SEE GABY IN RM 1029 FOR BANNER.	DFRC-B4800-FLOOR1	MECH		0:30
89493	TC	B/703S Rm 140B - (DR 449) Repair/Replace Tile	DAOF-B703	MECH		0:00
89548	TC	T-20 IN THE REST ROOM AND THE KITCHEN ARE ONE EACH SOAP DISPENSERS THAT NEED TO BE REPLACED WITH NEW ONES. SEE BLANCA FOR SPECIFICS	DFRC-T-20	MECH		0:30
89565	TC	B/703S Rm 120B (DR 449) - Restroom Repairs	DAOF-B703	MECH		0:00
89558	TC	NASA - Check Vaults	DFRC	MECH		0:30
89610	TC	4800-2526 DOOR CLOSER NEEDS REPAIR OR REPLACEMENT	DFRC-B4800-FLOOR2	MECH		1:30
89645	TC	B/4800 Rm 1422 - Pest Control	DFRC-B4800-FLOOR1	MECH		0:30
89646	TC	B/4839 - Troubleshoot Faucet	DFRC-B4839	MECH		1:00
89628	TC	703-122S SENSOR LAB DOOR COMING FROM THE HANGAR HAS A BAD KNOB AND THE DOOR IS VERY DIFFICULT TO OPEN	DAOF-B703	MECH		1:00
89654	TC	DAOF - Troubleshoot Sewer Back Up	DAOF	MECH		32:48:00
89657	TC	B/4838 2nd Fl - Troubleshoot Hot Water	DFRC-B4838	MECH		9:00
89353	TC	B703 South Side - Repair Door(s)	DAOF-B703	MECH		0:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

89655	TC	4800-2008 LADIES' ROOM - WATER ON THE FLOOR MAY BE AN INDICATOR ONE OF THE TOILET SEALS IS BAD	DFRC-B4800-FLOOR2	MECH		0:30
89670	TC	B/4800 Rm 2501 - Sinks Clogged	DFRC-B4800-FLOOR2	MECH		1:00
89422	TC	4800 FANHOUSE 1A CHILLER #2 - REPLACE EIGHT 3/4 IN. BALL VALVES WITH EIGHT 3/4 IN. X 2 IN. GALVANIZED NIPPLES; SEE BILL FOR SPECIFICS.	DFRC-B4800	MECH		3:30
89442	TC	4800 ACROSS THE HALL FROM ROOM 1806 THE DRINKING FOUNTAIN WAS MAKING VERY BAD NOISE AS THOUGH A BEARING WAS GOING OUT. THE NOISE WAS SO BAD THE CUSTOMER UNPLUGGED THE UNIT	DFRC-B4800-FLOOR1	MECH		2:00
89500	TC	4825 - Replace Flag Pole Rope	DFRC-B4825	MECH		5:00
89528	TC	4806 THE MOP SINK POWERED SOAP DISPENSER NEEDS TO BE CHANGED OUT FOR A NEWER LIQUID SOAP DISPENSER.	DFRC-B4806	MECH		0:45
89533	TC	B4801 - Roof Leak	DFRC-B4801	MECH		0:15
89578	TC	B/4825 Gift Shop- Door Repair	DFRC-B4825-GIFT-SHOP	MECH		3:30
91489	TC	B/703 Rm 342S - Remove Glass Cover	DAOF-B703	MECH		0:00
91671	TC	4800-1016 LADIES ROOM HAND SANITIZER DISPENSER LID KEEPS COMING OFF; TAPE DOES NOT WORK. THERE IS NOT A NEW ONE TO REPLACE IT. TROUBLESHOOT A SOLUTION.	DFRC-B4800-FLOOR1	MECH		0:00
91672	TC	4800-1029 REPLACE OLD BANNER WITH NEW ONE. SEE GABY IN RM 1029 FOR BANNER.	DFRC-B4800-FLOOR1	MECH		0:00
91679	TC	B/4824 - Fire Investigation & System Start Up	DFRC-B4824	MECH		1:00
91498	TC	B/703 Rm 322B- Tighten Threshold	DAOF-B703	MECH		0:00
91681	TC	4820 FIRST FLOOR MENS ROOM THE LEFT SINK FAUCET DOES NOT WORK AND THE LEFT URINAL DOES NOT WORK WELL	DFRC-B4820	MECH		0:00
91682	TC	4800-2205 LADIES ROOM MIDDLE STALL TOILET IS STUCK RUNNING	DFRC-B4800-FLOOR2	MECH		0:00
91684	TC	4800-1018 MENS ROOM WATER LEAKING UNDER THE SINK	DFRC-B4800-FLOOR1	MECH		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

91687	TC	B/703 Sophia Lab - Door Adjustment	DAOF-B703	MECH		0:00
91691	TC	B/4720 - Repair Generator Door	DFRC-B4720	MECH	803012	1:00
91490	TC	B/4823 - Toilet Leaking	DFRC-B4823	MECH		0:45
91688	TC	NASA - Test & Inspect Backflow Preventers	DFRC	MECH		6:30
91689	TC	4830C - CURB IS SEPERATING FROM THE SIDEWALK CREATING A TRIPPING HAZARD	DFRC-B4830C	MECH		2:45
91510	TC	4850 LADIES ROOM OFF THE MAIN HALL HAS A TOILET THAT IS NOT FLUSHING WELL; THE TOILET IS STRAIGHT IN THE DOOR AND TO THE LEFT	DFRC-B4850	MECH		0:45
91568	TC	B/4800 Rm 2002 - Clogged Sink	DFRC-B4800-FLOOR2	MECH		19:45
91574	TC	4841 WEATHERSTRIPPING ON DOOR INTERFERING WITH CLOSURE OF DOOR	DFRC-B4841	MECH		0:15
91519	TC	B/4800 Rm 2407 - Sink Clogged	DFRC-B4800-FLOOR2	MECH		4:15
91523	TC	4840 THE HANDRAIL BY THE LOBBY PAINTING HAS COME OFF THE WALL; SEE KNUT FOR SPECIFICS	DFRC-B4840	MECH		0:45
91524	TC	4982 WINDOW SCREEN SHREDDED ON BLDG'S EAST WINDOW	DFRC-B4982	MECH		3:30
91527	TC	4800-2008 LADIES ROOM HAS AN ODD SMELL IN IT	DFRC-B4800-FLOOR2	MECH		0:15
91576	TC	GATE 9 - A WHEEL CAME OFF THE GATE AND THE GATE CANNOT WORK PROPERLY.	DFRC-GATE-09	MECH		2:15
91578	TC	4840 BAY 3 HANGAR DOOR IS NOT OPENING	DFRC-B4840	MECH		1:00
91530	TC	4802 YELLOW SWING DOOR HAS A HINGE THAT IS COMING APART; IT IS ON THE WEST SIDE OF THE BLDG NEXT TO A ROLL UP DOOR. SEE PAUL FOR SPECIFICS.	DFRC-B4802	MECH		1:45
91531	TC	4800-3305 MENS ROOM FAUCET IS RUNNING	DFRC-B4800-FLOOR3	MECH		0:15
91538	TC	4800 FANHOUSE 1 - REPLACE DOMESTIC WATER LINE	DFRC-B4800	MECH		0:00
91539	TC	4800-1720 REPLACE CEILING TILE OUTSIDE OFFICE IN HALLWAY	DFRC-B4800-FLOOR1	MECH		0:15
91587	TC	B/4839 - Door Panel Repair	DFRC-B4839	MECH		0:15
91590	TC	B/4839 - Mouse Removal	DFRC-B4839	MECH		0:15

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

91591	TC	4800-3305 MENS ROOM HAND SANITIZER DISPENSER CAME OFF THE WALL	DFRC-B4800-FLOOR3	MECH		0:30
91593	TC	T-47 CHECK THE PIPES UNDER THE KITCHEN SINK FOR WATER HAMMER	DFRC-T-47	MECH		6:00
91595	TC	4801 PERSONNEL DOORS WITHIN HANGAR DOORS ON GLOBAL HAWK SIDE HAVE A SIGN EACH THAT IS DUCT TAPED AT THE TOP AND HANGING FREE AT THE BOTTOM. WHEN THE HANGAR DOORS LIFT UP THE SIGNS DANGLE UNSAFELY	DFRC-B4801	MECH		0:15
91597	TC	4800-2204 MENS ROOM TWO FAUCETS ARE NOT OPERATING	DFRC-B4800-FLOOR2	MECH		1:15
91601	TC	4806 EMPLOYEES SMELL A GAS LEAK	DFRC-B4806	MECH		2:15
91603	TC	T-69 IN THE UNISEX REST ROOM THE MIDDLE TOILET IS RUNNING	DFRC-T-69	MECH		1:00
91604	TC	T-70 IN REST ROOM NEAR KITCHEN A TOILET IS RUNNING VERY BADLY	DFRC-T-70	MECH		0:00
91606	TC	703-S111D DOOR HANDLE NOT WORKING	DAOF-B703	MECH		0:30
91607	TC	703-S211 CEILING TILE IS OUT OF PLACE	DAOF-B703	MECH		0:15
91608	TC	B/703 NE Mens R/R - Toilets Not Flushing	DAOF-B703	MECH		0:00
91614	TC	4827 REPAIR ROLL UP DOOR	DFRC-B4827	MECH		1:30
91615	TC	4808 MENS ROOM TOILET NOT FLUSHING; SEE BLANCA FOR ACCESS.	DFRC-B4808-LIFE-SUPPORT	MECH		1:00
91616	TC	703-221 CUBICLE " U " NEEDS MICE TRAPS ESPECIALLY IN THE DESK DRAWERS	DAOF-B703	MECH		0:10
91631	TC	B/4810 - Door Handle Repair	DFRC-B4810	MECH		0:45
91632	TC	B/4801 Rm 2204 - Faucet Repair	DFRC-B4801	MECH		1:00
91635	TC	B/4806 - Clogged Sink	DFRC-B4806	MECH		2:00
91636	TC	B/4810 - Troubleshoot Toilet	DFRC-B4810	MECH		0:30
91646	TC	B/4720 - Pest Control	DFRC-B4720	MECH		0:30
91647	TC	B/703 Rm 122 - Door Repair	DAOF-B703	MECH		0:00
91655	TC	B/4840 Rm 156 - Pest Control	DFRC-B4840	MECH		0:30
91656	TC	DAOF - Sewage Lift Station Failure	DAOF	MECH		0:00
91657	TC	DAOF - Sewage Lift Station Failure	DAOF	MECH		0:00
91658	TC	GATE 8 - Gate Non Operational	DFRC-GATE-08	MECH		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

91659	TC	DAOF - Troubleshoot Control Panel for Lift Station	DAOF	MECH		0:00
91661	TC	4876 NORTH EAST DOOR HANDLE IS NOT CLOSING SECURELY. THE SPRING IS NOT CLOSING.	DFRC-B4876	MECH		0:30
91662	TC	703 TROUBLESHOOT PRESSURE REGULATOR MAKING A LOUD NOISE	DAOF-B703	MECH		0:00
91664	TC	T-47 THE KITCHEN PAPER TOWEL DISPENSER IS BROKEN	DFRC-T-47	MECH		0:45
93868	TC	Gate 22 - (ATF) Troubleshoot Gate Operation	DFRC-GATE-22	MECH		0:00
93882	TC	B/703 Sophia Ofc (DR #465) - Repair/Replace CLA Valve	DAOF-B703	MECH		0:00
93894	TC	DFRC- Back Flow Preventer Repairs	DFRC	MECH		0:00
93897	TC	4839 SMELLS OF DEAD RODENT IN ONE AREA	DFRC-B4839	MECH		0:00
93836	TC	4800-F/H6 CHECK WATER PRESSURE FLUCTUATION; MAY NEED WATER PRESSURE REGULATOR	DFRC-B4800	MECH		0:00
93839	TC	4825 ISF HAS A PHOTO HANGING LOOSE AND IT IS ABOUT TO FALL; NEEDS TO BE REMOVED BEFORE THE 2PM TOWN HALL MTG.	DFRC-B4825	MECH		0:00
93871	TC	703-S341 REPLACE SOME DAMAGED CARPET SQUARES AT THE ROOM'S ENTRANCE	DAOF-B703	MECH		0:00
93799	TC	DAOF - Sewage Lift Pumps Inspections	DAOF	MECH		0:00
93896	TC	B/4982 - Troubleshoot Generator	DFRC-B4982	MECH	803004	0:00
93813	TC	B/4824 - Door Closer	DFRC-B4824	MECH		1:00
93818	TC	4825 ISF MENS ROOM MIDDLE URINAL IS NOT DRAINING	DFRC-B4825	MECH		1:00
93819	TC	4820 FIRST FLOOR MENS ROOM FAUCETS NOT WORKING PROPERLY	DFRC-B4820	MECH		0:30
93837	TC	4822 REPAIR LEAK IN THE REDUCE PRESSURE VALVE	DFRC-B4822	MECH		0:00
93841	TC	703 SECOND FLOOR NORTH WEST MENS ROOM SECOND TOILET IS OVERFLOWING	DAOF-B703	MECH		1:00
93856	TC	B/T-20 - Water Heater	DFRC-T-20	MECH		0:00
93802	TC	Gate 8 - Clean Out Tracks	DFRC-NB119	MECH	1303002	1:00
93803	TC	Gate 50 - Clean Out Tracks	DFRC-B4826	MECH	1303000	1:30

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

93878	TC	4839 JANITORIAL SINK FAUCET HAS NO WATER COMING FROM IT	DFRC-B4839	MECH		0:00
93805	TC	DFRC- Back Flow Preventer Repairs	DFRC	MECH		8:00
93806	TC	DAOF- Back Flow Preventer Inspection	DAOF	MECH		1:00
93827	TC	B/4801 - Water Leak	DFRC-B4801	MECH		0:00
93828	TC	703-221 CUBICLE "O" HAS A MOUSE IN IT	DAOF-B703	MECH		0:10
93858	TC	4800-1625 DOOR KEEPS GETTING STUCK OPEN. MAY BE CAUSED BY THE DOOR SWEEP.	DFRC-B4800-FLOOR1	MECH		0:15
93865	TC	4823 MACHINE SHOP SINK IS FLOODING	DFRC-B4823	MECH		0:00
93879	TC	B/4823 - Hazmat Locker Fan Inop	DFRC-B4823	MECH		0:00
93822	TC	4800-3102 MENS ROOM FAUCET IS WORKING INTERMITTENTLY	DFRC-B4800-FLOOR3	MECH		0:30
93859	TC	4840 repair broken and missing cement joints, cracked expansion joints and broken brick on the lake bed side	DFRC-B4840	MECH		0:00
93883	TC	4800-1726 CEILING TILE IN HALL WAY NEED TO BE CHANGED OUT FROM A LEAK THIS PAST WEEKEND	DFRC-B4800-FLOOR1	MECH		0:00
93809	TC	B/4809 - Door Repair	DFRC-B4809	MECH		1:00
93835	TC	4844 LADIES ROOM - MOVE A SOAP DISPENSER FROM A GFI OUTLET SO THE OUTLET CAN BE USED BECAUSE THE DISPENSER IS TOO CLOSE	DFRC-B4844	MECH		0:30
93884	TC	4820 REST ROOM FAUCETS ARE NOT WORKING AGAIN	DFRC-B4820	MECH		0:00
93843	TC	B/4800 Rm 1006 - Seal Door	DFRC-B4800-FLOOR1	MECH		2:30
93850	TC	4809 REPLACE SOAP DISPENSER WITH INDUSTRIAL SOAP DISPENSER AT THE UTILITY SINK IN THE SHOP; SEE LISA FOR DISPENSER, HARDWARE AND SPECIFICS.	DFRC-B4809	MECH		1:00
93870	TC	703-S234 REPLACE BROKEN CEILING TILE	DAOF-B703	MECH		0:00
93872	TC	4800-1413 LADIES ROOM TOILET NOT FLUSHING AND MAY BE CLOGGED	DFRC-B4800-FLOOR1	MECH		0:00
93892	TC	B/4854 Lift #6 - Troubleshoot Sewage Lift	DFRC-B4854	MECH		0:00
93874	TC	4800-1016 LADIES ROOM ENTRY WAY DOOR SWINGS TOO "LOOSE"	DFRC-B4800-FLOOR1	MECH		0:00

TROUBLE CALL and SERVICE REQUESTS HISTORICAL DATA

93887	TC	703 REPAINT FADED CROSS WALKS; SEE RALPH FOR SPECIFICS	DAOF-B703	MECH		0:00
93798	TC	DAOF - Troubleshoot Sewage Lift Pumps	DAOF	MECH		0:00
93812	TC	B/4801 Rm 107 - Repair Urinal	DFRC-B4801	MECH		1:00

2:09