

## SOLICITATION NNL14504840E SITE VISIT INSTRUCTIONS

All attendees should meet at the Langley Research Center Badge & Pass Office no later than 1330 local time. There will be a short briefing by the Contracting Officer, followed by a drive (in individual vehicles) to the Building 1213 parking area. The group will proceed down the sidewalk and tour Building 1192 and then Building 1213. The last stop will be at the adjacent steam plant and down into the utility tunnel that feeds Building 1213 to view the piping that has to be abated and removed. Hard hats, safety glasses and steel toe boots are mandatory. Please ensure you have these safety items or you will not be allowed entry into the steam plant and tunnel area.

Link to Google Maps for LaRC Main Gate location:

[https://www.google.com/mapmaker?ll=37.085769,-76.380132&spn=0.002409,0.004565&t=h&z=18&vpsrc=0&utm\\_medium=website&utm\\_campaign=relatedproducts\\_maps&utm\\_source=mapseditbutton\\_normal](https://www.google.com/mapmaker?ll=37.085769,-76.380132&spn=0.002409,0.004565&t=h&z=18&vpsrc=0&utm_medium=website&utm_campaign=relatedproducts_maps&utm_source=mapseditbutton_normal)

The section L site visit clause is restated below for your reference.

### **L.12 52.236-27 SITE VISIT (CONSTRUCTION) (FEB 1995)**

(b) A **mandatory** organized site visit has been scheduled for:

**April 8, 2014 at 2:00 p.m.**

(c) Access to LaRC is restricted to appropriately badged individuals; therefore, prospective bidders must submit their Name, Company Affiliation and Citizenship no later than 4:00 p.m. April 7, 2014 to:

M.T. Stubbs, Contracting Officer  
Email: m.t.stubbs@nasa.gov

(End of provision)